

 <p>CARLO GAVAZZI</p>	<p>CARLO GAVAZZI SPACE SpA</p> <p>VIA GALLARATE, 150 20151 - MILANO ITALY</p> <p>TEL. +39 02.380481 FAX +39 02.3086458 e-mail: cgs@cgspace.it</p>	<p>TELEFAX</p>
---	--	-----------------------

TO : ASI

FAX N.: 06 8567 320

ATT.: Luigi De Angelis

ESA-ESTEC

0049 89 30000 3272

Dr. Wolfgang Schmid

0031 71 565 5244

Jan Rautakoski

0044 1235 446667

Ken King

0031 30 2540 860

Kees Wafelbakker

FROM : A. Ricciu, M. Vitta

DATE : 07/10/2005

REF : 50948

PROJECT Nr: 1916

PAGE: 1 OF : 7

INTERNAL COPIES (e-mail): M. Vitta, E. Francini

SUBJECT : Major NCRs


Dear Sirs,

Please find attached the major NCRs NCR-HERS-CGS-B-004 and NCR-DPU-CGS-B-032 (related to the old DPU-FIRST contract).


The original documents will follow by ordinary mail.


Best regards,

Alessandro Ricciu



Massimo Vitta



 CARLO GAVAZZI SPACE Spa		HERSCHEL DPU's/ICU			1 N C R ref	Doc.N°: NCR-HERS-CGS-D-004 Rev: 1 Date: 26/09/2005 Page 1 of 2 attach: /				
2 NCR Title: unreliability of the Boot SW Telemetry packet										
IDENTIFICATION	3	Supplier	4	Purchase Order N°	5	Model	6	Subsystem	7	Procedure/Work Item N°
						CFM HIFI (1916)		NA		NA
	8	NC ITEM Identification	9	Drawing N°	Rev.	10	P.N. / C.I. N°	11	Serial N°	
		HERSCHEL DPU's/ICU CFM	12-GEN-05.00	ver 1.0		12-GEN-05.00				
12	Next Higher Unit Id.	13	Drawing N°	Rev.	14	P.N. / C.I. N°	15	Serial N°		
	NA		NA		NA		NA			
DESCRIPTION	16 NON CONFORMANCE Detected During:									
	RECEIVING INSP. <input type="checkbox"/> MANUFACT. <input type="checkbox"/> ASSEMBLY/INTEGRATION <input type="checkbox"/> FINAL INSPECTION <input type="checkbox"/> TEST <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>									
	17 Initiator, Dept., Date, Signature : A. Bertoli SW Engineer (26/9/2005)									
	18 Description of NON CONFORMANCE									
Unreliability of the telemetry packets APID 400 of the boot software during the OBS uploading procedure. The following errors were detected and SPRs were raised by IFSI. <ul style="list-style-type: none"> The APID counter incorrectly managed when TM(5,1) and TM(5,4) is received The TM(5,4) packet page lost is not received when one TC is lost During the OBS uploading some TM(5,1) packets have an incorrect CRC 										
18 Requirements violated										
BSRD-100, BSRD-150, BSRD-240										
INTERNAL NRB DISPOSITIONS	20 INTERNAL NRB Dispositions:									
	1) other informations about the problems 2) investigation of the problems									
	21 Verifications									
	See page 2									
	22 Suspected cause of NC:									
	HANDLING <input type="checkbox"/> TRANSPORTATION <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TOOLS <input type="checkbox"/> SW <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> OPERATOR/PROCEDURE ERROR <input type="checkbox"/> PART <input type="checkbox"/> MATERIAL <input type="checkbox"/> PROCESS <input type="checkbox"/> TEST <input type="checkbox"/> OTHER <input type="checkbox"/>									
23 Classification										
MINOR <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/>										
24 Corrective/Preventive Actions:										
25 REQUEST FOR WAIVER										
YES <input type="checkbox"/> NO <input type="checkbox"/> N°										
26 Analysis Required										
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N°										
27 Other related documents:										
Department:										
28 P.A.		29 Syst. Engineering		30 Sw Engineering						
Name		Name		Name						
Signature:		Signature:		Signature:						
Date:		Date:		Date:						
M. Vignoli		G. Magistrati		A. Bertoli						
6/10/05		2/10/05		6/30/2005						
				A. Zicchi						
				6/10/05						
				C. Cinguepalmi						
				6/10/05						
CUSTOMER/HIGHER LEVEL CONTRACTOR NRB DISPOSITIONS	32 CUSTOMER/HIGHER LEVEL CONTRACTOR NRB Dispositions (Class Major Only):									
	33 Finally determined Cause of NC									
	34 Corrective/Preventive Actions:									
	35 Customer/HLContractor Approval:									
36 CLOSE OUT CERTIFICATION										
Department:										
Name:										
Signature:										
Date:										
CGS PA/QA				PA/QA Stamp						



CARLO GAVAZZI SPACE SpA

HERSCHEL DPUs/ICU

NON CONFORMANCE REPORT

1
N
C
R
ref

Doc N°: NCR-HERS-CGS-D-004

Rev.: 1 Date: 26/09/2005

Page 2 of 2 attach: /

37 CONTINUATION SHEET

<input checked="" type="checkbox"/>	SUSPECTED CAUSE OF NC	<input type="checkbox"/>	INTERNAL NRB DISPOSITION	<input type="checkbox"/>	DESCRIPTION OF NC
<input type="checkbox"/>	FINALLY DETECTED CAUSE	<input type="checkbox"/>	CUSTOMER NRB DISPOSITION	<input type="checkbox"/>	CORRECT/PREVENT. ACTIONS
<input type="checkbox"/>	REQUIREMENTS VIOLATED				

21 Verifications

1) Other Information about the problems

- Two APID counters are managed for the TM(5,1) and TM(5,4) packets. Basically there two separate APIDcounter for TM(5,1) packet and TM(5,4) packet. This is not correct. The same APID counter should be used for both TM packets
- The TM(5,4) memory page lost is not generated when one TC is not received from the boot software during the uploading procedure.
- during the OBS uploading procedure the CRC of some TM(5,1) packets transmitted by Boot Sw is wrong

26/09/2005

The Software Problem report was raised by IFSI. The HIFI SPR references are SPR-384, SPR-383, SPR-382

Current version of the Boot Software 12-GEN-05 00ver1.0

26/09/2005

2) Investigation of the first Problem

Performing the inspection of the code, the incorrect management has been identified. Actually two counters are managed for APID counter of the TM(5,1) and TM(5,4) packets. The function SendTelemetry has been modified and only one counter has been inserted for the APID management.

26/09/2005

3) investigation of the second Problem

Performing code inspection of the Page lost management the problem has been identified. Uncorrect TC page counter initialization and compare condition has been detected and isolated. The TCManagement function has been modified concerning the page lost check.

27/09/2005

4) investigation of the third problem

Performing the inspection of the code no error was detected but several access to the MILBUS has been identified during the Telemetry packet preparation. The Milbus management during the Telemetry packet preparation was changed. Basically now the packet is prepared in data memory and it is written to the Milbus one shot.

29/09/2005

5) Test of the new Boot Software

The test procedure for the Memory Page lost detection has been changed. Instead of select Start / stop button on CQMS simulator (this doesn't allow to control how many TCs are lost), a TC is deleted from the EGSE TCs set and the uploading is launched.

The same problems have been verified and detected on the CFM1 unit available at CGS, with Boot Sw 12-HERS-05.00ver1.0. In particular concerning the CRC problem the following CRC error rate was detected according to the error rate communicated by IFSI.

- about 2 / 3 wrong CRC packets during 1 OBS uploading (about 1600 TM(5,1) packets).
- Therefore the Tests for the code correction verification have been performed on CFM1

After the installation of the Boot SW, with the new modification the following tests have been performed

- about 30 tests of Load and Boot procedure and 500 uploading procedures were performed during the test session. A program for CRC check has been generated to check the CRC of the received telemetry packets
 - At the end of the test session the following results have been found: about 500000 telemetry TM(5,1) packets has been received and no CRC errors in the TM(5,1) packets have been detected.
- The APID counter is correctly managed and the TM(5,4)
- TM(5,4) packet page lost error messages is generated when one TC is lost.


The modification will be implemented in the Boot software 12-GEN-05.00 ver1.1
The modification shall be applicable to all the units PACS, SPIRE, HIFI

13/10/2005

6) Actions and Conclusion

The Boot Software 12-GEN-05.00ver1.1 will be initially installed on CFM HIFI. The Boot SW upgrade for the other two units PACS and SPIRE will be decided after the 13/10/2005 progress meeting concerning the consolidation of the Boot Sw requirements.

All information contained in this document are property of CARLO GAVAZZI SPACE SpA. All rights reserved

 CARLO GAVAZZI SPACE SpA	HSO/FIRST-DPU	1 Doc.N°: NCR-DPU-CGS-B-032 NCR ref Rev.: 1 Date: 28/9/2005 Page 1 of 2 attach: Ann. A
	NON CONFORMANCE REPORT	

2 NCR Title: Anomaly on power section of PACS DPU AVM1

IDENTIFICATION	3 Supplier CGS	4 Purchase Order N° NA	5 Model EM	6 Subsystem NA	7 Procedure/Work Item N° NA
	8 NC ITEM Identification DC/DC board	9 Drawing N° DPU-EM-300 00-0	Rev /	10 P.N. / C.I. N° DPU-EM-300 00-0	11 Serial N° 02
	12 Next Higher Unit Id. NA	13 Drawing N° NA	Rev.	14 P.N. / C.I. N° NA	15 Serial N°

DESCRIPTION	16 NON CONFORMANCE Detected During: RECEIVING INSP. <input type="checkbox"/> MANUFACT. <input type="checkbox"/> ASSEMBLY/INTEGRATION <input type="checkbox"/> FINAL INSPECTION <input type="checkbox"/> TEST <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>				
	17 Initiator, Dept., Date, Signature G. Magistrati Orb.infr. 28/09/05 <i>SGP</i>				
	18 Description of NON CONFORMANCE During PACS IMT testing 2 power anomalies have been detected as described in NCR HP-113000-ASED-NC-141 (see annex A)				19 Requirements violated NONE

INTERNAL NRB DISPOSITIONS	20 INTERNAL NRB Dispositions: The board was provided inside a box, produced by IFSI and not included in the CGS supply Continues on next page				21 Verifications
	22 Suspected cause of NC: HANDLING <input checked="" type="checkbox"/> TRANSPORTATION <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TOOLS <input type="checkbox"/> SW <input type="checkbox"/> DESIGN <input type="checkbox"/> OPERATOR/PROCEDURE ERROR <input type="checkbox"/> PART <input type="checkbox"/> MATERIAL <input type="checkbox"/> PROCESS <input type="checkbox"/> TEST <input type="checkbox"/> OTHER <input type="checkbox"/>				
	23 Classification MINOR <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/>		24 Corrective/Preventive Actions: None		
	25 REQUEST FOR WAIVER YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N°		26 Analysis Required YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N°		27 Other related documents: None
	Department:	28 P.A.	29 Syst. Engineering	30 P.M.	31 C.C.
	Name:	<i>M. VITTA</i>	<i>G. MAGISTRATI</i>	<i>A. RICCIU</i>	<i>C. CINQUEPACI</i>
Signature:	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>	
Date:	<i>28/9/05</i>	<i>28/9/05</i>	<i>28/09/05</i>	<i>30/9/05</i>	

CUSTOMER/HIGHER LEVEL CONTRACTOR NRB DISPOSITIONS	32 CUSTOMER/HIGHER LEVEL CONTRACTOR NRB Dispositions (Class Major Only):				21 Verifications
	33 Finally determined Cause of NC		34 Corrective/Preventive Actions:		
	35 Customer/HLContractor Approval:				36 CLOSE OUT CERTIFICATION
	Department:				CGS PAQA
Name:				PA/QA Stamp	
Signature:					
Date:					



CARLO GAVAZZI SPACE SpA

HSO/FIRST-DPU

NON CONFORMANCE REPORT

1 Doc.N°: NCR-DPU-CGS-B-032

N C R Rev.: 1 Date: 28/9/2005

ref Page 2 of 2 attach: Ann. A

37 CONTINUATION SHEET

<input type="checkbox"/> SUSPECTED CAUSE OF NC <input type="checkbox"/> FINALLY DETECTED CAUSE <input type="checkbox"/> REQUIREMENTS VIOLATED	<input checked="" type="checkbox"/> INTERNAL NRB DISPOSITION <input type="checkbox"/> CUSTOMER NRB DISPOSITION	<input type="checkbox"/> DESCRIPTION OF NC <input type="checkbox"/> CORRECT/PREVENT. ACTIONS	21 Verifications
1) Perform an Impedance measurement between 28Vdc Hot and Return side at box level on J01 2) Remove the top cover of the box and to measure the impedances among the secondary power voltages and the return line 3) Power on the Unit and to measure the current provided to the unit 4) Extract the DC/DC board from the box 5) Perform a visual inspection on the DC/DC board 6) Measure the continuity of the Filter Inductor placed on the input of the 28Vdc feed 7) Bypass the Inductor using a wire soldered on the soldering side of the DC/DC board 8) Test the DC/DC board in stand alone configuration 9) Remove the bypass and refresh/reinforce the soldering points of the inductor			1) CLOSED. 28/9/05 A value of 300kohm approx. has been measured. <i>S. G. S.</i> 2) CLOSED. 28/9/05 No anomalous values have been detected (no permanent short circuit are present on secondary side of the DC/DC). <i>S. G. S.</i> 3) CLOSED. 28/9/05 A current consumption of 0A @ 28Vdc has been measured; it seems that also the input stage circuitry of the DC/DC is not supplied. <i>S. G. S.</i> 4) CLOSED 28/9/05 <i>S. G. S.</i> 5) CLOSED 28/9/05 NO PROBLEMS DETECTED <i>S. G. S.</i> 6) CLOSED 28/9/05 An anomaly has been detected: The inductor L1 is open. <i>S. G. S.</i> 7) CLOSED. 28/9/05 <i>S. G. S.</i> 8) CLOSED 28/9/05 The DC/DC board has been powered ON with dummy loads and it works properly. <i>S. G. S.</i>

NEX A TO: NCR-DPU-CGS-3-032

Wednesday September 21 2005 4:55 PM

Company ESTEC		Project Name HERSCHEL-PLANCK		NCR-No: HP-113000-ASED-NC-1491		Related internal NCR-No:		Critical Item: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Revision 0	
				Page 1 of 2							
Nonconformance Report											
NCR Title PACS DPU power anomaly											
NC Item Identification PACS											
Next Higher Assembly HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)											
Drawing No						Sr No.					
Procedure No											
Supplier MPE						Purchase Order					
Subsystem						Model			EQM		
NC Observation Date: 21-SEP-05 Location: ASED OTN						NC Detected During Test					
Description of Nonconformance										Requirements Violated	
<p>During PACS IMT testing 2 power anomalies were seen as follows:</p> <p>1) DPU rebooted itself during testing -> No power surge was identified on PLM SCOE</p> <p>2) DPU's power consumption dropped to zero during test.</p> <p>PACS (all modules) were powered down on request of PACS instrument team.</p> <p>DPU was restarted after 40 minutes, power consumption stayed at 0 A.</p> <p>Power cable was checked with breakout box.</p> <p>Result: 28 V is available at the end of the PLM SCOE cable.</p> <p>NRB to be held, to decide on further investigations</p>											
Initiator: Date, Name and Signature 21-SEP-05 D. HENDRY											
Internal NRB Dispositions 21.09.05 internal NRB, ASED, PACS, ASP, ESA Perform initial investigations as follows: Disconnect cable DB 32 GO1 3-22 and 4-23 measure voltage result 28 volts. Insert break out box in line GO1 and reconnect harness. measure voltage during DPU switch on, result initial current peak of 150 ma then zero current. Disconnect GO1 and connect 50 ohm load and measure switch on current and voltage, result 28v ok and 250 ma current ok Initial conclusion power SCOE is operating ok and fault is within the DPU. Convene customer NRB Ref. to MoMs										Classification: Major <input checked="" type="checkbox"/> Minor <input type="checkbox"/>	
Customer Notification											
Cause of NC				Corrective/Preventative Actions				Verification			
Ref to Failure Report											
Date:	PA	Engineering	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05
Name:	21-SEP-05	21-SEP-05	D.Hendry	S.ilsen	C.Schlosser	A.Heske	W.Pinter-Krainer	G.Doubrovik	H.Feuchtgruber	E.Wiezorrek	
Signature:	D.Hendry	S.ilsen	D.Hendry	S.ilsen	C.Schlosser	A.Heske	W.Pinter-Krainer	G.Doubrovik	H.Feuchtgruber	E.Wiezorrek	

Wednesday September 21 2005 4:55 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No. HP-113000-ASED-NC-1491 Related Internal NCR-No. Critical Item: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Page 2 of 2	Revision 0
-------------------------	--	---	------------

Nonconformance Report - Continuation Sheet -

Customer NRB Dispositions (Class Major Only) Ref. to MoMs	Verification
<p>21.09.05 ESA, ASP, ASED, PACS, Following initial investigations it was considered that the SCOE and harness were not the cause of the failure and PACS recommend to deintegrate the DPU and return to the supplier for failure investigations. PACS state that no similar problem has been seen during any lower level testing, during ILT the instrument was power on for a max of 3 days, during the present JMT phase PACS has been on for max of 5 days (in stand by during HIFI IMT and weekend). Unit temp was 28 degees C. All Instruments use the same design of DPU I/F power circuit PACS have a replacement unit model CFM at MPI which can be available at OTN by 09-00 tomorrow, this unit needs to have a OBSW upload with Issue 7.68, present unit has 7.65. the new issue is for internal H/W changes and to be compatible with I EGSE. AI/1 PACS The unit will have stand alone test at MPI following OBSW upload. The Mechanical I/F of the CFM is the same as existing AVM. AI/2 PACS The electrical I/F (no redundancy) Connector configuration with respect to which redundancy is connected needs to be confirmed by PACS to ensure correct harness length. AI/3 PACS PACS to raise NCR to track the failure investigations of the AVM List of activities: 1) Switch off HIFI and SPIRE 2) Switch off power SCOE and CDMU FE 3) Check grounding of power SCOE and DPU. 4) Electrically disconnect DPU using general ESD protection no specific order for connector removal is required. 5) Mechanically deintegrate unit. 6) Perform SCOE power on electrical check and current and voltage measurement using dummy loads (analogous measurement). 7) Mechanically integrate CFM 8) Electrical integration check of power and isolation. 9) perform DPU power up check. 10) Pack AVM in transport container and return to supplier for failure investigations</p>	

Finally Determined Cause of NC Ref to Failure Report	Corrective/Preventative Actions
---	---------------------------------

Request for Waiver Yes <input type="checkbox"/> No <input type="checkbox"/> Reference:	Alert Yes <input type="checkbox"/> No <input type="checkbox"/> Reference:	Other related Documents
---	--	-------------------------

	NCR Close Out
--	----------------------

NRB Approval Organization/ Name	
Date, Signature	