

SPIRE-AST-REP-002628

Title: PACS IMT

CI-No: 153300

Prepared by:	S. Ilsen / M. Koelle <i>[Signature]</i>	Date:	04/10/2005
Checked by:	C. Schlosser <i>[Signature]</i>		27/10/05
Product Assurance:	for R. Stritter <i>[Signature]</i>		7. 11. 05
Configuration Control:	W. Wietbrock <i>[Signature]</i>		02. 11. 05
Project Management:	Dr. W. Fricke <i>[Signature]</i>		07/11/05

Distribution: See Distribution List (last page)

Copying of this document, and giving it to others and the use or communication of the contents thereof, are forbidden without express authority. Offenders are liable to the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design.

Issue	Date	Sheet	Description of Change	Release
1	04/10/ 2005		First Issue	

Table of Content

1	Scope	10
1.1	Objective	10
1.2	Summary	10
2	Documents/Drawings	13
2.1	Applicable Documents	13
2.2	Reference Documents	13
2.3	Other Documents	13
3	Configuration	14
3.1	PLM Configuration	14
3.2	Environment	14
4	Conditions	15
4.1	Personnel	15
4.2	Environmental	15
4.3	General Precautions and Safety	15
4.3.1	General Safety Requirements, Precautions	15
4.3.2	ESD constraints	15
4.3.3	Special QA Requirements	15
4.4	EGSE	15
4.4.1	Hardware: CCS, EGSE's and DFE's	16
4.4.2	Hardware: Prime Instrument	16
4.4.3	Software	16
4.4.4	Special Equipment	18
4.5	MIB	19
4.5.1	Version	19
4.5.2	Configuration & Manual changes	19
5	Step by Step Procedure: Configure CCS and EGSE	22
6	Step by Step Procedure: Power On Instruments	23
6.1	Power on HIFI to STANDBY Mode	24
6.2	Power on PACS to PRIME Mode	27

6.3	Power on SPIRE to STANDBY Mode	29
6.3.1	SFT-SPIRE-CCS-DPU-ON	29
6.3.2	SFT-SPIRE-CCS-DRCU-ON	30
6.3.3	SFT-SPIRE-CCS-FUNC-SCU-03	31
6.3.4	SFT-SPIRE-CCS-FUNC-SCU-06	32
6.3.5	Extra	33
7	Step by Step Procedure: PACS IMT results	34
7.1	Test ID: 401 - PACS Switch on	34
7.2	Test ID: 402 - Memory Management Test	34
7.3	Test ID: 403 - PACS Setup of Spectroscopy with CSs off and Open Grating Launch Lock	35
7.4	Test ID: 403 - PACS Setup of Spectroscopy with CSs off and Open Grating Launch Lock	35
7.5	Test ID: 404 – Grating Test	36
7.6	Test ID: 406 – Thermal Behaviour Test in Spectroscopy	37
7.7	Test ID: 407 – Setup Spectroscopy, Data Rate and Cryostat Background Adjustment	38
7.8	Test ID: 408 – Chopper Full FOV Scan in Spectroscopy	39
7.9	Test ID: 409 – Reconfiguration and Optional Switch-off/on Cycle	39
7.10	Test ID: 410 – Cooler Recycling	39
7.11	Test ID: 516 – Detector Dark Current on Internal Calibration Sources	41
7.12	Test ID: 517 – Grating Performance Test	42
7.13	Test ID: 518 – Chopper Performance Test Spectroscopy	43
7.14	Test ID: 519 – Emissivity of internal calibration sources	43
8	Step by Step Procedure: Switch Off Instruments	47
8.1	Switch Off HIFI	47
8.2	Switch Off SPIRE	48
8.2.1	SFT-SPIRE-CCS-FUNC-THO	48
8.2.2	SFT-SPIRE-CCS-DRCU-OFF	49
8.2.3	SFT-SPIRE-CCS-DPU-OFF	50
8.3	Switch Off PACS	51
9	Step by Step Procedure: Set EGSE to OFFLINE	52
10	Step by Step Procedure: Configure CCS and EGSE (2)	53

11	Step by Step Procedure: Power On Instruments (2)	54
11.1	Power on PACS to PRIME Mode (2)	55
11.2	Power on HIFI to STANDBY Mode	56
11.3	Power on SPIRE to STANDBY Mode	59
11.3.1	SFT-SPIRE-CCS-DPU-ON	59
11.3.2	SFT-SPIRE-CCS-DRCU-ON	60
11.3.3	SFT-SPIRE-CCS-FUNC-SCU-03	61
11.3.4	SFT-SPIRE-CCS-FUNC-SCU-06	62
12	Step by Step Procedure: PACS IMT results	63
12.1	Test ID: 410 – Cooler Recycling	63
12.2	Test ID: 411 – Thermal Behaviour Test in Photometry	64
12.3	Test ID: 407 – Setup Spectroscopy, Data Rate and Cryostat Background Adjustment – only Step1	65
12.4	Test ID: 520 – Quick Wavelength Check	66
13	Step by Step Procedure: Switch Off Instruments	67
13.1	Switch Off HIFI	67
13.2	Switch Off SPIRE	68
13.3	Switch Off PACS	70
14	Step by Step Procedure: Set EGSE to OFFLINE	71
15	Summary Sheets	72
15.1	Procedure Variation Summary	72
15.2	Non Conformance Report (NCR) Summary	73
15.3	Sign-off Sheet	74
Appendix 1: PACS Nominal Bus Profile (PACS_prime_inst.PST)		75
Appendix 2: PACS Burst Mode Bus Profile (PACS_burst_mode.PST)		79
Appendix 3: Log of EGSE_CONFIG_AUTO.tcl		84
Appendix 4: Log of INSTR_POWER_ON.tcl (Used for HIFI power on)		87

Appendix 5: Log of PACS_POWER_ON.tcl	92
Appendix 6: Log of INSTR_POWER_ON.tcl (Used for SPIRE power on)	96
Appendix 7: Log of PACS_POWER_ON_BOLCout.tcl (used to recover from ASED NCR 1494)	100
Appendix 8: Log of PACS_POWER_OFF.tcl	104
Appendix 9: Log of INSTR_POWER_OFF.tcl (used for HIFI and SPIRE power down)	108
Appendix 10: Log of EGSE_OFFLINE_AUTO.tcl	113
Appendix 11: HP-111000-ASED-NC-1282 - Wrong MIB definition of command PC162420	116
Appendix 12: HP-111000-ASED-NC-1491 – PACS DPU power anomaly	117
Appendix 13: HP-111000-ASED-NC-1493 - CRC in HK not compliant with CRC in procedure Memory Management Test	119
Appendix 14: HP-111000-ASED-NC-1494 - DEC_MEC got blocked and DEC_MEC - DPU comm link dead	120
Appendix 15: HP-111000-ASED-NC-1495 - Cooler Recycle Failed	121
Appendix 16: HP-111000-ASED-NC-1496 – IMT TestID 516 should be run in Burst mode (SPEC_dark_current...tcl)	122
Appendix 17: HP-111000-ASED-NC-1497 - DPU packets get corrupted (bad packets)	123
Appendix 18: Power Profile (from PLM SCOE) during DPU power down	124

16 Distribution List

125

Table of Figures

Error! No table of figures entries found.

List of Tables

Table 15.1-1: Procedure Variation Sheet72
Table 15.2-1: Non-Conformance Record Sheet.....73

1 Scope

1.1 Objective

This test report describes the results of the IMT until the failure of the PACS DPU performed for the Herschel PACS Instrument.

The test was performed at ASED in Ottobrunn from 19/09/2005 to 21/09/2005.

1.2 Summary

Detailed results are given in the as-run-procedure in Chapter 7

The following NCR's have been raised:

- HP-111000-ASED-NC-1282 - Wrong MIB definition of command PC162420 (see Appendix 11)
- HP-111000-ASED-NC-1491 – PACS DPU power anomaly (see Appendix 12)
- HP-111000-ASED-NC-1493 - CRC in HK not compliant with CRC in procedure Memory Management Test (see Appendix 13)
- HP-111000-ASED-NC-1494 - DEC_MEC got blocked and DEC_MEC - DPU comm link dead (see Appendix 14)
- HP-111000-ASED-NC-1495 - Cooler Recycle Failed (see Appendix 15)
- HP-111000-ASED-NC-1496 – IMT TestID 516 should be run in Burst mode (SPEC_dark_current...tcl) (see Appendix 16)
- HP-111000-ASED-NC-1497 - DPU packets get corrupted (bad packets) (see Appendix 17)

The following NCR's have been altered:

- N/A

An overview can be found in chapter 15.2

Conclusion:

During the IMT numerous problem were recognised. NCR have been raised to trace these problems. The test is stopped on the third day of IMT because of the PACS DPU failure. After a DPU exchange on day 4, the tests are restarted. Continuous problems with the new DPU however caused another stop.

During the IMT HIFI and SPIRE were in STANDBY mode and monitored regularly by the test operator. No problems were detected.

Extra Comments:

- During the PACS IMT it is noticed that a lot of SPIRE HK are arriving in an incorrect order (SSC errors). Since the PACS bus profile should allow enough space for at least 2 SPIRE TM packets a second, this is not nominal. An NCR is already raised (1375) to investigate if this problem is caused by problems in the bus profile or on the CDMU DFE or somewhere else.
- During the PACS IMT multiple out of limits were reported on PACS parameters. This is a known ASED NCR 1276. Also SSC errors are reported on the CCS (known ASED NCR 1247). In the beginning these problems are reported in the test report. After discussion with PA, it is decided that the errors are too frequent to include them each time.
- During the first part of the IMT (before DPU crash), 3 TCL scripts are updated by PACS to fix known problems detected during the IMT. It concerns the following scripts:
 - emissivity_SPEC_spu_setup.tcl
 - rsrf_SPEC_spu_setup.tcl
 - wavecal_SPEC_spu_setup.tcl
- During the second part of IMT (after DPU crash), 5 TCL scripts were updated on the CCS. It concerns the following scripts:
 - BOLO_cooler_OBS_shell.tcl
 - emissivity_SPEC_spu_setup.tcl
 - rsrf_SPEC_spu_setup.tcl
 - SPEC_dark_current_spt_eqmimt_obs_shell.tcl
 - wavecal_SPEC_spu_setup.tcl

2 Documents/Drawings

2.1 Applicable Documents

INSTRUMENT PLM EQM LEVEL TEST PROCEDURE

HP-2-ASED-PR-0051, issue 1.1 from 24.06.2005

EGSE CONFIGURATION PROCEDURE

HP-2-ASED-PR-0035, Issue 4 from 03.08.2005

INSTRUMENT TEST PROCEDURE

PACS-ME-TP-021, Issue 1.1 from 06.09.2005

2.2 Reference Documents

N/A

2.3 Other Documents

N/A

3 Configuration

3.1 PLM Configuration

SVM integrated with cryostat. Cryostat is at He II level (~1.7 K).

3.2 Environment

Environmental	Actual
Clean Room Class	100.000
Temperature	~21 °C
Rel. Humidity	~52.10 %
Pressure	~857 mbar

4 Conditions

4.1 Personnel

Responsibility	Name / Organization
Test Manager	S. Idler
Test Engineer	S. Ilsen
EGSE Operator	S. Ilsen
Instrument Engineer	H Feuchtgruber, T. Mueller, E. Wiezorrek
PA Responsible	D. Hendry / E. Lamprecht
ESA/Alcatel Representative	W. Pinter-Krainer, A. Heske / G. Doubrovik

4.2 Environmental

See chapter 3.2

4.3 General Precautions and Safety

N/A

4.3.1 General Safety Requirements, Precautions

N/A

4.3.2 ESD constraints

N/A

4.3.3 Special QA Requirements

N/A

4.4 EGSE

4.4.1 Hardware: CCS, EGSE's and DFE's

Item	Hardware Id	Serial No.
CCS	N/A	HPCCS 4
PLM SCOE	SE8426	03/001
CDMU DFE	SE8455	03/002
CRYO SCOE	EQM	N/A
IEGSE	N/A	N/A

4.4.2 Hardware: Prime Instrument

Item	Model	Remark
DPU	AVM	During the test, this module is exchanged with the CFM
SPU	AVM	
DEC/MEC	EM	

4.4.3 Software**Prime Instrument: PACS**

SW Ident	Issue /Version	Responsible	Comment
Inst OBS SPU	11.7	Inst	
Inst SPU boot OBSW	1.4	Inst	
Inst OBS DECMEC	5.0.25 Version for Mech control cold	Inst	V 5.0.24 Mech controller hot
Inst DECMEC boot OBSW	1.1	Inst	
Inst OBS DPU	7.65	Inst	
Inst DPU Boot OBSW	1.0	Inst	

Standby Instrument: HIFI

SW Ident	Issue /Version	Responsible	Comment
Inst ICU OBS	2.22	Inst	18.05.2005
Inst LCU OBS	17.0	Inst	01.10.2004

Standby Instrument: SPIRE

SW Ident	Issue /Version	Responsible	Comment
Inst DPU OBS	2.0.A1	Inst	

Inst DRCU OBS	Boot SW June 2003	Inst	
---------------	-------------------	------	--

IEGSE Configuration

SW Ident	Issue /Version	Responsible	Comment
MIB on I-EGSE	7_18	Inst	
HCSS Build Version	687	Inst	
PACS Build	20050706A	Inst	

CCS Configuration

SW Ident	Issue /Version	Responsible	Comment
TCL Scripts HIFI	ist_cus_0.7_tcl.zip	ASP	Delivered on 19.08.2005
TCL Scripts PACS	IMT_cus-shell-scripts_19092005.zip	ASP	Delivered on 19.09.2005
TCL Scripts SPIRE	SPIRE-SFTs-09092005.tar.gz + adapted script: SFT-SPIRE-CCS-DRCU-ON-STEP2.tcl	ASP	Delivered on 09.09.2005 (12.09.2005)
CCS MIB Bridge files	CCS_Her_PLM__01_v1_2.zip	ASP	2005-09-08
CCS S/W Release	2.0.614	Terma	

CDMU DFE Configuration

SW Ident	Issue /Version	Responsible	Comment
CDMU DFE CMS	2.3.0.0	SSBV	Part of CDMU DFE Workstation
CDMU DFE Pipe I/F (IPC Handler P7001)	2.4.0.0	SSBV	Part of CDMU DFE Workstation
CDMU DFE Pipe I/F (IPC Handler Pipe P7002)	1.2.1.0	SSBV	Part of CDMU DFE Workstation
CDMU archive Browser	2.2.2.72	SSBV	Part of CDMU DFE Workstation
Mil-STD-1553b BusMonitor	1.11.1.87	SSBV	Part of CDMU DFE Workstation
CDMU DFE IPC Handler object implementation	2.4.0.18	SSBV	Part of CDMU DFE Workstation
SimFE	1.5.0.0	SSBV	Part of CDMU DFE Platform
HLBC	1.07.00	SSBV	Part of CDMU DFE Platform

PLM SCOE Configuration

SW Ident	Issue /Version	Responsible	Comment
PLM SCOE CMS	1.5.0.0	SSBV	Part of PLM SCOE Workstation
PLM SCOE archive browser	2.2.1.70	SSBV	Part of PLM SCOE Workstation
PLM SCOE pipe I/F	1.3.0.0	SSBV	Part of PLM SCOE Workstation
PLM SCOE IPC Handler object implementation	2.1.0.7	SSBV	Part of PLM SCOE Workstation
PDU Controller	1.5.0.0	SSBV	Part of PLM SCOE Platform

Bus Profiles

The following bus profiles are loaded on the CDMU DFE. They are provided, checked and validated by Patrice Couzin (ASP). They were delivered by email on 01.09.2005

- PACS_prime_inst.PST
- SPIRE_prime_inst.PST
- HIFI_prime_inst.PST
- PACS_SPIRE_par.PST
- PACS_burst_mode.PST
- Inst_sdby.PST

The profiles allow one instrument in PRIME mode, while the others are in standby mode. This test will use only the following bus profile(s):

- PACS_prime_inst.PST (see Appendix 1)

4.4.4 *Special Equipment*

N/A

4.5 MIB

4.5.1 Version

The used MIB has reference: CCS_Her_PLM__01_v1_2.zip

And reference date: 2005-09-08

The MIB was received by email from Sonia Dos-Santos (ASP) on 08/09/2005

4.5.2 Configuration & Manual changes

The following files have been manually changed by Alcatel after the generation process (taken from the configuration.txt file included in the MIB):

- CDF.DAT
HPSDB does not allows fixed counter flags (ie CDF_ELTYPR=F for counters)
HPSDB NCR 478
- CDF.DAT
Problem on the (PTC,PFC)=(7,0) Variable octect string (PP004380).
PACS has the following data:
PC010380 E 8 32 PP004380 R
On HPSDB this line is generated
PC010380 E 0 32 0 PP004380 R
For now has been manually replaced.
- DPC.DAT
Add the line
HA000289 HU035197 63 1 Y N
HPSDB NCR, not possible to add User parameters on an alphanumeric display (NCR 495)
Note: The parameter HU035197 can not be loaded via S2K files, because is not associated to a Packet (NCR created 475)
Error HPSDB Solution: The parameter as been loaded by the an XML file Add_Parameter_HU035197.xml, to correct this problem.
- PLF.DAT
(HPSDB NCR 474) error when loading/generating SCOS TM packets has fixed and variable but with diferent definitions, (the following packet has the

parameter repeated 16 times on plf.dat, and repeated 0 times (variable) on the vpd.dat table)

The vpd.dat is corrected generated but not the plf.dat

replace the line (manual)

HM057190 80044289 0 0 1 0 0 0

by

HM056190 80044289 16 0 1 0 0 0

HM057190 80044289 17 0 64 0 0 0

- TCD.DAT

Generated empty by HPSDB, NCR 497 replaced by the one used on the tests week 28

- SCO.DAT

replaced by the one used on the tests week 28. This file shall be discussed with S. Ilsen because of the SCOE's names, HPSDB generates the names of the real elements.

- TMD.DAT

Add packets sent by SPIRE team by email on 31/08/2005

- PCF.DAT

Change PCF_VALPAR=0 on the parameter HU035197 inside of the pcf.dat. This was ok on HIFI, but not done on the XML file loaded

Add_Parameter_HU035197.xml

- PLF.DAT

Change the field PLF_LOGCC from NULL to 32 bits (see email from Luc Dubbeldam- HIFI on 06/09/2005)

HM057190 80044289 17 0 64 32 0 0

The following files have been changed manually by ASSED OTN (Stijn Ilsen):

- CAP.DAT – The decimal separator for the EQM CRYO SCOE calibration is manually changed from “,” to “.”. This also to solve problems with the EQM CRYO SCOE calibrations. EQM CRYO SCOE MIB will be updated by ASSED to avoid this problem in the future.
- TMD.DAT – The EQM CRYO packets have been added to the tmd.dat file on the CCS to make sure all EQM CRYO SCOE packets are forwarded to the IEGSE.

Remark: Because of NCR 1482, a MIB change was necessary after the first day of IMT. The CDF.DAT file is changed. Command PC162420 allows 8 entries for parameter PP067420, this is changed into 9.

5 Step by Step Procedure: Configure CCS and EGSE

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution - steps 1 to 9)

Step #	Action	Comments	Check
1	Note Testsession	2005_09_19_12_06_ilsens_hpws42_REA LTIME_P_IMT_1	OK
2	Power on CDMU DFE platform		OK
3	Power on PLM SCOE platform		OK
4	Power on the CDMU DFE workstation and wait for the BIST to finish.	Check: BIST successful?	OK
5	Power on the PLM SCOE workstation and wait for the BIST to finish.	Check: BIST successful?	OK
6	Execute "EGSE_CONFIG_AUTO.tcl" (see log in Appendix 3)	Check: PLM SCOE HK packets arriving	OK
		Check: CDMU DFE HK packets arriving	OK
		Check: Check name of bus profile (PST) in CDMU DFE HK or on CDMU DFE workstation Result: HIFI_prime_inst.pst This is done because the OBSW upload with HIFI as standby would be too slow.	OK
7	Execute "SubscribeParams.tcl"	Check: Wait until status of TCL file has changed to WAITING. This can take up to 10 minutes.	OK
8	Execute "Connect HIEGSE"	Check with IEGSE operators if IEGSE is connected.	OK
9	Execute "WARNING_LAMP_POWER_ON.tcl"	Not done since warning lamp is broken.	N/A
extra	Execute "connect EQMCRYO"		OK

6 Step by Step Procedure: Power On Instruments

Philosophy:

Before power on of any instrument, the PACS prime bus profile is loaded on the CDMU DFE. This means that HIFI and SPIRE are considered to be in standby mode from the beginning.

After the CDMU DFE configuration, the instruments are powered on in the following order:

- HIFI (to STANDBY mode)
- PACS (to PRIME mode)
- SPIRE (to STANDBY mode)

Monitoring:

All data coming from the instruments will be stored on the CCS. No active monitoring will be done on the instruments in standby mode. Of course limits will be monitored and checked and if necessary the instrumenters will be contacted and corrective actions taken.

For SPIRE a check list ("Common Herschel Instrument Checkout Procedure for IMT") is available to monitor regularly the status of the instrument. It is confirmed by SPIRE that these checks shall not be done during night and only sporadically during the day.

6.1 Power on HIFI to STANDBY Mode

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- SRON-G/HIFI/PR/2005-101 chapter 2.4.1 & 2.4.5

Remark: The actual switching of the LCL's (PLM SCOE switches) is done with the INSTR_POWER_ON.tcl script. The log file of this script can be found in Appendix 4

Remark: To speed up the booting of the ICU, it is decided by HIFI that chapter 2.4.5 should be executed instead of 2.4.1 (nominal power on procedure). Chapter 2.4.5 powers on the ICU, uploads new OBSW and boots from this new OBSW.

Step #	Action	Comments	Check
1	Apply power to ICU	Select ICU_housekeeping AND	OK
		Check voltage in the range 26V – 29V Actual value = 27.9 V	OK
		Check ICU current draw is 480 - 560 mA Actual value = 0.52 A	OK
		Check for receipt of (5,2) event packet after power-on	OK
2	Upload new OBSW	The stack file (OBS2_22.hpws42) containing the OBSW is adapted since a new version of the MIB is used on the CCS. The version is 07092005. This is entered in the first line of the stack file.	OK
		Load stack file "OBS2_22.hpws42"	OK
		Arm All -> Send	OK
		Send Command HIFI_load_boot	OK
		No reply (as expected by HIFI)	
		Bus is cycled and no HK is coming in.	OK
		RESET button is pressed and HK is coming in	OK
		Continue 2.4.1 after POWER ICU	OK
		Check for receipt of HK packets every 3 sec	OK
		Check OBS version	OK
		Result: 2.16hex = 2.22dec	
Compare HK (secondary supply voltages) with previous results	OK		
	This could not be done since HIFI is not present. No out-of-limits have been crossed, so it is assumed that all values are OK.		
2	Manual Stack command: HIFI_Housekeeping_on HIF_HK_rate=1_pkt_per_s ec	Select ICU_housekeeping and HRH_analog AND's	OK
		Check for HK updates every 1 sec (1,1) packet arrived causing a SSC error. This is a result	OK

		from the OBSW upload.	
		Check FCU HK received and no limit errors	OK
		This could not be done since HIFI is not present. No out-of-limits have been crossed, so it is assumed that all values are OK.	
3	Apply power to FCU	Check power supply HK fields are green (FCU SCOE display).	OK
		This is done by ASED personal according to procedure: SRON-G/HIFI/PR/2005-102	
4	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on	Check that the voltages and currents are within the following ranges PS1: "+15V": +15.6V – +16.4V, 107mA – 131mA; 15.853 0.114 "-15V": -16.4V – -15.6V, 78mA – 96mA; -15.824 0.086 "+5V": +5.5V – +6.0V, 119mA – 147mA. 5.946 0.133 PS2: "+18V": +17.0V – +19.0V, 120mA – 148mA; 18.007 0.132 "-18V": -18.0V – -17.0V, 104mA – 128mA; -18.014 0.116 "+8V": +7.0V – +9.0V, 16mA – 26mA. 8.003 0.021	OK
5	Apply power to HRH	<i>Select ICU_housekeeping and HRH_analog AND's</i>	OK
		Check voltage in the range 26V – 29V Actual value = 27.7 V	OK
		Check HRH current draw is 2.2A – 2.8A Actual value = 2.4 A	OK
6	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on HIF_HRSH_s=on	Check HRH HK received and no limit errors	OK
7	Apply power to WEH	<i>Select ICU_housekeeping and WBS_H AND's</i>	OK
		Temperature out of limit (soft): HM075192 HM076192 This is due a faulty calibration	
		This known error is already traced in ASED-NCR-1261	
		Check voltage in the range 26V – 29V Actual value = 27.9 V	OK
		Check WEH current draw is 0.9A – 1.0A Actual value = 0.94 A	OK
8	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on HIF_HRSH_s=on	Check WBS_H HK received and no limit errors	
		This command failed the command completion. This is a known NCR: 1262	

	HIF_WBSH_s=on		
9	Apply power to <u>LCU</u>	Select ICU_housekeeping and LCU_status AND's	OK
	In procedure HRH is mentioned, this is a type error, it should be LCU. This known error is already traced in ASED-NCR-1260	Check voltage in the range 26V – 29V Actual value = V	OK
		Check WEH current draw is 0.69A – 0.72A Actual value = A	OK
10	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on HIF_HRSH_s=on HIF_WBSH_s=on HIF_LCU_s=on	Check LCU HK received and no limit errors This command failed the command completion. This is a known NCR: 1262	OK

Remark: After this power on, the HIFI_housekeeping_on command is send to change the HK rate to once every 5 seconds.

6.2 Power on PACS to PRIME Mode

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- PACS-ME-TP-021 (Issue 1.1 – 06/09/05 – chapter 4.1)

Important remark : At this point the bus profile has changed from HIFI_prime_inst.pst to PACS_prime_inst.pst. This because HIFI needs a time-consuming OBSW upload to power on, which would take double the time in case the HIFI was non-prime in the bus profile.

Configuration Check:

Step #	Action	Comments	Check
1	PACS warm electronics is mounted on the SVM		OK
2	28 V power is connected to CCS power supplies		OK
3	PACS OBT interface is connected to CCS OBT simulator		OK
4	DPU 1553 interface is connected to CDMU DFE		OK
5	The CDMU DFE is up and running bus list "nominal"	PACS_prime_inst.pst	OK
6	PACS+EGSE grounding has been verified against AD-7		OK
7	Check that all TOPE-Tcl scripts (sec.10) are accessible via the CCS	All received PACS TCL scripts have been added to the CCS. No time was available to check this. In case TCL scripts would be missing, they will be added to the running CCS session later.	OK

Remark: During the power on multiple out of limits were reported. This is a known ASED NCR 1276. Also a SSC error was reported on the CCS (known ASED NCR 1247).

Step #	Action	Comments	Check
1	Execute script: PACS_POWER_ON.tcl (log see Appendix 5)	During the PACS_POWER_ON.tcl script the CCS reported a TOPE CORBA error. The CCS process EXIF_TM1 was restarted after which the script was repeated. This is a known ASED NCR 1440.	NOK

		PACS is sending regular non-Prime HK packets and essential HK packets	OK
		1355 links DPU-SPUS, DPU-SPUL, DPU-DMC, DMC-SPUS, DMC-SPUL, DMC-BOLC are on and communicating	OK
		Counters for TM(1,2), TM(1,8) and NACKs shall be 0	OK
		" 28 V power is on for all 4 sub-systems	OK

6.3 Power on SPIRE to STANDBY Mode

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- SPIRE-RAL-PRC-002494 (Issue 1.1 Appendix 1 – 09/09/05)

Step #	Action	Comments	Check
1	CCS 28V Power Supply to the DPU is available		OK
2	SPIRE MIB is imported in the CCS database.		OK
3	CCS is up and running (SCOS, TOPE and the CDMU Simulator)		OK
4	DPU AND OBS PARAMETERS display is selected on the CCS		OK

6.3.1 SFT-SPIRE-CCS-DPU-ON

Purpose: To switch on the SPIRE DPU and start generating housekeeping

Step #	Action	Comments	Check
1	Power on the SPIRE DPU using the CCS 28V Power Supply	This action is performed from INSTR_POWER_ON.tcl (see Appendix 6) Result: <ul style="list-style-type: none"> • Voltage: 27.8 V • Current: 0.45 A (5,2) packet received	OK
2	Execute TCL script SFT-SPIRE-CCS-DPU-ON.tcl		OK
3	Check that THSK parameter on the DPU AND OBS PARAMETERS display on SCOS is refreshing every second	THSK incrementing every second	OK
4	Check that TM2N parameter on the DPU AND OBS PARAMETERS display on SCOS is incrementing every second	TM2N incrementing every second	OK

Final Configuration: SPIRE DPU is on but the DRCU is still off

6.3.2 SFT-SPIRE-CCS-DRCU-ON

Purpose: To switch on the SPIRE DRCU and start generating housekeeping

Step #	Action	Comments	Check
1	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP1.tcl	HK stopped as expected Remark: This script sends more then 2 TC's a second. The current bus profile (HIFI_prim_inst.pst) does not allow this and puts the TC's in a queue. This caused multiple SSC errors, although no packets or TC's are lost. This error is traced in a new ASED NCR 1471	OK
2	Check that THSK parameter is not refreshing anymore		OK
3	Check that TM2N parameter is not incrementing anymore		OK
4	Ensure the SPIRE Power Bench is connected to the mains – see Figure 2.		OK
	Ensure all 5 remote DCU switches are in the off position – see Figures 3 & 4 below.		OK
	Switch on the Primary Power on the back of the SPIRE Power Bench (Figure 2).	Prime power led becomes orange Main power led becomes green	OK
	Switch on the Secondary Power on the front of the SPIRE Power Bench by pulling out and lifting up the switch (shown in yellow circle in Figure 5)	Secondary power led becomes red	OK
5	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP2.tcl	Remark: This script sends more then 2 TC's a second. The current bus profile (HIFI_prim_inst.pst) does not allow this and puts the TC's in a queue. This caused multiple SSC errors, although no packets or TC's are lost. This error is traced in a new ASED NCR 1471 Since this script has a lot of TC's inside, the tie between	OK

		<p>sending the TC from the CCS and actual acceptance on the instrument went up to 35 seconds.</p> <p>This caused a series of SSC errors.</p> <p>Because issue 1.1 was used instead of 1.2, the HK is coming in each second instead of each 4 seconds. This is communicated to SPIRE.</p>	
6	Manual Switch on of the DRCU by the CCS staff step 2: <ul style="list-style-type: none"> Switch on all 5 remote DCU switches 		OK
7	Check that THSK parameter is again refreshing every second	THSK incrementing every 4 second	OK
8	Check that TM2N parameter is again incrementing every second	TM2N incrementing every 4 second	OK

Final Configuration:

- SPIRE DPU and DRCU are both on
- HK generation is on

6.3.3 SFT-SPIRE-CCS-FUNC-SCU-03**Purpose: SCU DC thermometry check**

Step #	Action	Comments				Check
1	Execute TCL script SFT-SPIRE-CCS-FUNC-SCU-03.tcl					OK
2	Wait for the parameter BBFULLTYPE to get set to SCU_DC_Therm					OK
3	A few seconds later record the value of parameter SCUTEMPSTAT	Check if the following parameters change value:				
		Parameter	Start	During	End	
		SCUTEMPSTAT Observed	0 000000	FFFF 0000FF FF	FFFF 0000FF FF	OK
4	Record the RAW values	Parameter	Value			OK

of SCU temperatures	PUMPHTRTEMP	4.02
	PUMPHSTEMP	7.94
	EVAPHSTEMP	7.38
	SHUNTTEMP	1.57
	SOBTEMP	10.9
	SL0TEMP	1.95
	PL0TEMP	2.03
	OPTTEMP	10.39
	BAFTEMP	10.09
	BSMIFTEMP	9.64
	SCAL2TEMP	8.21
	SCAL4TEMP	10.56
	SCALTEMP	10.67
	SMECIFTEMP	10.73
	SMECTEMP	11.19
BSMTEMP	9.78	

Final Configuration: Unchanged

6.3.4 SFT-SPIRE-CCS-FUNC-SCU-06

Purpose: SCU AC thermometry check

Preconditions: SPIRE CQM is electrically integrated with the Herschel EQM

Initial Configuration:

- SPIRE DPU is on and generating HK
- DRCU is switched ON
- SCU PARAMETERS display is selected on the CCS

Step #	Action	Comments	Check												
1	Execute TCL script SFT-SPIRE-CCS-FUNC-SCU-06.tcl		OK												
2	Wait for the parameter BBFULLTYPE to get set to SCU_AC_Therm		OK												
3	A few seconds later record the value of parameter SUBKSTAT	Check if the following parameters change value:													
		<table border="1"> <thead> <tr> <th>Parameter</th> <th>Start</th> <th>During</th> <th>End</th> </tr> </thead> <tbody> <tr> <td>SUBKSTAT</td> <td>0</td> <td>1</td> <td>1</td> </tr> <tr> <td>Observed values</td> <td>0</td> <td>1</td> <td>1</td> </tr> </tbody> </table>	Parameter	Start	During	End	SUBKSTAT	0	1	1	Observed values	0	1	1	OK
		Parameter	Start	During	End										
SUBKSTAT	0	1	1												
Observed values	0	1	1												
4	Record the RAW value of SUBKTEMP	Check if the following parameters change value:													
		<table border="1"> <thead> <tr> <th>Parameter</th> <th>Start</th> <th>During</th> <th>End</th> </tr> </thead> <tbody> <tr> <td>SUBKTEMP</td> <td>?</td> <td></td> <td>?</td> </tr> </tbody> </table>	Parameter	Start	During	End	SUBKTEMP	?		?	OK				
		Parameter	Start	During	End										
SUBKTEMP	?		?												

		Observed values	-	-	2.28	
5	Note down the value of the MODE parameter on the DPU AND OBS PARAMETERS display	Parameter	Start	During	End	OK
		MODE	-	-	REDY	
		Observed values	-	-	REDY	

Final Configuration: Unchanged

6.3.5 Extra

Because SPIRE-CCS-DRCU-ON-STEP2 was executed instead of SPIRE-CCS-DRCU-ON-STEP2-STBY, the SPIRE HK rate was once every second instead of once every 4 seconds. SPIRE informed us that this can be solved by running SPIRE-CCS-DRCU-ON-STEP1 and afterwards SPIRE-CCS-DRCU-ON-STEP2-STBY.

Step #	Action	Comments	Check
1	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP1.tcl	HK stopped as expected	OK
5	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP2-STBY.tcl	HK coming in at a rate of one every 4 seconds. The MODE is now ON instead of REDY. This has been discussed with SPIRE and is nominal.	OK

7 Step by Step Procedure: PACS IMT results

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 11)
- PACS-ME-TP-021

Important Remark: The HK and science data checks in this chapter are executed by PACS personal on the IEGSE. This report is focussed on ‘command and control’ issues and only those issues will be discussed below. A separate PACS report will be generated to discuss all science data analysis.

7.1 Test ID: 401 - PACS Switch on

This script is already executed as part of the PACS power on (see chapter 0)

7.2 Test ID: 402 - Memory Management Test

Step #	Action	Comments	Check
1	Send command from SCOS2000: DPU_MEMORY_LOAD_DRAM Parameters: Repeater value: 1 DPU_MEMORY_BLOCK_ID: 0x1100 DPU_MEMORY_ADDR : 0x1FB2 DPU_4_BYTES_WORDS_DATA: 0x7D0 DPU_CHECKSUM: 0xD62A	Check in HK that DPU OBSW telecommands lost counter will go to 20 Counter indicates 2000 instead of 20. PACS will investigate.	NOK
2	Send command from SCOS2000: DPU_MEMORY_CHECK Parameters: DPU_MEMORY_BLOCK_ID: 0x1100 DPU_MEMORY_ADDR : 0x1FB1 DPU_DATA_LENGTH: 1	Reported checksum is 0xD62A Checksum is DC10 instead of D62A. An NCR is raised to cover this (ASED NCR 1493)	NOK
extra	Send command from SCOS2000: DPU_MEMORY_CHECK Parameters: DPU_MEMORY_BLOCK_ID: 0x1100 DPU_MEMORY_ADDR : 0x1FB2 DPU_DATA_LENGTH: 1	Reported checksum is 0xD62A	OK
3	Send command from SCOS2000: DPU_MEMORY_DUMP Parameters: DPU_MEMORY_BLOCK_ID: 0x1100 DPU_MEMORY_ADDR : 0x1FB2 DPU_DATA_LENGTH: 1	Dumped value is 0x7D0	OK

7.3 Test ID: 403 - PACS Setup of Spectroscopy with CSs off and Open Grating Launch Lock

Only step b is executed.

Remark: At this point a response from SPIRE is received to change the HK rate. (see chapter 6.3.5)

Remark: During the next script multiple out of limits were reported. This is a known ASED NCR 1276. Also SSC errors are reported on the CCS (known ASED NCR 1247).

Step #	Action	Comments	Check
1	Execute: SetupSpectroscopyCSoff_Shell.tcl	This script failed during its execution. The command PC162420 allows 8 times parameter PP067420, but the TCL script tried to send 9 times this parameter. The script stopped after this command (~75% of script executed). An NCR is raised (ASED NCR 1482)	NOK
		Spectroscopy HK packets are sent	N/A
		Nominal detector setting (C=0.3pF, r=64, bias=[210mV, 70mV], heater=200uA)	N/A
		Chopper controller on	N/A
		Grating controller on and grating homing completed	N/A
extra	To put the instrument in a safe mode after a not fully completed TCL script, the following script is run: ENTER_SAFE_Mode_Shell.tcl		OK

Important Remark: This end the first day of IMT (19/09/2005).

Important Remark: At this point the second day of IMT (20/09/2005) is started. The CCS is restarted, because the connection with the server was lost (new session name: 2005_09_20_06_18_ilsens_hpws42_REALTIME_P_IMT_2) and all connections are restored (CDMUDFE, PLMSCOE, HIEGSE, EQMCRYO).

Important Remark: Because of NCR 1482, a MIB change is necessary. The current CCS session is stopped, the CDF.DAT file is changed and a new CCS session is started (new session name: 2005_09_20_07_07_ilsens_hpws42_REALTIME_P_IMT_3). After startup, all connections are restored (CDMUDFE, PLMSCOE, HIEGSE, EQMCRYO). HIFI and PACS have been checked briefly and are OK.

7.4 Test ID: 403 - PACS Setup of Spectroscopy with CSs off and Open Grating Launch Lock

Only step b is executed.

Remark: This test step is repeated since it was not completely executed yesterday.

Remark: During the next script multiple out of limits were reported. This is a known ASED NCR 1276. Also SSC errors are reported on the CCS (known ASED NCR 1247).

Step #	Action	Comments	Check
1	Execute: SetupSpectroscopyCSoff_Shell.tcl	Spectroscopy HK packets are sent	OK
		Nominal detector setting (C=0.3pF, r=64, bias=[210mV, 70mV], heater=200uA)	OK
		Chopper controller on	OK
		Grating controller on and grating homing completed	OK

7.5 Test ID: 404 – Grating Test

Remark: During the next script the CCS was restarted (server + workstations). A new session is started and all connections were restored. New session name:
2005_09_20_07_53_ilsens_hpws42_REALTIME_P_IMT_4

Step #	Action	Comments	Check
1	Execute: PACS_Spec_Gra_Diaghk_Setup.tcl	This TCL script blocked during its execution while it was requesting the output for procedure getChkSum. This procedure was not found by the CCS. A check was done and the procedure is available. It was used during last 2 SFTs without problems. Since the CCS showed some strange behaviour in the morning (workstation is restarted for this), it is chosen to restart the CCS server and all workstation to make a clean start. (new session name: 2005_09_20_07_53_ilsens_hpws42_REALTIME_P_IMT_4)	NOK
extra	Execute (second time): PACS_Spec_Gra_Diaghk_Setup.tcl	Diagnostic HK packets are produced	OK
2	Execute: SPEC_Gra_Healthcheck_obs_Shell.tcl	During the execution the DEC/MEC got blocked (according to PACS). The script is aborted and a manual stack command is executed: PC005380 (DPU_SET_FUNCT) With the following parameter: PP007380 = 103 PP006380 = 1	NOK

		<p>An NCR is raised to track this problem. (AED NCR 1494)</p> <p>During this multiple out of limits were reported. This is a known ASSED NCR 1276. Also SSC errors are reported on the CCS (known ASSED NCR 1247).</p> <p>Grating moves between extreme values (<100000 and >900000)</p>	
3	Execute: PACS_Diaghk_Reset.tcl	Production of diagnostic HK packets stops	OK

7.6 Test ID: 406 – Thermal Behaviour Test in Spectroscopy

Step #	Action	Comments	Check
1	Execute: ENTER_SAFE_Mode_Shell.tcl	Check that PACS is in SAFE mode	OK
2	Execute: SPEC_thermal_OBS_shell.tcl	0 Check that spectroscopy HK packets are sent and temperature Sensors are on	OK
	<p>During the script, PACS detected some problems and 2 manual stack commands were executed during the execution of the TCL. The script is not stopped. PC005380 (DPU_SET_FUNCT) With the following parameter: PP007380 = 103 PP006380 = 1</p> <p>PC013380 (DPU_STOP_OBCP) With the following parameter: PP012380 = 27</p>	1 Check that blue array is on and biased	OK
		3 Check that red array is on and biased	OK
		5 Check that both arrays and DEC's are off	OK
		7 Check that both arrays are on and biased	OK
		9 Check that both arrays are off, but DEC's are on	OK
		11 Check heater current sequence with 50/100/200 microA and temperatures of the blue module with sensors	OK
		26 Check that both arrays are on, biased and blue heater current is at 200 microA	OK
		31 Check that chopper is chopping for 5 min	OK
		36 Check tht grating is homing	OK
		41 Check grating and chopper operation for about 5 min	NOK
		49 Check that CS's are powering	NOK
		69 Check that CS's are off again	
		71 Check that chopper and grating controllers are off	OK
		73 Check that arrays and DEC's are switched off, heater current set to zero	OK

		again	
		78 Check that HK packets are set to "NonPrime"	OK
3	Execute: ENTER_SAFE_Mode_Shell.tcl	Check that PACS is in SAFE mode	OK

7.7 Test ID: 407 – Setup Spectroscopy, Data Rate and Cryostat Background Adjustment

Step #	Action	Comments	Check
1	Execute: SetupSpectroscopyEQMIMT_Shell.tcl	Spectroscopy HK packets are sent	OK
		Nominal detector setting (C=0.3pF, r=64, bias=[210mV,70mV], heater=200uA)	OK
		Chopper controller on	OK
		Grating controller on and grating homing completed	OK
		Calibration sources are heating up	OK
2	Execute: SPEC_spu_data_rate_obs_Shell.tcl	Check that chopper moves to CS2	OK
		Check correct display of science data in QLA	OK
		Check that chopper moves to zero	OK
3	Execute: Background_Adjustment_Shell_01.tcl	Monitor detector signal due to cryostat background in comparison to signal of internal calibration sources	OK
4	Execute (again): Background_Adjustment_Shell_01.tcl During this part of the script, the cover temperature is adjusted.	Continue monitoring cryostat background signal until the signal level reaches a value between the CS1 and CS2 signal	OK
extra	Execute (again): Background_Adjustment_Shell_01.tcl During this part of the script, the cover temperature is adjusted.	Continue monitoring cryostat background signal until the signal level reaches a value between the CS1 and CS2 signal	OK
extra	Execute (again): Background_Adjustment_Shell_01.tcl During this part of the script, the cover temperature is adjusted.	Continue monitoring cryostat background signal until the signal level reaches a value between the CS1 and CS2 signal	OK
5	Execute: Background_Adjustment_Shell_02.tcl	Monitor detector signal	OK
6	Execute: Background_Adjustment_Shell_03.tcl	Monitor detector signal	OK
7	Execute: Background_Adjustment_Shell_04.tcl	Monitor detector signal	OK
8	Execute: Background_Adjustment_Shell_05.tcl	Monitor detector signal	OK

7.8 Test ID: 408 – Chopper Full FOV Scan in Spectroscopy

Step #	Action	Comments	Check
1	Execute: SPEC_Chop_fft_eqmimt_obs_Shell.tcl	Diagnostic HK for chopper is activated	OK
		Grating is on position 461000	OK
		First chopper scan is from - 25000 to +25000 in steps of 500	OK
		Observing time is 5 seconds on each position	OK
		Second chopper scan is from +25000 to - 25000 in steps of 500	OK
		Diagnostic HK is deactivated	OK
		Chopper and grating move back to their default positions	OK


7.9 Test ID: 409 – Reconfiguration and Optional Switch-off/on Cycle

Since we are not at the end of a day, only step a is executed.

Step #	Action	Comments	Check
1	Execute: ENTER_SAFE__Mode_Shell.tcl	PACS is in SAFE mode	OK
2	Execute: PACS_Switch_Off_CCS.tcl	PACS is sending no TM packets anymore and the 28 V power is off	N/A
3	Wait >10 sec		N/A
4	Execute: PACS_Switch_On_CCS.tcl	PACS is sending regular non-Prime HK packets and essential HK packets	N/A
		1355 links DPU-SPUS, DPU-SPUL, DPU-DMC, DMC-SPUS, DMC-SPUL, DMC-BOLC are on and communicating	N/A
		Counters for TM(1,2), TM(1,8) and NACKs shall be 0	N/A
		28 V power is on for all 4 sub-systems	N/A

7.10 Test ID: 410 – Cooler Recycling

Step #	Action	Comments	Check
1	<p>Execute: BOLO_cooler_OBS_shell.tcl</p> <p>During the script, PACS requested to send a manual stack command to request more HK packets. The script is not stopped. The following command is send: PC003380 (DPU_SET_HK_LIST) With the following parameter: PP005380 = PHOT PP025380 = BOTH Array</p> <p>During the cooldown the DEC/MEC connection was lost. To recover from this without loosing the cooler recycle, DEC/MEC is manually powered down and up again. After this all DEC/MEC commands in the PACS_POWER_ON.tcl are executed with the manual stack. This was not successful. Another approach is tried:</p> <ul style="list-style-type: none"> • power down SPU, DEC/MEC, DPU (manually from PLM SCOE) • Execute PACS_POWER_ON_BOLCout.TCL (see Appendix 7) • PC003380 (with PP005380 = PHOT and PP025380 = BOTH Array) <p>This problem is track by a new NCR (ASED NCR 1494).</p> <p>The cooler recycle itself was not successful. An NCR is raised to track this problem. (ASED NCR 1495)</p>		NOK



Step #	Action	Comments	Check
1	Execute: ENTER_SAFE_Mode_Shell.tcl	Check that PACS is in SAFE mode	OK

Important Remark: This ends the second day of IMT (20/09/2005).

Important Remark: This is the start of the 3rd day of IMT (21/09/2005). Since yesterday, the cooler recycle was not successful, the tests that require this are moved to the end of IMT and we continue now with the tests planned for day 4.

7.11 Test ID: 516 – Detector Dark Current on Internal Calibration Sources

Step #	Action	Comments	Check
1	Execute: SetupSpectroscopyCSoff_Shell.tcl	Spectroscopy HK packets are sent	OK
		Nominal detector setting (C=0.3pF, =64, bias=[210mV,70mV], heater=200uA)	OK

		Chopper controller on	OK
		Grating controller on and grating homing completed	OK
2	Execute: SPEC_dark_current_spt_eqmimt_obs_shell.tc 1	Check that the chopper moved to position -22605 cu. (CS1)	OK
		CRE setup has ramp length of 512 for blue and red and capacitor is 0 for 100fF	OK
		Buffer Transmission Mode is activated	OK
		Check that after 10 minutes of measurements on CS1 the chopper moved to position 24162 cu. (CS2)	OK
		SPU reset is done after 10 minutes of measurements on CS2	OK
		Chopper moved to default position 0 cu.	OK
		CRE setup is set back to its default values	OK
	<p>During this test, a lot of SSC errors were detected on the following packets (APID: 1157, Type 21, Subtype 1).</p> <p>To solve this, during this test, the bus profile is changed to PACS_burst_mode.pst on request of PACS and the following command is sent: PC009380 (DPU_SET_BUS_LIST) – Enabled.</p> <p>Now both the DPU and the CDMU DFE are configured for PACS burst mode and no SSC errors are reported for the packets mentioned above. After this change 2 more SSC errors were detected, both on HK packets (3,25 – APID 1152)</p> <p>This problem is tracked with a new NCR (ASED NCR 1496)</p> <p>During the execution of this script (towards the end), the connection between CDMU DFE and CCS is lost. Just before this occurred, CCS reported “IFMGRconn: Telecommand buffer size just reached 103 for SCOE HIEGSE”.</p> <p>This looks a lot like a hick-up in the network. Further investigation will be done if this problem happens again.</p>		

7.12 Test ID: 517 – Grating Performance Test

Remark: The bus profile is changed back to PACS_prime_inst.pst

Step #	Action	Comments	Check
1	Execute: ENTER_SAFE_Mode_Shell.tcl	PACS is in SAFE mode	OK
2	Execute: SetupSpectroscopyEQMIMT_Shell.tcl	Spectroscopy HK packets are sent	OK
		Nominal detector setting (C=0.3pF, r=64, bias=[210mV,70mV], heater=200uA)	OK
		Chopper controller on	OK

		Grating controller on and grating homing completed	OK
		Calibration sources are heating u	OK
3	Execute: PACS_Spec_Gra_Diaghk_Setup.tcl	Diagnostic HK packets are produced	OK
4	Execute: SPEC_Gra_slew_time_cal_Shell.tcl	Grating moves between extreme values	OK
5	Execute: PACS_Diaghk_Reset.tcl	Production of diagnostic HK packets stops	OK

7.13 Test ID: 518 – Chopper Performance Test Spectroscopy

Step #	Action	Comments	Check
1	Execute: SPEC_Chop_spt_eqmimt_obs_shell.tcl	Diagnostic HK for chopper is activated	OK
		CRE setup has ramp length of 32	OK
		OBCP08 is executed (with 3 ramps per chopper plateau)	OK
		CRE setup has ramp length of 16	OK
		OBCP08 is executed (with 2 ramps per chopper plateau)	OK
		CRE setup has ramp length of 32	OK
		OBCP27 is executed (with 5 ramps per chopper plateau)	OK
		OBCP27 is executed (with 3 ramps per chopper plateau)	OK
		CRE setup has ramp length of 16	OK
		OBCP27 is executed (with 3 ramps per chopper plateau)	OK
		OBCP27 is executed (with 2 ramps per chopper plateau)	OK
		CRE setup is set back to its default values	OK
		Diagnostic HK for chopper is deactivated	OK

7.14 Test ID: 519 – Emissivity of internal calibration sources

Step #	Action	Comments	Check
1	Execute: SPEC_spu_reset.tcl	Science data flow stops	OK
2	Execute: emissivity_SPEC_cre_setup.tcl	CRE HK values as commanded	OK
3	Execute: emissivity_SPEC_SPU_setup.tcl	Science data flow starts	OK

	In this script 2 commands were missing according to PACS. This was caused by a translation error from CUS to TCL scripts. The 2 missing commands have been manually send. PC039400 and PC040390.		
4	Execute: emissivity_SET_temp_cs2_50.tcl	CS2 temperature decreases	OK
5	Execute: emissivity_SPEC_full_cs1_scan.tcl	Grating moves in steps of 1600 up + down over full range	OK
6	Execute: emissivity_SET_temp_cs1_50.tcl	CS1 temperature decreases	OK
7	Execute: emissivity_SPEC_full_cs2_scan.tcl During this test a (5,2) was received from the PACS DPU (2005.264.09.11.36.585). According to PACS this can only be caused by a power cycle. The PLM SCOE HK does not show any power abnormalities. The force boot command is send and HK is coming in. To restart testing a power cycle is needed. This problem is tracked by ASED NCR 1490 and is probably related to ASED NCR 1991)	Grating moves in steps of 1600 up + down over full range	NOK
extra	Execute: PACS_POWER_OFF.tcl		OK
extra	Execute: PACS_POWER_ON.tcl		OK
extra	Execute: SetupSpectroscopyCSoff_Shell.tcl After execution of this script. The CCS process EXIF_TM1 died without any reason. The process is restarted and the script SubscribeParams has been stopped and started again. This is a known problem and is tracked with ASED NCR 1440		OK
extra	Send Manual Stack Command: PC140420 (DMC_SET_TEMP_BB_1) With PP094420 = 59 Ohm (Eng)		OK
extra	Send Manual Stack Command: PC144420 (DMC_SET_TEMP_BB_2) With PP094420 = 59 Ohm (Eng)		OK
extra	Unrelated to the previous error, 3 updated TCL scripts are loaded onto the CCS.	emissivity_SPEC_spu_setup.tcl rsrf_SPEC_spu_setup.tcl wavecal_SPEC_spu_setup.tcl	OK
extra	Execute: SPEC_spu_reset.tcl	Science data flow stops	OK
extra	Execute: emissivity_SPEC_cre_setup.tcl	CRE HK values as commanded	OK
extra	Execute: emissivity_SPEC_SPU_setup.tcl	Science data flow starts	OK
8	Execute: emissivity_SET_temp_cs2_90.tcl	CS2 temperature increases	N/A

	Script is skipped because of previous error		
9	Execute: emissivity_SPEC_full_cs1_scan.tcl Script is skipped because of previous error	Grating moves in steps of 1600 up + down over full range	N/A
10	Execute: emissivity_SET_temp_cs1_90.tcl Script is skipped because of previous error	CS1 temperature increases	N/A
11	Execute: emissivity_SPEC_full_cs2_scan.tcl During this script, suddenly all CRC checks failed on all PACS packets. PACS reacted by sending command PC367380 (DPU_RESET_1553). Apparently this is a known PACS bug which occurs every ~30 hours. To track this problem a new NCR is rased (ASED NCR 1497) In the time all packets were rejected, something went wrong and PACS asked for some manual stack commands to make sure everything is configured correctly. This is done by the following manual commands: PC005380 (DPU_SET_FUNCT) With the following parameter: PP007380 = 103 PP006380 = 1 PC108420 (DMC_SWON_GRAT_CONT) PC110420 (DMC_ENABLE_GRAT_CONT) After these commands it is noticed that no PACS packets are coming in anymore. The PLM SCOE reported 28 V, but no current on the DPU. The time the current went to 0 is 2005.264.10.26.20.00. PACS is powered down (PACS_POWER_OFF.tcl see Appendix 8) During the power off procedure the current went back up to ~0.45 A and multiple (5,4) ERROR_REPORT packets arrived on the CCS. Power profile of this situation is in Appendix 18	Grating moves in steps of 1600 up + down over full range	
12	Execute: emissivity_SET_temp_cs2_75.tcl	CS2 temperature decreases	N/A
13	Execute:	Grating moves in steps of 1600 up +	N/A

	emissivity_SPEC_full_cs1_scan.tcl	down over full range	
14	Execute: emissivity_SET_temp_cs1_70.tcl	CS1 temperature decreases	N/A
15	Execute: emissivity_SPEC_full_cs2_scan.tcl	Grating moves in steps of 1600 up + down over full range	N/A
16	Execute: SPEC_spu_reset.tcl	Check that science data flow stops	N/A

Important Remark:

At this point it is concluded in a NRB related to ASED NCR 1491 that the PACS DPU should be dismantled and changed with a new DPU. To do this in a safe and controlled way, all instruments are shut down according to their relevant procedure.

The DPU AVM is changed for the DPU CFM (OBSW 7.68). More details can be found in ASED NCR 1491. PACS indicates that the operation of both DPU's should be very similar. The only differences are:

- A (5,1) packet instead of a (5,2) at booting.**
- A minimum of 4 minutes wait time between a power off and power on**

8 Step by Step Procedure: Switch Off Instruments

8.1 Switch Off HIFI

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 12)
- SRON-G/HIFI/PR/2005-101 chapter 2.4.3

Remark : Switching of LCLs has been done with INSTR_POWER_OFF.tcl (see Appendix 9)

Step #	Action	Comments	Check
1	Select LCU_status AND	Verify LCU is in standby mode. Do not continue if this is not so!	OK
2	Switch off power to LCU	Check voltage and current go to zero.	OK
3	Switch off power to WEH	Check voltage and current go to zero.	OK
4	Switch off power to HRH	Check voltage and current go to zero.	OK
5	Switch off power to ICU	Check voltage and current go to zero.	OK
6	Switch off power to FCU manually (executed by HIFI)	Check voltage and current go to zero.	OK

8.2 Switch Off SPIRE

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- SPIRE-RAL-PRC-002494 (Issue 1.1 Appendix 2 – 09/09/05)

Remark : Switching of LCLs has been done with INSTR_POWER_OFF.tcl (see Appendix 9)

8.2.1 SFT-SPIRE-CCS-FUNC-THO

Purpose: Switch off SCU DC and AC thermometry – if necessary

Step #	Action	Comments	Check								
1	Execute TCL script SFT-SPIRE-CCS-FUNC-THO.tcl		OK								
2	A few seconds later record the value of parameter SCUTEMPSTAT	Check if the following parameters change value:									
		<table border="1"> <thead> <tr> <th>Parameter</th> <th>Start</th> <th>During</th> <th>End</th> </tr> </thead> <tbody> <tr> <td>SCUTEMPSTAT</td> <td>FFFF</td> <td>-</td> <td>0</td> </tr> </tbody> </table>	Parameter	Start	During	End	SCUTEMPSTAT	FFFF	-	0	OK
		Parameter	Start	During	End						
SCUTEMPSTAT	FFFF	-	0								
3	A few seconds later record the value of parameter SUBKSTAT	Check if the following parameters change value:									
		<table border="1"> <thead> <tr> <th>Parameter</th> <th>Start</th> <th>During</th> <th>End</th> </tr> </thead> <tbody> <tr> <td>SUBKSTAT</td> <td>1</td> <td>-</td> <td>0</td> </tr> </tbody> </table>	Parameter	Start	During	End	SUBKSTAT	1	-	0	OK
		Parameter	Start	During	End						
SUBKSTAT	1	-	0								
4	Note down the value of the MODE parameter on the DPU AND OBS PARAMETERS Display	Check if the following parameters change value:									
		<table border="1"> <thead> <tr> <th>Parameter</th> <th>Start</th> <th>During</th> <th>End</th> </tr> </thead> <tbody> <tr> <td>MODE</td> <td>REDY</td> <td>-</td> <td>ON</td> </tr> </tbody> </table>	Parameter	Start	During	End	MODE	REDY	-	ON	OK
		Parameter	Start	During	End						
MODE	REDY	-	ON								

8.2.2 SFT-SPIRE-CCS-DRCU-OFF**Purpose: Switch off the DRCU**

Step #	Action	Comments	Check
1	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP1.tcl		OK
2	Check that THSK parameter is not refreshing anymore		OK
3	Check that TM2N parameter is not incrementing anymore		OK
4	Manual Switch off of the DRCU by the I-EGSE staff: <ul style="list-style-type: none"> • Switch off all 5 remote DCU switches in ANY order (see Figure 4) • Switch off secondary power to the SPIRE Power Bench (see Figure 5) • Switch off primary power to the SPIRE Power Bench (see Figure 2) 		OK

8.2.3 SFT-SPIRE-CCS-DPU-OFF**Purpose: Switch off the DPU**

Step #	Action	Comments	Check
1	Request the CCS staff to power off the SPIRE DPU using the CCS 28V Power Supply		OK

8.3 Switch Off PACS

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- PACS-ME-TP-026 (Issue 1.0 – 29/08/05)

Remark : This step is not executed since PACS was already OFF

Step #	Action	Comments	Check
1	Execute: PACS_POWER_OFF.tcl	PACS is sending no TM packets anymore	N/A
		28 V power is off	N/A

9 Step by Step Procedure: Set EGSE to OFFLINE

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 13 to 15)

Step #	Action	Comments	Check
1	Execute: "WARNING_LAMP_POWER_OFF.tcl"	Warning lamp is broken.	N/A
2	Execute: "EGSE_OFFLINE_AUTO.tcl" The log of this script can be found in Appendix 10	Check: PLM SCOE HK packets stopped	OK
		Check: CDMU DFE HK packets stopped	OK
3	Shut down PLM EGSE		OK

10 Step by Step Procedure: Configure CCS and EGSE (2)

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution - steps 1 to 9)

This is the start of the second part of the IMT (after DPU exchange). In total this is the fourth day of IMT (22/09/2005)

Step #	Action	Comments	Check
1	Note Testsession	2005_09_22_11_30_ilsens_hpws42_REA LTIME_P_IMT4	OK
2	Power on CDMU DFE platform		OK
3	Power on PLM SCOE platform		OK
4	Power on the CDMU DFE workstation and wait for the BIST to finish.	Check: BIST successful?	OK
5	Power on the PLM SCOE workstation and wait for the BIST to finish.	Check: BIST successful?	OK
6	Execute "EGSE_CONFIG_AUTO.tcl"	Check: PLM SCOE HK packets arriving	OK
		Check: CDMU DFE HK packets arriving	OK
		Check: Check name of bus profile (PST) in CDMU DFE HK or on CDMU DFE workstation Result: PACS_prime_inst.pst	OK
7	Execute "SubscribeParams.tcl"	Check: Wait until status of TCL file has changed to WAITING. This can take up to 10 minutes.	OK
8	Execute "Connect HIEGSE"	Check with IEGSE operators if IEGSE is connected.	OK
9	Execute "WARNING_LAMP_POWER_ON.tcl"	Not done since warning lamp is broken.	N/A
extra	Execute "connect EQMCRYO"		OK

11 Step by Step Procedure: Power On Instruments (2)

Philosophy:

Before power on of any instrument, the PACS prime bus profile is loaded on the CDMU DFE. This means that HIFI and SPIRE are considered to be in standby mode from the beginning.

After the CDMU DFE configuration, the instruments are powered on in the following order:

- PACS (to PRIME mode) – This to give PACS personal maximum time to check out the new DPU
- HIFI (to STANDBY mode)
- SPIRE (to STANDBY mode)

11.1 Power on PACS to PRIME Mode (2)

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- PACS-ME-TP-021 (Issue 1.1 – 06/09/05 – chapter 4.1)

Configuration Check:

Step #	Action	Comments	Check
1	PACS warm electronics is mounted on the SVM		OK
2	28 V power is connected to CCS power supplies		OK
3	PACS OBT interface is connected to CCS OBT simulator		OK
4	DPU 1553 interface is connected to CDMU DFE		OK
5	The CDMU DFE is up and running bus list "nominal"	PACS_prime_inst.pst	OK
6	PACS+EGSE grounding has been verified against AD-7		OK
7	Check that all TOPE-Tcl scripts (sec.10) are accessible via the CCS		OK

Remark: During the power on multiple out of limits were reported. This is a known ASEED NCR 1276. Also a SSC error was reported on the CCS (known ASEED NCR 1247).

Step #	Action	Comments	Check
1	Execute script: PACS_POWER_ON.tcl	PACS is sending regular non-Prime HK packets and essential HK packets	OK
		1355 links DPU-SPUS, DPU-SPUL, DPU-DMC, DMC-SPUS, DMC-SPUL, DMC-BOLC are on and communicating	OK
		Counters for TM(1,2), TM(1,8) and NACKs shall be 0	OK
		" 28 V power is on for all 4 sub-systems	OK

11.2 Power on HIFI to STANDBY Mode

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- SRON-G/HIFI/PR/2005-101 chapter 2.4.1 & 2.4.5

Remark: The actual switching of the LCL's (PLM SCOE switches) is done with the INSTR_POWER_ON.tcl script.

Remark: To speed up the booting of the ICU, it is decided by HIFI that chapter 2.4.5 should be executed instead of 2.4.1 (nominal power on procedure). Chapter 2.4.5 powers on the ICU, uploads new OBSW and boots from this new OBSW.

Step #	Action	Comments	Check
1	Apply power to ICU	Select ICU_housekeeping AND	OK
		Check voltage in the range 26V – 29V Actual value = 27.9 V	OK
		Check ICU current draw is 480 - 560 mA Actual value = 0.52 A	OK
		Check for receipt of (5,2) event packet after power-on	OK
2	Upload new OBSW	The stack file (OBS2_22.hpws42) containing the OBSW is adapted since a new version of the MIB is used on the CCS. The version is 07092005. This is entered in the first line of the stack file.	OK
		Load stack file "OBS2_22.hpws42"	OK
		Arm All -> Send	OK
		Send Command HIFI_load_boot	OK
		No reply (as expected by HIFI)	
		Bus is cycled and no HK is coming in.	OK
		RESET button is pressed -> HK expected, but not coming	NOK
		Send Command HIFI_load_boot	NOK
		Bus is cycled and HK is coming in.	OK
		Continue 2.4.1 after POWER ICU	OK
		Check for receipt of HK packets every 3 sec	OK
		Check OBS version	OK
		Result: 2.16hex = 2.22dec	
Compare HK (secondary supply voltages) with previous results	OK		
	This could not be done since HIFI is not present. No out-of-limits have been crossed, so it is assumed that all values are OK.		
2	Manual Stack command:	Select ICU_housekeeping and HRH_analog AND's	

	HIFI_Housekeeping_on HIF_HK_rate=1_pkt_per_sec Changed to once every 5 seconds.	Check for HK updates every 1 sec (1,1) packet arrived causing a SSC error. This is a result from the OBSW upload.	OK
		Check FCU HK received and no limit errors This could not be done since HIFI is not present. No out-of-limits have been crossed, so it is assumed that all values are OK.	OK
3	Apply power to FCU	Check power supply HK fields are green (FCU SCOE display). This is done by ASED personal according to procedure: SRON-G/HIFI/PR/2005-102	OK
4	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on	Check that the voltages and currents are within the following ranges PS1: "+15V": +15.6V – +16.4V, 107mA – 131mA; 15.853 0.114 "-15V": -16.4V – -15.6V, 78mA – 96mA; -15.824 0.086 "+5V": +5.5V – +6.0V, 119mA – 147mA. 5.946 0.133 PS2: "+18V": +17.0V – +19.0V, 120mA – 148mA; 18.007 0.132 "-18V": -18.0V – -17.0V, 104mA – 128mA; -18.014 0.116 "+8V": +7.0V – +9.0V, 16mA – 26mA. 8.003 0.021	OK
5	Apply power to HRH	<i>Select ICU_housekeeping and HRH_analog AND's</i>	OK
		Check voltage in the range 26V – 29V Actual value = 27.7 V	OK
		Check HRH current draw is 2.2A – 2.8A Actual value = 2.4 A	OK
6	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on HIF_HRSH_s=on	Check HRH HK received and no limit errors	OK
7	Apply power to WEH	<i>Select ICU_housekeeping and WBS_H AND's</i> Temperature out of limit (soft): HM075192 HM076192 This is due a faulty calibration This known error is already traced in ASED-NCR-1261	OK
		Check voltage in the range 26V – 29V Actual value = 27.9 V	OK
		Check WEH current draw is 0.9A – 1.0A Actual value = 0.94 A	OK
8	Manual Stack command: HIFI_notify_PDU_status	Check WBS_H HK received and no limit errors	OK

	HIF_FCU_s=on HIF_HRSH_s=on HIF_WBSH_s=on		
9	Apply power to <u>LCU</u> In procedure HRH is mentioned, this is a type error, it should be LCU. This known error is already traced in ASED-NCR-1260	Select ICU_housekeeping and LCU_status AND's Check voltage in the range 26V – 29V Actual value = V Check WEH current draw is 0.69A – 0.72A Actual value = A	OK
10	Manual Stack command: HIFI_notify_PDU_status HIF_FCU_s=on HIF_HRSH_s=on HIF_WBSH_s=on HIF_LCU_s=on	Check LCU HK received and no limit errors	

11.3 Power on SPIRE to STANDBY Mode

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- SPIRE-RAL-PRC-002494 (Issue 1.1 Appendix 1 – 09/09/05)

Step #	Action	Comments	Check
1	CCS 28V Power Supply to the DPU is available		OK
2	SPIRE MIB is imported in the CCS database.		OK
3	CCS is up and running (SCOS, TOPE and the CDMU Simulator)		OK
4	DPU AND OBS PARAMETERS display is selected on the CCS		OK

11.3.1 SFT-SPIRE-CCS-DPU-ON

Purpose: To switch on the SPIRE DPU and start generating housekeeping

Step #	Action	Comments	Check
1	Power on the SPIRE DPU using the CCS 28V Power Supply	This action is performed from INSTR_POWER_ON.tcl Result: <ul style="list-style-type: none"> • Voltage: 27.8 V • Current: 0.45 A (5,2) packet received	OK
2	Execute TCL script SFT-SPIRE-CCS-DPU-ON.tcl		OK
3	Check that THSK parameter on the DPU AND OBS PARAMETERS display on SCOS is refreshing every second	THSK incrementing every second	OK
4	Check that TM2N parameter on the DPU AND OBS PARAMETERS display on SCOS is incrementing every second	TM2N incrementing every second	OK

Final Configuration: SPIRE DPU is on but the DRCU is still off

11.3.2 SFT-SPIRE-CCS-DRCU-ON

Purpose: To switch on the SPIRE DRCU and start generating housekeeping

Step #	Action	Comments	Check
1	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP1.tcl	HK stopped as expected	OK
2	Check that THSK parameter is not refreshing anymore		OK
3	Check that TM2N parameter is not incrementing anymore		OK
4	Ensure the SPIRE Power Bench is connected to the mains – see Figure 2.		OK
	Ensure all 5 remote DCU switches are in the off position – see Figures 3 & 4 below.		OK
	Switch on the Primary Power on the back of the SPIRE Power Bench (Figure 2).	Prime power led becomes orange Main power led becomes green	OK
	Switch on the Secondary Power on the front of the SPIRE Power Bench by pulling out and lifting up the switch (shown in yellow circle in Figure 5)	Secondary power led becomes red	OK
5	Execute TCL script SFT-SPIRE-CCS-DRCU-ON-STEP2-STBY.tcl		OK
6	Manual Switch on of the DRCU by the CCS staff step 2: <ul style="list-style-type: none"> Switch on all 5 remote DCU switches 		OK

7	Check that THSK parameter is again refreshing every second	THSK incrementing every 4 second	OK
8	Check that TM2N parameter is again incrementing every second	TM2N incrementing every 4 second	OK

Final Configuration:

- SPIRE DPU and DRCU are both on
- HK generation is on

11.3.3 SFT-SPIRE-CCS-FUNC-SCU-03**Purpose: SCU DC thermometry check**

Step #	Action	Comments				Check
1	Execute TCL script SFT-SPIRE-CCS-FUNC-SCU-03.tcl					OK
2	Wait for the parameter BBFULLTYPE to get set to SCU_DC_Therm					OK
3	A few seconds later record the value of parameter SCUTEMPSTAT	Check if the following parameters change value:				
		Parameter	Start	During	End	
		SCUTEMPSTAT Observed	0 0000000	FFFF 0000FF FF	FFFF 0000FF FF	OK
4	Record the RAW values of SCU temperatures	Parameter	Value			OK
		PUMPHTRTEMP	4.20			
		PUMPHSTEMP	3.89			
		EVAPHSTEMP	3.73			
		SHUNTTEMP	1.61			
		SOBTEMP	5.30			
		SL0TEMP	1.67			
		PL0TEMP	1.68			
		OPTTEMP	5.13			
		BAFTEMP	5.10			
		BSMIFTEMP	4.82			
		SCAL2TEMP	4.16			
		SCAL4TEMP	6.19			
		SCALTEMP	5.16			
SMECIFTEMP	5.17					
SMECTEMP	6.66					
BSMTEMP	4.50					

Final Configuration: Unchanged

11.3.4 SFT-SPIRE-CCS-FUNC-SCU-06

Purpose: SCU AC thermometry check

Preconditions: SPIRE CQM is electrically integrated with the Herschel EQM

Initial Configuration:

- SPIRE DPU is on and generating HK
- DRCU is switched ON
- SCU PARAMETERS display is selected on the CCS

Step #	Action	Comments				Check
1	Execute TCL script SFT-SPIRE-CCS-FUNC-SCU-06.tcl					OK
2	Wait for the parameter BBFULLTYPE to get set to SCU_AC_Therm					OK
3	A few seconds later record the value of parameter SUBKSTAT	Check if the following parameters change value:				
		Parameter	Start	During	End	
		SUBKSTAT	0	1	1	OK
		Observed values	0	1	1	
4	Record the RAW value of SUBKTEMP	Check if the following parameters change value:				
		Parameter	Start	During	End	
		SUBKTEMP	?		?	OK
		Observed values	-	-	2.03	
5	Note down the value of the MODE parameter on the DPU AND OBS PARAMETERS display	Parameter	Start	During	End	OK
		MODE	-	-	REDY	
		Observed values	-	-	REDY	

Final Configuration: Unchanged

12 Step by Step Procedure: PACS IMT results

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 11)
- PACS-ME-TP-021

The first test is a retest of the cooler recycling. Since last time, the TCL file hasn't changed, but some extra commands are sent to prepare PACS.

Step #	Action	Comments	Check
1	Send the following commands in a MSK: PC003380 (DPU_SET_HK_LIST) With the following parameter: PP005380 = PHOT PP025380 = BOTH Array PC221410 With the following parameter: PP114410 = 0 PC217410 With the following parameter: PP109410 = 0.00118 A (Eng) = 3011 (Raw)		OK


12.1 Test ID: 410 – Cooler Recycling

Important Remark: Before this test, 5 TCL scripts were updated on the CCS. This was a request from PACS. It concerns the following scripts:

- BOLO_cooler_OBS_shell.tcl
- emissivity_SPEC_spu_setup.tcl
- rsrf_SPEC_spu_setup.tcl
- SPEC_dark_current_spt_eqmimt_obs_shell.tcl
- wavecal_SPEC_spu_setup.tcl

Step #	Action	Comments	Check
1	Execute: BOLO_cooler_OBS_shell.tcl	Heater currents are set as commanded	
		TEMP_EV should be close to 0.3 K after the execution of the script (110 min)	
		TEMP_EV should be below 300mK 120	

	min after starting of the recycling	
--	-------------------------------------	--



12.2 Test ID: 411 – Thermal Behaviour Test in Photometry

Step #	Action	Comments	Check
1	Execute: PHOT_thermal_OBS_shell.tcl	0 Check that photometry HK packets are sent and temperature sensors are on	
		1 Check that groups 1,3,5,6 are switched-on and bolometer temperature sensors are on	
		6 Check if the safe polarisations for M7 configuration are set	
		11 Is the chopper moving between the 2 CSs?	
		16 Are both calibration sources heating up?	
		36 Is the filter wheel changing positions every 15 sec?	

		39 Is the chopper moving between the 2 CSs?	
		44 Are both CSs switched off?	
		46 Are the chopper and grating controller switched-off?	
		48 Are the bolometer array groups 1,3,5,6 switched-off?	
		53 Is the HK list set again to NonPrime?	
extra	<p>Execute Manual Stack Command on PACS request:</p> <p>PC221410 PP114410 = 35 Hex</p> <p>PC003380 (DPU_SET_HK_LIST) With the following parameter: PP005380 = PHOT PP025380 = BOTH Array</p>		NOK
2	<p>Execute: ENTER_SAFE_Mode_Shell.tcl</p> <p>Execute Manual Stack Command on PACS request: PC222410 PP115410 = ON</p>	PACS is in SAFE mode	OK

Remark: This ends day 4 of IMT testing.

Remark: This is the start of day 5 of IMT testing.

extra		PACS DPU stopped sending HK packets (last packet 06:03:40 UTC)	NOK
extra	<p>Manually switch Off</p> <ul style="list-style-type: none"> • SPU (send TC YC041942 (1,14) • DEC/MEC (send TC YC041942 (1,12) • DPU (send TC YC041942 (1,13) 	<ul style="list-style-type: none"> • Current = 0 (YM440942) • Current = 0 (YM408942) • Current = 0 (YM424942) 	OK
extra	Wait 4 min		
extra	<p>Patch and Execute: PACS_POWER_ON_BOLCout.TCL</p>	HK Packets arrive	OK

12.3 Test ID: 407 – Setup Spectroscopy, Data Rate and Cryostat Background Adjustment – only Step1

Step #	Action	Comments	Check
1	Execute:	Spectroscopy HK packets are sent	OK

	SetupSpectroscopyEQMIMT_Shell.tcl	Nominal detector setting (C=0.3pF, r=64, bias=[210mV,70mV], heater=200uA)	OK
		Chopper controller on	OK
		Grating controller on and grating homing completed	OK
		Calibration sources are heating up	OK

12.4 Test ID: 520 – Quick Wavelength Check

Step #	Action	Comments	Check
1	Execute: SPEC_spu_reset.tcl	Science data flow stops	OK
2	Execute: wavecal_SPEC_cre_setup.tcl	CRE housekeeping as commanded	OK
3	Execute: wavecal_SPEC_spu_setup.tcl	Science data flow starts	OK
4	Execute: wavecal_cs1_scan.tcl	Grating moves in steps of 133 from position 535000 to 715000 and back	
extra		Many SSC check failures due to a mass of TM (science) packets arrive. CCS complains about Unknown TM packet received (APID 1157, Type 21,1)	
extra		DPU crashed again, No HK packets sent anymore. Last HK at 10:37:09	NOK
extra	Execute: PACS_Poweer_Off.tcl		OK

Remark: The test is stopped because of problem with the PACS DPU and cooler recycle.

13 Step by Step Procedure: Switch Off Instruments

13.1 Switch Off HIFI

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 12)
- SRON-G/HIFI/PR/2005-101 chapter 2.4.3

Step #	Action	Comments	Check
1	Select LCU_status AND	Verify LCU is in standby mode. Do not continue if this is not so. Result: Check and OK	OK
2	Switch off power to LCU (Send TC YC514942)	Check voltage and current go to zero.	OK
3	Switch off power to WEH (Send TC YC515942)	Check voltage and current go to zero.	OK
4	Switch off power to HRH (Send TC YC517942)	Check voltage and current go to zero.	OK
5	Switch off power to FCU manually	Check voltage and current go to zero.	OK
6	Switch off power to ICU (Send TC YC513942)	Check voltage and current go to zero.	OK

13.2 Switch Off SPIRE

According to Procedure(s):

- **HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)**
- **SPIRE-RAL-PRC-002494 (Issue 1.1 Appendix 2 – 09/09/05)**

Step #	Action	Comments	Check
1	Run SFT_SPIRE_CCS_THO procedure		
1.1	Execute SFT_SPIRE_CCS_FUNC_THO	Many SSC check failures	OK
1.2	A few seconds later record the value of parameter SCUTEMPSTAT	SCUTEMPSTAT = 0	OK
1.3	A few seconds later record the value of parameter SUBKSTAT	SUBKSTAT = 0	OK
1.4	Note down the value of the MODE parameter on the DPU AND OBSPARAMETERS display	MODE = DRCU_ON ??? = ON ???	??
2	Run SFT_SPIRE_CCS_DRCU_OFF procedure		
2.1	Execute TCL script SFT-SPIRECCS-DRCU-ON-STEP1.tcl	Many SSC check failures	OK
2.2	Check that THSK parameter is not refreshing anymore		OK
2.3	Check that TM2N parameter is not incrementing anymore		OK
2.4	Manual Switch off of the DRCU by the CCS staff: <ul style="list-style-type: none"> • Switch off all 5 remote DCU switches in ANY order • Switch off secondary power to the SPIRE Power Bench (see Figure 5) • Switch off primary 		OK OK OK

	power to the SPIRE Power Bench		
3	Run SFT_SPIRE_CCS_ DPU_OFF procedure		
3.1	Request the CCS staff to power off the SPIRE DPU using the CCS 28V Power Supply Send TC YC511942	Check voltage and current go to zero	OK

13.3 Switch Off PACS

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 10)
- PACS-ME-TP-026 (Issue 1.0 – 29/08/05)

PACS is already switched off because of DPU problems at the end of IMT.

Step #	Action	Comments	Check
1	Execute: PACS_POWER_OFF.tcl	PACS is sending no TM packets anymore	N/A
		28 V power is off	N/A

14 Step by Step Procedure: Set EGSE to OFFLINE

According to Procedure(s):

- HP-2-ASED-PR-0035 (Chapter 3: Order of Execution – Step 13 to 15)

Remark: This step is executed manually.

Step #	Action	Comments	Check
1	Execute: "WARNING_LAMP_PO WER_OFF.tcl"	Warning lamp is broken.	N/A
2	Execute: "EGSE_OFFLINE_AUTO. tcl"	Check: PLM SCOE HK packets stopped	N/A
		Check: CDMU DFE HK packets stopped	N/A
3	Shut down PLM EGSE		N/A

15 Summary Sheets

15.1 Procedure Variation Summary

	Test Change	Curr. No.:	
		Date	
		Page	of
Test designation	Test Procedure	Issue	Rev.
Test step changed	Reason for Change		
Prepared by:	Resp. Test Leader	Project Engineer	
PA/QA	Prime	Customer	




Table 15.1-1: Procedure Variation Sheet

15.2 Non Conformance Report (NCR) Summary

NCR - No.	NCR - Title	Date	Open Closed	PA sig.
1482	Wrong MIB definition of command PC162420	19/09/05	Open	
1491	PACS DPU power anomaly	21/09/05	Open	
1493	CRC in HK not compliant with CRC in procedure Memory Management Test	21/09/05	Open	
1494	DEC_MEC got blocked and DEC_MEC - DPU comm link dead	21/09/05	Open	
1495	Cooler Recycle Failed	21/09/05	Open	
1496	IMT TestID 516 should be run in Burst mode (SPEC_dark_current...tcl)		Open	
1497	DPU packets get corrupted (bad packets)	21/09/05	Open	

Table 15.2-1: Non-Conformance Record Sheet

15.3 Sign-off Sheet

	Name	Date	Signature
Test Manager	S. ILSER	17.10.05	
Operator	S. ILSER	04.10.05	
PA Responsible	D. HENDRY	04/10/05	

Appendix 1: PACS Nominal Bus Profile (PACS_prime_inst.PST)

```
;Nominal HERSCHEL/PACS Prime bus profile
;PACS is RT 25: 25TM, 2TC
;SPIRE is RT 21: 2TM, 1TC
;HIFI is RT 16: 2TM, 1TC
```

```
[Config]
```

```
NumberOfSubFrames=64
```

```
[SubFrame1]
```

```
1=RTaccessSA
```

```
[SubFrame2]
```

```
1=RTaccessSA
```

```
[SubFrame3]
```

```
1=RTaccessSA
```

```
[SubFrame4]
```

```
1=TMpoll,21 ;TM poll from: SPIRE
```

```
2=RTaccessSA
```

```
[SubFrame5]
```

```
1=TMpacket,21 ;TM packet from: SPIRE
```

```
2=TMpoll,16 ;TM poll from: HIFI
```

```
3=RTaccessSA
```

```
[SubFrame6]
```

```
1=TMpacket,16 ;TM packet from: HIFI
```

```
2=TMpoll,25 ;TM poll from: PACS
```

```
3=RTaccessSA
```

```
[SubFrame7]
```

```
1=TMpacket,25 ;TM packet from: PACS
```

```
2=TMpoll,21 ;TM poll from: SPIRE
```

```
3=RTaccessSA
```

```
[SubFrame8]
```

```
1=TMpacket,21 ;TM packet from: SPIRE
```

```
2=TMpoll,16 ;TM poll from: HIFI
```

```
3=RTaccessSA
```

```
[SubFrame9]
```

```
1=TMpacket,16 ;TM packet from: HIFI
```

```
2=TMpoll,25 ;TM poll from: PACS
```

```
3=RTaccessSA
```

```
[SubFrame10]
```

```
1=TMpacket,25 ;TM packet from: PACS
```

```
2=RTaccessSA
```

```
[SubFrame11]
```

```
1=TMpoll,25 ;TM poll from: PACS
```

```
2=RTaccessSA
```

```
[SubFrame12]
```

```
1=TMpacket,25 ;TM packet from: PACS
```

```
2=RTaccessSA
```

```
[SubFrame13]
```

```
1=TMpoll,25 ;TM poll from: PACS
```

```
2=RTaccessSA
```

```
[SubFrame14]
```

```
1=TMpacket,25 ;TM packet from: PACS
```

```
2=RTaccessSA
```

```
[SubFrame15]
```

1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame16]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame17]
1=TCpacket ;TC packet to: PACS
2=RTaccessSA

[SubFrame18]
1=TCpacket ;TC packet to: SPIRE
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame19]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame20]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame21]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame22]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame23]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame24]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame25]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame26]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame27]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,21 ;TM poll from: SPIRE
3=RTaccessSA

[SubFrame28]
1=TMpacket,21 ;TM packet from: SPIRE
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame29]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame30]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame31]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,16 ;TM poll from: HIFI
3=RTaccessSA

```
[SubFrame32]
1=TMpacket,16 ;TM packet from: HIFI
2=RTaccessSA

[SubFrame33]
1=TimeSync ;Time distribution broadcast
2=TCpacket ;TC packet to: PACS
3=TMpoll,25 ;TM poll from: PACS
4=RTaccessSA

[SubFrame34]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame35]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame36]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame37]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame38]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame39]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame40]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame41]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame42]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame43]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame44]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame45]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame46]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame47]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame48]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame49]
```

```
1=TCpacket ;TC packet to: HIFI
2=TMPoll,25 ;TM poll from: PACS
3=RTAccessSA

[SubFrame50]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame51]
1=TMPoll,25 ;TM poll from: PACS
2=RTAccessSA

[SubFrame52]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame53]
1=TMPoll,25 ;TM poll from: PACS
2=RTAccessSA

[SubFrame54]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame55]
1=TMPoll,25 ;TM poll from: PACS
2=RTAccessSA

[SubFrame56]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame57]
1=TMPoll,25 ;TM poll from: PACS
2=RTAccessSA

[SubFrame58]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame59]
1=TMPoll,25 ;TM poll from: PACS
2=RTAccessSA

[SubFrame60]
1=TMpacket,25 ;TM packet from: PACS
2=RTAccessSA

[SubFrame61]
1=RTreadSA,25,1 ;RT status from: PACS
2=TMPoll,25 ;TM poll from: PACS

[SubFrame62]
1=RTreadSA,21,1 ;RT status from: SPIRE
2=TMpacket,25 ;TM packet from: PACS

[SubFrame63]
1=RTreadSA,16,1 ;RT status from: HIFI
```

Appendix 2: PACS Burst Mode Bus Profile (PACS_burst_mode.PST)

```
;Burst HERSCHEL bus profile
;PACS is RT 25: 38TM, 2TC
;SPIRE is RT 21: 2TM, 1TC
;HIFI is RT 16: 2TM, 1TC

[Config]
NumberOfSubFrames=64

[SubFrame1]
1=RTaccessSA

[SubFrame2]
1=RTaccessSA

[SubFrame3]
1=RTaccessSA

[SubFrame4]
1=TMpoll,21 ;TM poll from: SPIRE
2=RTaccessSA

[SubFrame5]
1=TMpacket,21 ;TM packet from: SPIRE
2=TMpoll,16 ;TM poll from: HIFI
3=RTaccessSA

[SubFrame6]
1=TMpacket,16 ;TM packet from: HIFI
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame7]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame8]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame9]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame10]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame11]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame12]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame13]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame14]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
```

3=RTaccessSA

[SubFrame15]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame16]

1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame17]

1=TCpacket ;TC packet PACS
2=RTaccessSA

[SubFrame18]

1=TCpacket ;TC packet SPIRE
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame19]

1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame20]

1=TMPoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame21]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame22]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame23]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame24]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame25]

1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame26]

1=TMPoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame27]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,21 ;TM poll from: SPIRE
3=RTaccessSA

[SubFrame28]

1=TMpacket,21 ;TM packet from: SPIRE
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame29]

1=TMpacket,25 ;TM packet from: PACS
2=TMPoll,25 ;TM poll from: PACS
3=RTaccessSA


```
[SubFrame30]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame31]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,16 ;TM poll from: HIFI
3=RTaccessSA

[SubFrame32]
1=TMpacket,16 ;TM packet from: HIFI
2=RTaccessSA

[SubFrame33]
1=TimeSync ;Time distribution broadcast
2=TCpacket ;TC packet PACS
3=RTaccessSA

[SubFrame34]
1=RTaccessSA

[SubFrame35]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame36]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame37]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame38]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame39]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame40]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame41]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame42]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame43]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame44]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame45]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA
```

[SubFrame46]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame47]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame48]
1=TMpacket,25 ;TM packet from: PACS
2=RTaccessSA

[SubFrame49]
1=TCpacket ;TC packet HIFI
2=RTaccessSA

[SubFrame50]
1=RTaccessSA

[SubFrame51]
1=TMpoll,25 ;TM poll from: PACS
2=RTaccessSA

[SubFrame52]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame53]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame54]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame55]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame56]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame57]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame58]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame59]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,25 ;TM poll from: PACS
3=RTaccessSA

[SubFrame60]
1=TMpacket,25 ;TM packet from: PACS
2=TMpoll,21 ;TM poll from: SPIRE
3=RTaccessSA

```
[SubFrame61]
1=RTreadSA,25,1 ;RT status from: PACS
2=TMpacket,21 ;TM packet from: SPIRE
3=TMPoll,16 ;TM poll from: HIFI
```

```
[SubFrame62]
1=RTreadSA,16,1 ;RT status from: HIFI
2=TMpacket,16 ;TM packet from: HIFI
3=TMPoll,25 ;TM poll from: PACS
```

```
[SubFrame63]
1=RTreadSA,21,1 ;RT status from: SPIRE
2=TMpacket,25 ;TM packet from: PACS
```


2005.262.12.14.18.952085 Status_PLM_LCL12_I is currently 0.000506599550135 (extracted from TLM YM408942)
2005.262.12.14.18.956936 Status_PLM_LCL13_V is currently 0.0185891501606 (extracted from TLM YM420942)
2005.262.12.14.18.960752 Status_PLM_LCL13_I is currently 0.000506599550135 (extracted from TLM YM424942)
2005.262.12.14.18.965702 Status_PLM_LCL14_V is currently 0.0952693969011 (extracted from TLM YM436942)
2005.262.12.14.18.969788 Status_PLM_LCL14_I is currently 0.000253299775068 (extracted from TLM YM440942)


```

2005.262.12.19.18.753452 User Info>: Check Successful! PSU 1 has been enabled.
2005.262.12.19.18.754091 *****
2005.262.12.19.22.056586
2005.262.12.19.22.136690 Sending Telecommand YC036942
2005.262.12.19.22.137054 Synchronizing on SEV...
2005.262.12.19.22.138028 Synchronised on SEV for TC(s): YC036942
2005.262.12.19.22.138674
2005.262.12.19.22.139323 >>> Checking
2005.262.12.19.28.144751 PSU 2 Master status is currently 1 (from YM177942)
2005.262.12.19.28.145231 PSU 2 Slave status is currently 1 (from YM193942)
2005.262.12.19.28.145836
2005.262.12.19.28.176821 ***** USER INFORMATION *****
2005.262.12.19.28.177552 User Info>: Check Successful! PSU 2 has been enabled.
2005.262.12.19.28.178205 *****
2005.262.12.19.29.436922
2005.262.12.19.29.437327 >>> Start Enabling LCL's
2005.262.12.19.29.437943
2005.262.12.19.29.466667 Do you want to enable LCL 3? : Choose Yes or No
2005.262.12.19.32.037536 User has chosen YES
2005.262.12.19.34.042281
2005.262.12.19.34.140231 Sending Telecommand YC040942 to Enable Limiter
2005.262.12.19.34.140604 Synchronizing on SEV...
2005.262.12.19.34.141680 Synchronised on SEV for TC(s): YC040942
2005.262.12.19.34.142310
2005.262.12.19.34.207361 Sending Telecommand YC043942 to Set Limiter
2005.262.12.19.34.207825 Synchronizing on SEV...
2005.262.12.19.34.251141 Synchronised on SEV for TC(s): YC043942
2005.262.12.19.34.251526
2005.262.12.19.34.252097 >>> Checking
2005.262.12.19.40.257859 LCL 3 has currently a voltage of 27.9371700287.(from YM260942)
2005.262.12.19.40.258263 LCL 3 has currently a current of 0.525850355625.(from YM264942)
2005.262.12.19.40.258866
2005.262.12.19.40.285970 ***** USER INFORMATION *****
2005.262.12.19.40.286671 User Info>: Check Successful! LCL 3 has been enabled.
2005.262.12.19.40.287275 *****
2005.262.14.51.22.308280
2005.262.14.51.22.385529 Do you want to enable LCL 7? : Choose Yes or No
2005.262.14.51.23.754512 User has chosen YES
2005.262.14.51.25.756222
2005.262.14.51.25.871895 Sending Telecommand YC040942 to Enable Limiter
2005.262.14.51.25.872271 Synchronizing on SEV...
2005.262.14.51.25.873360 Synchronised on SEV for TC(s): YC040942
2005.262.14.51.25.874019
2005.262.14.51.25.941478 Sending Telecommand YC043942 to Set Limiter
2005.262.14.51.25.941850 Synchronizing on SEV...
2005.262.14.51.25.972807 Synchronised on SEV for TC(s): YC043942
2005.262.14.51.25.973215
2005.262.14.51.25.973798 >>> Checking
2005.262.14.51.31.980521 LCL 7 has currently a voltage of 27.7350139618.(from YM324942)
2005.262.14.51.31.980935 LCL 7 has currently a current of 2.43015789986.(from YM328942)
2005.262.14.51.31.981540
2005.262.14.51.32.011969 ***** USER INFORMATION *****
2005.262.14.51.32.012743 User Info>: Check Successful! LCL 7 has been enabled.
2005.262.14.51.32.013351 *****
2005.262.14.52.23.209069
2005.262.14.52.23.258344 Do you want to enable LCL 5? : Choose Yes or No
2005.262.14.52.24.606455 User has chosen YES
2005.262.14.52.26.609800
2005.262.14.52.26.715549 Sending Telecommand YC040942 to Enable Limiter
2005.262.14.52.26.715921 Synchronizing on SEV...
2005.262.14.52.26.721063 Synchronised on SEV for TC(s): YC040942
2005.262.14.52.26.721473
2005.262.14.52.26.782424 Sending Telecommand YC043942 to Set Limiter
2005.262.14.52.26.782803 Synchronizing on SEV...
2005.262.14.52.26.845470 Synchronised on SEV for TC(s): YC043942
2005.262.14.52.26.846098
2005.262.14.52.26.846706 >>> Checking
2005.262.14.52.32.852758 LCL 5 has currently a voltage of 27.9394931793.(from YM292942)
2005.262.14.52.32.853228 LCL 5 has currently a current of 0.948354363441.(from YM296942)
2005.262.14.52.32.853847
2005.262.14.52.32.879351 ***** USER INFORMATION *****

```


Appendix 5: Log of PACS_POWER_ON.tcl

```

2005.262.15.00.48.255557
*****
2005.262.15.00.48.256466 Start of PACS POWER ON sequence.
*****
2005.262.15.00.48.256803
2005.262.15.00.48.257034 To run this script, the CDMU DFE and PLM SCOE should be
2005.262.15.00.48.257269 powered and configured.
2005.262.15.00.48.257495 To initiate, this script will connect and attach to the CDMUDFE
2005.262.15.00.48.257731 and PLM SCOE.
2005.262.15.00.48.257955
2005.262.15.00.48.258181 >>> Connecting to CDMU DFE.
2005.262.15.00.51.263996 >>> Attaching to CDMU DFE.
2005.262.15.00.54.272785
2005.262.15.00.54.273149 >>> Connecting to PLM SCOE.
2005.262.15.00.57.277568 >>> Attaching to PLM SCOE.
2005.262.15.01.00.280612
2005.262.15.01.00.280988 >>> Reading out CDMUDFE Settings
2005.262.15.01.00.281406
2005.262.15.01.00.710024 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.262.15.01.00.713797 Status_CDMU_Tmpolling is 1 (extracted from TLM YM780944)
2005.262.15.01.00.919526 Status_CDMU_SAReadActive is 1 (extracted from TLM YM781944)
2005.262.15.01.00.922264 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.262.15.01.00.924911 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.262.15.01.01.167698 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)
2005.262.15.01.01.170548 Status_CDMU_PSTfileName is PACS_prime_inst... (extracted from TLM
YM809944)
2005.262.15.01.01.414217 Status_CDMU_PSTrunning is 1 (extracted from TLM YM829944)
2005.262.15.01.01.414832
2005.262.15.01.01.415318 >>> Reading out PLM SCOE Settings
2005.262.15.01.01.415817
2005.262.15.01.01.594898 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.262.15.01.01.680038 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.262.15.01.01.923809 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.262.15.01.01.926602 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.262.15.01.01.929412 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.262.15.01.02.175169 Status_PLM_LCL1_V is currently 0.00697093131021 (extracted from TLM
YM228942)
2005.262.15.01.02.179303 Status_PLM_LCL1_I is currently 0.00101930263918 (extracted from TLM
YM232942)
2005.262.15.01.02.183950 Status_PLM_LCL2_V is currently 0.0650620236993 (extracted from TLM
YM244942)
2005.262.15.01.02.477901 Status_PLM_LCL2_I is currently 0.00607919460163 (extracted from TLM
YM248942)
2005.262.15.01.02.483277 Status_PLM_LCL3_V is currently 27.9418182373 (extracted from TLM
YM260942)
2005.262.15.01.02.486985 Status_PLM_LCL3_I is currently 0.484815746546 (extracted from TLM
YM264942)
2005.262.15.01.02.781677 Status_PLM_LCL4_V is currently 27.9394931793 (extracted from TLM
YM276942)
2005.262.15.01.02.785869 Status_PLM_LCL4_I is currently 0.723424196243 (extracted from TLM
YM280942)
2005.262.15.01.02.790642 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM
YM292942)
2005.262.15.01.03.035063 Status_PLM_LCL5_I is currently 0.95088738203 (extracted from TLM
YM296942)
2005.262.15.01.03.040206 Status_PLM_LCL6_V is currently 0.0766802430153 (extracted from TLM
YM308942)
2005.262.15.01.03.043777 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM
YM312942)
2005.262.15.01.03.287862 Status_PLM_LCL7_V is currently 27.7257175446 (extracted from TLM
YM324942)
2005.262.15.01.03.376065 Status_PLM_LCL7_I is currently 2.5324909687 (extracted from TLM
YM328942)
2005.262.15.01.03.620976 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM
YM340942)
2005.262.15.01.03.711949 Status_PLM_LCL8_I is currently 0.0045593958348 (extracted from TLM
YM344942)

```

```
2005.262.15.01.03.716487 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM
YM356942)
2005.262.15.01.03.960227 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM
YM360942)
2005.262.15.01.03.964874 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM
YM372942)
2005.262.15.01.03.968304 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM
YM376942)
2005.262.15.01.04.213367 Status_PLM_LCL11_V is currently 0.00697093131021 (extracted from TLM
YM388942)
2005.262.15.01.04.217172 Status_PLM_LCL11_I is currently 0.00354619673453 (extracted from TLM
YM392942)
2005.262.15.01.04.462023 Status_PLM_LCL12_V is currently 0.00697093131021 (extracted from TLM
YM404942)
2005.262.15.01.04.514680 Status_PLM_LCL12_I is currently 0.0116517897695 (extracted from TLM
YM408942)
2005.262.15.01.04.572918 Status_PLM_LCL13_V is currently 0.0185891501606 (extracted from TLM
YM420942)
2005.262.15.01.04.817428 Status_PLM_LCL13_I is currently 0.00151979865041 (extracted from TLM
YM424942)
2005.262.15.01.04.822507 Status_PLM_LCL14_V is currently 0.090622112155 (extracted from TLM
YM436942)
2005.262.15.01.04.827056 Status_PLM_LCL14_I is currently 0.00430609611794 (extracted from TLM
YM440942)
2005.262.15.01.04.827891
2005.262.15.01.04.828532 >>> Switch ON PSU(s)
2005.262.15.01.04.829156
2005.262.15.01.04.963249 >>> Sending Telecommand YC036942
2005.262.15.01.04.963616
2005.262.15.01.04.964244 >>> Checking
2005.262.15.01.11.095200 PSU 2 Master status is currently 1 (from YM177942)
2005.262.15.01.11.095607 PSU 2 Slave status is currently 1 (from YM193942)
2005.262.15.01.11.096324
2005.262.15.01.11.096970 >>> Switch ON DPU
2005.262.15.01.11.097632
2005.262.15.01.11.135820 >>> Sending Telecommand YC040942 to Enable Limiter 13 -> PACS DPU
2005.262.15.01.11.136217
2005.262.15.01.11.275545 >>> Sending Telecommand YC043942 to Set Limiter 13 -> PACS DPU
2005.262.15.01.11.275923
2005.262.15.01.11.276531 >>> Checking
2005.262.15.01.17.431963 LCL 13 has currently a voltage of 27.9487876892.(from YM420942)
2005.262.15.01.17.432657 LCL 13 has currently a current of 0.471644192934.(from YM424942)
2005.262.15.01.17.433496
2005.262.15.01.34.441434 Force Boot DPU
2005.262.15.01.35.585478 ***** USER INFORMATION *****
2005.262.15.01.35.585923 User Info>: Please check if the force boot has been executed
correctly and press OK.
2005.262.15.01.35.586608 *****
2005.262.15.01.55.837898
2005.262.15.01.55.838250
2005.262.15.01.55.838847 >>> Switch ON DEC/MEC
2005.262.15.01.55.839434
2005.262.15.01.55.981851 >>> Sending Telecommand YC040942 to Enable Limiter 12 -> PACS DEC/MEC
2005.262.15.01.55.982224
2005.262.15.01.56.049014 >>> Sending Telecommand YC043942 to Set Limiter 12 -> PACS DEC/MEC
2005.262.15.01.56.049507
2005.262.15.01.56.050106 >>> Checking
2005.262.15.02.02.129507 LCL 12 has currently a voltage of 27.909286499.(from YM404942)
2005.262.15.02.02.129919 LCL 12 has currently a current of 0.55320674181.(from YM408942)
2005.262.15.02.02.130534
2005.262.15.02.22.139044 DPU reset of 1355
2005.262.15.02.24.267313 Establish DPU --> DMC connection (DPU-START-OBCEP, n=19)
2005.262.15.02.28.303133 Copy DMC SW from EEPROM to RAM
2005.262.15.02.30.339564 DMC_LLSW_LOAD_EEPROM
2005.262.15.02.32.409179 Start DMC HLSW
2005.262.15.02.43.019064 DPU starts link with DMC with DPU as slave
2005.262.15.02.46.070903
2005.262.15.02.46.071457
2005.262.15.02.46.072242 >>> Switch ON BOLC
2005.262.15.02.46.073078
2005.262.15.02.46.137728 >>> Sending Telecommand YC040942 to Enable Limiter 11 -> PACS BOLC
```

```
2005.262.15.02.46.138105
2005.262.15.02.46.247009 >>> Sending Telecommand YC043942 to Set Limiter 11 -> PACS BOLC
2005.262.15.02.46.247608
2005.262.15.02.46.248425 >>> Checking
2005.262.15.02.52.572952 LCL 11 has currently a voltage of 27.9627304077.(from YM388942)
2005.262.15.02.52.573387 LCL 11 has currently a current of 0.044580757618.(from YM392942)
2005.262.15.02.52.573998
2005.262.15.03.07.581563 DMC_RESET_SMCS_CHIP_2
2005.262.15.03.11.701699 Execute BOLC initialisation including frequency setting
2005.262.15.03.17.931660 set image frequency to 20 Hz
2005.262.15.03.18.517404
2005.262.15.03.18.517769
2005.262.15.03.18.518342 >>> Switch ON SPU
2005.262.15.03.18.518907
2005.262.15.03.18.535640 >>> Sending Telecommand YC040942 to Enable Limiter 14 -> PACS SPU
2005.262.15.03.18.536103
2005.262.15.03.18.639316 >>> Sending Telecommand YC043942 to Set Limiter 14 -> PACS SPU
2005.262.15.03.18.639696
2005.262.15.03.18.640291 >>> Checking
2005.262.15.03.24.763135 LCL 14 has currently a voltage of 28.0463829041.(from YM436942)
2005.262.15.03.24.763727 LCL 14 has currently a current of 0.448340594769.(from YM440942)
2005.262.15.03.24.764505
2005.262.15.03.44.772619 DPU reset of 1355
2005.262.15.03.48.861162 DPU starts link with DMC with DPU as slave
2005.262.15.03.58.967384 DPU starts link with (blue) SPUS with DPU as master
2005.262.15.04.03.040231 DPU starts link with (red) SPUL with DPU as master
2005.262.15.04.07.179496 LOAD SPU RED HLSW FROM EEPROM TO RAM
2005.262.15.04.13.460660 LOAD SPU BLUE HLSW FROM EEPROM TO RAM
2005.262.15.04.21.633824 Start SPUS HLSW
2005.262.15.04.24.708998 DPU starts link with (blue) SPUS with DPU as slave
2005.262.15.04.28.776094 Start SPUL HLSW
2005.262.15.04.31.816188 DPU starts link with (red) SPUL with DPU as slave
2005.262.15.04.36.959012 Establish connection SPUL-DMC, DMC as master
2005.262.15.04.37.993893 Establish connection SPUS-DMC, DMC as master
2005.262.15.04.40.026365 Establish connection DMC-SPURS DMC Master
2005.262.15.04.41.096345 Establish connection DMC-SPURL DMC Master
2005.262.15.04.43.736125 FPU T-sensors are activated
2005.262.15.04.43.736504
2005.262.15.04.43.737093
2005.262.15.04.43.737696 >>> Reading out CDMUDFE Settings
2005.262.15.04.43.738307
2005.262.15.04.43.848460 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.262.15.04.43.849846 Status_CDMU_Tmpolling is 1 (extracted from TLM YM780944)
2005.262.15.04.43.851277 Status_CDMU_SAReadActive is 1 (extracted from TLM YM781944)
2005.262.15.04.43.852849 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.262.15.04.43.854095 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.262.15.04.43.855935 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)
2005.262.15.04.43.857281 Status_CDMU_PSTfileName is PACS_prime_inst... (extracted from TLM
YM809944)
2005.262.15.04.43.859297 Status_CDMU_PSTRunning is 1 (extracted from TLM YM829944)
2005.262.15.04.43.860000
2005.262.15.04.43.860594 >>> Reading out PLM SCOE Settings
2005.262.15.04.43.861246
2005.262.15.04.44.104378 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.262.15.04.44.105738 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.262.15.04.44.107283 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.262.15.04.44.109637 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.262.15.04.44.110817 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.262.15.04.44.112000 Status_PLM_LCL1_V is currently 0.00697093131021 (extracted from TLM
YM228942)
2005.262.15.04.44.113126 Status_PLM_LCL1_I is currently 0.000917372351978 (extracted from TLM
YM232942)
2005.262.15.04.44.114557 Status_PLM_LCL2_V is currently 0.0627383813262 (extracted from TLM
YM244942)
2005.262.15.04.44.115673 Status_PLM_LCL2_I is currently 0.00607919460163 (extracted from TLM
YM248942)
2005.262.15.04.44.116833 Status_PLM_LCL3_V is currently 27.9394931793 (extracted from TLM
YM260942)
2005.262.15.04.44.359922 Status_PLM_LCL3_I is currently 0.484815746546 (extracted from TLM
YM264942)
```

2005.262.15.04.44.414408 Status_PLM_LCL4_V is currently 27.9418182373 (extracted from TLM YM276942)
2005.262.15.04.44.415635 Status_PLM_LCL4_I is currently 0.722917497158 (extracted from TLM YM280942)
2005.262.15.04.44.417268 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM YM292942)
2005.262.15.04.44.418459 Status_PLM_LCL5_I is currently 0.95012742281 (extracted from TLM YM296942)
2005.262.15.04.44.419651 Status_PLM_LCL6_V is currently 0.079003892839 (extracted from TLM YM308942)
2005.262.15.04.44.421158 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM YM312942)
2005.262.15.04.44.422355 Status_PLM_LCL7_V is currently 27.7233943939 (extracted from TLM YM324942)
2005.262.15.04.44.423860 Status_PLM_LCL7_I is currently 2.53907704353 (extracted from TLM YM328942)
2005.262.15.04.44.425127 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM YM340942)
2005.262.15.04.44.668391 Status_PLM_LCL8_I is currently 0.0045593958348 (extracted from TLM YM344942)
2005.262.15.04.44.729355 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM YM356942)
2005.262.15.04.44.730599 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM YM360942)
2005.262.15.04.44.732228 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM YM372942)
2005.262.15.04.44.733475 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM YM376942)
2005.262.15.04.44.734657 Status_PLM_LCL11_V is currently 27.967376709 (extracted from TLM YM388942)
2005.262.15.04.44.736208 Status_PLM_LCL11_I is currently 0.0448340587318 (extracted from TLM YM392942)
2005.262.15.04.44.737370 Status_PLM_LCL12_V is currently 27.8953456879 (extracted from TLM YM404942)
2005.262.15.04.44.738886 Status_PLM_LCL12_I is currently 0.753820121288 (extracted from TLM YM408942)
2005.262.15.04.44.740079 Status_PLM_LCL13_V is currently 27.9511127472 (extracted from TLM YM420942)
2005.262.15.04.44.982766 Status_PLM_LCL13_I is currently 0.437195420265 (extracted from TLM YM424942)
2005.262.15.04.44.984057 Status_PLM_LCL14_V is currently 28.0231437683 (extracted from TLM YM436942)
2005.262.15.04.44.985243 Status_PLM_LCL14_I is currently 0.750527203083 (extracted from TLM YM440942)
2005.262.15.04.44.986319
2005.262.15.04.44.986968

2005.262.15.04.44.987979 PACS Power On Sequence has ended

2005.262.15.04.44.988971

Appendix 7: Log of PACS_POWER_ON_BOLCout.tcl (used to recover from ASED NCR 1494)

```

2005.263.14.47.56.036900
*****
2005.263.14.47.56.037809 Start of PACS POWER ON sequence.
*****
2005.263.14.47.56.038125
2005.263.14.47.56.038355 To run this script, the CDMU DFE and PLM SCOE should be
2005.263.14.47.56.038591 powered and configured.
2005.263.14.47.56.038817 To initiate, this script will connect and attach to the CDMUDFE
2005.263.14.47.56.039052 and PLM SCOE.
2005.263.14.47.56.039278
2005.263.14.47.56.039506 >>> Connecting to CDMU DFE.
2005.263.14.47.59.044494 >>> Attaching to CDMU DFE.
2005.263.14.48.02.051297
2005.263.14.48.02.051665 >>> Connecting to PLM SCOE.
2005.263.14.48.05.054241 >>> Attaching to PLM SCOE.
2005.263.14.48.08.057193
2005.263.14.48.08.057563 >>> Reading out CDMUDFE Settings
2005.263.14.48.08.057998
2005.263.14.48.08.162184 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.263.14.48.08.164381 Status_CDMU_Tmpolling is 1 (extracted from TLM YM780944)
2005.263.14.48.08.166484 Status_CDMU_SAreadActive is 1 (extracted from TLM YM781944)
2005.263.14.48.08.168529 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.263.14.48.08.170571 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.263.14.48.08.172791 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)
2005.263.14.48.08.174720 Status_CDMU_PSTfileName is PACS_prime_inst... (extracted from TLM
YM809944)
2005.263.14.48.08.176866 Status_CDMU_PSTrunning is 1 (extracted from TLM YM829944)
2005.263.14.48.08.177403
2005.263.14.48.08.177887 >>> Reading out PLM SCOE Settings
2005.263.14.48.08.178388
2005.263.14.48.08.401807 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.263.14.48.08.459563 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.263.14.48.08.461816 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.263.14.48.08.464103 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.263.14.48.08.466396 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.263.14.48.08.471228 Status_PLM_LCL1_V is currently 27.8604888916 (extracted from TLM
YM228942)
2005.263.14.48.08.474627 Status_PLM_LCL1_I is currently 0.434936404228 (extracted from TLM
YM232942)
2005.263.14.48.08.479008 Status_PLM_LCL2_V is currently 0.0650620236993 (extracted from TLM
YM244942)
2005.263.14.48.08.482303 Status_PLM_LCL2_I is currently 0.00607919460163 (extracted from TLM
YM248942)
2005.263.14.48.08.486765 Status_PLM_LCL3_V is currently 27.9418182373 (extracted from TLM
YM260942)
2005.263.14.48.08.490080 Status_PLM_LCL3_I is currently 0.481776177883 (extracted from TLM
YM264942)
2005.263.14.48.08.494552 Status_PLM_LCL4_V is currently 27.9418182373 (extracted from TLM
YM276942)
2005.263.14.48.08.497938 Status_PLM_LCL4_I is currently 0.72139775753 (extracted from TLM
YM280942)
2005.263.14.48.08.502484 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM
YM292942)
2005.263.14.48.08.505845 Status_PLM_LCL5_I is currently 0.952660441399 (extracted from TLM
YM296942)
2005.263.14.48.08.510839 Status_PLM_LCL6_V is currently 0.0766802430153 (extracted from TLM
YM308942)
2005.263.14.48.08.514735 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM
YM312942)
2005.263.14.48.08.519806 Status_PLM_LCL7_V is currently 27.7164230347 (extracted from TLM
YM324942)
2005.263.14.48.08.524292 Status_PLM_LCL7_I is currently 2.63026475906 (extracted from TLM
YM328942)

```

```
2005.263.14.48.08.529707 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM
YM340942)
2005.263.14.48.08.534154 Status_PLM_LCL8_I is currently 0.0045593958348 (extracted from TLM
YM344942)
2005.263.14.48.08.539595 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM
YM356942)
2005.263.14.48.08.543805 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM
YM360942)
2005.263.14.48.08.548614 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM
YM372942)
2005.263.14.48.08.552233 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM
YM376942)
2005.263.14.48.08.557065 Status_PLM_LCL11_V is currently 27.967376709 (extracted from TLM
YM388942)
2005.263.14.48.08.560712 Status_PLM_LCL11_I is currently 0.0448340587318 (extracted from TLM
YM392942)
2005.263.14.48.08.565501 Status_PLM_LCL12_V is currently 0.00697093131021 (extracted from TLM
YM404942)
2005.263.14.48.08.569095 Status_PLM_LCL12_I is currently 0.0116517897695 (extracted from TLM
YM408942)
2005.263.14.48.08.573805 Status_PLM_LCL13_V is currently 0.0185891501606 (extracted from TLM
YM420942)
2005.263.14.48.08.577395 Status_PLM_LCL13_I is currently 0.00151979865041 (extracted from TLM
YM424942)
2005.263.14.48.08.582184 Status_PLM_LCL14_V is currently 0.0952693969011 (extracted from TLM
YM436942)
2005.263.14.48.08.585826 Status_PLM_LCL14_I is currently 0.00430609611794 (extracted from TLM
YM440942)
2005.263.14.48.08.586572
2005.263.14.48.08.587190 >>> Switch ON PSU(s)
2005.263.14.48.08.587809
2005.263.14.48.08.707907 >>> Sending Telecommand YC036942
2005.263.14.48.08.708276
2005.263.14.48.08.708970 >>> Checking
2005.263.14.48.14.712429 PSU 2 Master status is currently 1 (from YM177942)
2005.263.14.48.14.712822 PSU 2 Slave status is currently 1 (from YM193942)
2005.263.14.48.14.713477
2005.263.14.48.14.714102 >>> Switch ON DPU
2005.263.14.48.14.714710
2005.263.14.48.14.813238 >>> Sending Telecommand YC040942 to Enable Limiter 13 -> PACS DPU
2005.263.14.48.14.813620
2005.263.14.48.14.884491 >>> Sending Telecommand YC043942 to Set Limiter 13 -> PACS DPU
2005.263.14.48.14.884928
2005.263.14.48.14.885552 >>> Checking
2005.263.14.48.20.890055 LCL 13 has currently a voltage of 27.9557590485.(from YM420942)
2005.263.14.48.20.890452 LCL 13 has currently a current of 0.464045166969.(from YM424942)
2005.263.14.48.20.891084
2005.263.14.48.37.899112 Force Boot DPU
2005.263.14.48.39.021982 ***** USER INFORMATION *****
2005.263.14.48.39.022461 User Info>: Please check if the force boot has been executed
correctly and press OK.
2005.263.14.48.39.023147 *****
2005.263.14.48.52.651628
2005.263.14.48.52.651975
2005.263.14.48.52.652582 >>> Switch ON DEC/MEC
2005.263.14.48.52.653197
2005.263.14.48.52.797152 >>> Sending Telecommand YC040942 to Enable Limiter 12 -> PACS DEC/MEC
2005.263.14.48.52.797522
2005.263.14.48.52.864606 >>> Sending Telecommand YC043942 to Set Limiter 12 -> PACS DEC/MEC
2005.263.14.48.52.864980
2005.263.14.48.52.865555 >>> Checking
2005.263.14.48.58.868039 LCL 12 has currently a voltage of 27.909286499.(from YM404942)
2005.263.14.48.58.868440 LCL 12 has currently a current of 0.56536513567.(from YM408942)
2005.263.14.48.58.869061
2005.263.14.49.18.878093 DPU reset of 1355
2005.263.14.49.20.979009 Establish DPU --> DMC connection (DPU-START-OBCEP, n=19)
2005.263.14.49.25.012831 Copy DMC SW from EEPROM to RAM
2005.263.14.49.27.090297 DMC_LLSW_LOAD_EEPROM
2005.263.14.49.29.122882 Start DMC HLSW
2005.263.14.49.39.701479 DPU starts link with DMC with DPU as slave
2005.263.14.49.42.786459
```

```
2005.263.14.49.42.786826
2005.263.14.49.42.787404 >>> Switch ON BOLC
2005.263.14.49.42.787969
2005.263.14.49.42.890355 >>> Sending Telecommand YC040942 to Enable Limiter 11 -> PACS BOLC
2005.263.14.49.42.890729
2005.263.14.49.42.959697 >>> Sending Telecommand YC043942 to Set Limiter 11 -> PACS BOLC
2005.263.14.49.42.960111
2005.263.14.49.42.960681 >>> Checking
2005.263.14.49.48.963299 LCL 11 has currently a voltage of 27.967376709.(from YM388942)
2005.263.14.49.48.963699 LCL 11 has currently a current of 0.0448340587318.(from YM392942)
2005.263.14.49.48.964295
2005.263.14.50.03.973046 DMC_RESET_SMCS_CHIP_2
2005.263.14.50.08.110309 Execute BOLC initialisation including frequency setting
2005.263.14.50.14.120070 set image frequency to 20 Hz
2005.263.14.50.14.623821
2005.263.14.50.14.624184
2005.263.14.50.14.624748 >>> Switch ON SPU
2005.263.14.50.14.625303
2005.263.14.50.14.764862 >>> Sending Telecommand YC040942 to Enable Limiter 14 -> PACS SPU
2005.263.14.50.14.765321
2005.263.14.50.14.832024 >>> Sending Telecommand YC043942 to Set Limiter 14 -> PACS SPU
2005.263.14.50.14.832580
2005.263.14.50.14.833186 >>> Checking
2005.263.14.50.20.835785 LCL 14 has currently a voltage of 28.0463829041.(from YM436942)
2005.263.14.50.20.836192 LCL 14 has currently a current of 0.456699460745.(from YM440942)
2005.263.14.50.20.836804
2005.263.14.50.40.845846 DPU reset of 1355
2005.263.14.50.44.948125 DPU starts link with DMC with DPU as slave
2005.263.14.50.55.089456 DPU starts link with (blue) SPUS with DPU as master
2005.263.14.50.59.232674 DPU starts link with (red) SPUL with DPU as master
2005.263.14.51.03.334739 LOAD SPU RED HLSW FROM EEPROM TO RAM
2005.263.14.51.09.510580 LOAD SPU BLUE HLSW FROM EEPROM TO RAM
2005.263.14.51.17.757800 Start SPUS HLSW
2005.263.14.51.20.862282 DPU starts link with (blue) SPUS with DPU as slave
2005.263.14.51.24.964484 Start SPUL HLSW
2005.263.14.51.28.039610 DPU starts link with (red) SPUL with DPU as slave
2005.263.14.51.33.106389 Establish connection SPUL-DMC, DMC as master
2005.263.14.51.34.211509 Establish connection SPUS-DMC, DMC as master
2005.263.14.51.36.314328 Establish connection DMC-SPURS DMC Master
2005.263.14.51.37.384317 Establish connection DMC-SPURL DMC Master
2005.263.14.51.39.988945 FPU T-sensors are activated
2005.263.14.51.39.989331
2005.263.14.51.39.989911
2005.263.14.51.39.990466 >>> Reading out CDMUDFE Settings
2005.263.14.51.39.991031
2005.263.14.51.39.992225 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.263.14.51.39.993259 Status_CDMU_TMPolling is 1 (extracted from TLM YM780944)
2005.263.14.51.39.994282 Status_CDMU_SAReadActive is 1 (extracted from TLM YM781944)
2005.263.14.51.39.995598 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.263.14.51.39.996673 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.263.14.51.39.997710 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)
2005.263.14.51.39.998784 Status_CDMU_PSTfileName is PACS_prime_inst.... (extracted from TLM
YM809944)
2005.263.14.51.39.999824 Status_CDMU_PSTRunning is 1 (extracted from TLM YM829944)
2005.263.14.51.40.000463
2005.263.14.51.40.001313 >>> Reading out PLM SCOE Settings
2005.263.14.51.40.001910
2005.263.14.51.40.002980 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.263.14.51.40.004012 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.263.14.51.40.005045 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.263.14.51.40.006072 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.263.14.51.40.007390 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.263.14.51.40.008711 Status_PLM_LCL1_V is currently 27.8604888916 (extracted from TLM
YM228942)
2005.263.14.51.40.009999 Status_PLM_LCL1_I is currently 0.432693988085 (extracted from TLM
YM232942)
2005.263.14.51.40.011288 Status_PLM_LCL2_V is currently 0.0650620236993 (extracted from TLM
YM244942)
2005.263.14.51.40.012566 Status_PLM_LCL2_I is currently 0.00557259470224 (extracted from TLM
YM248942)
```

2005.263.14.51.40.013894 Status_PLM_LCL3_V is currently 27.9418182373 (extracted from TLM YM260942)
2005.263.14.51.40.015207 Status_PLM_LCL3_I is currently 0.482282757759 (extracted from TLM YM264942)
2005.263.14.51.40.016524 Status_PLM_LCL4_V is currently 27.9418182373 (extracted from TLM YM276942)
2005.263.14.51.40.017818 Status_PLM_LCL4_I is currently 0.721904337406 (extracted from TLM YM280942)
2005.263.14.51.40.019104 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM YM292942)
2005.263.14.51.40.020400 Status_PLM_LCL5_I is currently 0.952407121658 (extracted from TLM YM296942)
2005.263.14.51.40.021693 Status_PLM_LCL6_V is currently 0.0766802430153 (extracted from TLM YM308942)
2005.263.14.51.40.023094 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM YM312942)
2005.263.14.51.40.024401 Status_PLM_LCL7_V is currently 27.7164230347 (extracted from TLM YM324942)
2005.263.14.51.40.025702 Status_PLM_LCL7_I is currently 2.63026475906 (extracted from TLM YM328942)
2005.263.14.51.40.027090 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM YM340942)
2005.263.14.51.40.028390 Status_PLM_LCL8_I is currently 0.00405279640108 (extracted from TLM YM344942)
2005.263.14.51.40.029701 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM YM356942)
2005.263.14.51.40.031014 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM YM360942)
2005.263.14.51.40.032328 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM YM372942)
2005.263.14.51.40.033612 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM YM376942)
2005.263.14.51.40.034923 Status_PLM_LCL11_V is currently 27.967376709 (extracted from TLM YM388942)
2005.263.14.51.40.036233 Status_PLM_LCL11_I is currently 0.0448340587318 (extracted from TLM YM392942)
2005.263.14.51.40.037528 Status_PLM_LCL12_V is currently 27.8906974792 (extracted from TLM YM404942)
2005.263.14.51.40.038835 Status_PLM_LCL12_I is currently 0.761925697327 (extracted from TLM YM408942)
2005.263.14.51.40.040154 Status_PLM_LCL13_V is currently 27.9534358978 (extracted from TLM YM420942)
2005.263.14.51.40.041467 Status_PLM_LCL13_I is currently 0.429089814425 (extracted from TLM YM424942)
2005.263.14.51.40.042793 Status_PLM_LCL14_V is currently 28.0254669189 (extracted from TLM YM436942)
2005.263.14.51.40.044128 Status_PLM_LCL14_I is currently 0.745967805386 (extracted from TLM YM440942)
2005.263.14.51.40.044829
2005.263.14.51.40.045440

2005.263.14.51.40.046434 PACS Power On Sequence has ended

2005.263.14.51.40.047157

Appendix 8: Log of PACS_POWER_OFF.tcl

```

2005.264.10.27.44.961773
*****
2005.264.10.27.44.962727 Start of PACS POWER OFF sequence.
*****
2005.264.10.27.44.963044
2005.264.10.27.44.963270 To run this script, the CDMU DFE and PLM SCOE should be
2005.264.10.27.44.963503 powered and configured.
2005.264.10.27.44.963728 To initiate, this script will connect and attach to the CDMUDFE
2005.264.10.27.44.963964 and PLM SCOE.
2005.264.10.27.44.964188
2005.264.10.27.44.964416 >>> Connecting to CDMU DFE.
2005.264.10.27.47.969210 >>> Attaching to CDMU DFE.
2005.264.10.27.50.976045
2005.264.10.27.50.976409 >>> Connecting to PLM SCOE.
2005.264.10.27.53.980293 >>> Attaching to PLM SCOE.
2005.264.10.27.56.981950
2005.264.10.27.56.982310 >>> Reading out CDMUDFE Settings
2005.264.10.27.56.982739
2005.264.10.27.57.090988 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.264.10.27.57.093409 Status_CDMU_Tmpolling is 1 (extracted from TLM YM780944)
2005.264.10.27.57.095762 Status_CDMU_SAReadActive is 1 (extracted from TLM YM781944)
2005.264.10.27.57.097872 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.264.10.27.57.100113 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.264.10.27.57.102265 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)
2005.264.10.27.57.104222 Status_CDMU_PSTfileName is PACS_prime_inst... (extracted from TLM
YM809944)
2005.264.10.27.57.106447 Status_CDMU_PSTrunning is 1 (extracted from TLM YM829944)
2005.264.10.27.57.107042
2005.264.10.27.57.107547 >>> Reading out PLM SCOE Settings
2005.264.10.27.57.108058
2005.264.10.27.57.110226 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.264.10.27.57.112706 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.264.10.27.57.115075 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.264.10.27.57.117295 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.264.10.27.57.119623 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.264.10.27.57.124179 Status_PLM_LCL1_V is currently 27.8628120422 (extracted from TLM
YM228942)
2005.264.10.27.57.127399 Status_PLM_LCL1_I is currently 0.435649961233 (extracted from TLM
YM232942)
2005.264.10.27.57.131784 Status_PLM_LCL2_V is currently 0.0627383813262 (extracted from TLM
YM244942)
2005.264.10.27.57.135189 Status_PLM_LCL2_I is currently 0.00557259470224 (extracted from TLM
YM248942)
2005.264.10.27.57.139993 Status_PLM_LCL3_V is currently 27.9418182373 (extracted from TLM
YM260942)
2005.264.10.27.57.143281 Status_PLM_LCL3_I is currently 0.487348765135 (extracted from TLM
YM264942)
2005.264.10.27.57.147690 Status_PLM_LCL4_V is currently 27.9418182373 (extracted from TLM
YM276942)
2005.264.10.27.57.150995 Status_PLM_LCL4_I is currently 0.72139775753 (extracted from TLM
YM280942)
2005.264.10.27.57.155380 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM
YM292942)
2005.264.10.27.57.158688 Status_PLM_LCL5_I is currently 0.952407121658 (extracted from TLM
YM296942)
2005.264.10.27.57.163247 Status_PLM_LCL6_V is currently 0.0766802430153 (extracted from TLM
YM308942)
2005.264.10.27.57.166524 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM
YM312942)
2005.264.10.27.57.170967 Status_PLM_LCL7_V is currently 27.7187461853 (extracted from TLM
YM324942)
2005.264.10.27.57.174257 Status_PLM_LCL7_I is currently 2.6292514801 (extracted from TLM
YM328942)
2005.264.10.27.57.178664 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM
YM340942)
2005.264.10.27.57.182002 Status_PLM_LCL8_I is currently 0.0045593958348 (extracted from TLM
YM344942)

```


2005.264.10.27.57.186403 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM YM356942)
2005.264.10.27.57.189821 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM YM360942)
2005.264.10.27.57.194276 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM YM372942)
2005.264.10.27.57.197779 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM YM376942)
2005.264.10.27.57.202386 Status_PLM_LCL11_V is currently 27.967376709 (extracted from TLM YM388942)
2005.264.10.27.57.205752 Status_PLM_LCL11_I is currently 0.0448340587318 (extracted from TLM YM392942)
2005.264.10.27.57.210231 Status_PLM_LCL12_V is currently 27.7907810211 (extracted from TLM YM404942)
2005.264.10.27.57.213601 Status_PLM_LCL12_I is currently 1.92153203487 (extracted from TLM YM408942)
2005.264.10.27.57.216950 Status_PLM_LCL13_V is currently 27.9534358978 (extracted from TLM YM420942)
2005.264.10.27.57.219964 Status_PLM_LCL13_I is currently 0.457206100225 (extracted from TLM YM424942)
2005.264.10.27.57.224544 Status_PLM_LCL14_V is currently 28.0254669189 (extracted from TLM YM436942)
2005.264.10.27.57.227987 Status_PLM_LCL14_I is currently 0.739128708839 (extracted from TLM YM440942)
2005.264.10.27.57.228699
2005.264.10.27.57.229327 Reset bias for all groups sequentially
2005.264.10.28.10.538123 BOL biases are set to zero
2005.264.10.28.10.538506 Now BOLC is prepared for switch-off
2005.264.10.28.10.539173 Set temperature probes off
2005.264.10.28.11.053585 Set all groups to OFF
2005.264.10.28.13.070846 >>> Switch OFF SPU
2005.264.10.28.13.071412
2005.264.10.28.13.138336 Sending Telecommand YC041942 to Disable Limiter 14 PACS SPU
2005.264.10.28.13.138911
2005.264.10.28.13.139557 >>> Checking
2005.264.10.28.19.145781 LCL 14 has currently a voltage of 0.0952693969011.(from YM436942)
2005.264.10.28.19.146190 LCL 14 has currently a current of 0.00430609611794.(from YM440942)
2005.264.10.28.19.146868
2005.264.10.28.19.650427 >>> Switch OFF BOLC
2005.264.10.28.19.650788
2005.264.10.28.19.797375 Sending Telecommand YC041942 to Disable Limiter 11 PACS BOLC
2005.264.10.28.19.797748
2005.264.10.28.19.798348 >>> Checking
2005.264.10.28.25.803718 LCL 11 has currently a voltage of 0.00929457508028.(from YM388942)
2005.264.10.28.25.804122 LCL 11 has currently a current of 0.00379949645139.(from YM392942)
2005.264.10.28.25.804743
2005.264.10.28.26.308518 >>> Switch OFF DECMEC
2005.264.10.28.26.308888
2005.264.10.28.26.384278 Sending Telecommand YC041942 to Disable Limiter 12 PACS DECMEC
2005.264.10.28.26.384924
2005.264.10.28.26.385574 >>> Checking
2005.264.10.28.32.391492 LCL 12 has currently a voltage of 0.00697093131021.(from YM404942)
2005.264.10.28.32.391892 LCL 12 has currently a current of 0.0121583892033.(from YM408942)
2005.264.10.28.32.392564
2005.264.10.28.32.896268 >>> Switch OFF DPU
2005.264.10.28.32.896628
2005.264.10.28.33.043212 Sending Telecommand YC041942 to Disable Limiter 13 PACS DPU
2005.264.10.28.33.043579
2005.264.10.28.33.044149 >>> Checking
2005.264.10.28.39.047565 LCL 13 has currently a voltage of 0.0185891501606.(from YM420942)
2005.264.10.28.39.047967 LCL 13 has currently a current of 0.00151979865041.(from YM424942)
2005.264.10.28.39.048558
2005.264.10.28.39.552301 PACS is off
2005.264.10.28.39.552667 >>> Reading out CDMUDFE Settings
2005.264.10.28.39.553245
2005.264.10.28.39.554448 Status_CDMU_OnLine is 1 (extracted from TLM YM777944)
2005.264.10.28.39.554494 Status_CDMU_TMpolling is 1 (extracted from TLM YM780944)
2005.264.10.28.39.556536 Status_CDMU_SAreAdActive is 1 (extracted from TLM YM781944)
2005.264.10.28.39.557557 Status_CDMU_SAqueueActive is 1 (extracted from TLM YM782944)
2005.264.10.28.39.558590 Status_CDMU_TMqueueActive is 1 (extracted from TLM YM783944)
2005.264.10.28.39.559607 Status_CDMU_TCqueueActive is 1 (extracted from TLM YM784944)

2005.264.10.28.39.560673 Status_CDMU_PSTfileName is PACS_prime_inst... (extracted from TLM YM809944)
2005.264.10.28.39.561711 Status_CDMU_PSTrunning is 1 (extracted from TLM YM829944)
2005.264.10.28.39.562339
2005.264.10.28.39.562911 >>> Reading out PLM SCOE Settings
2005.264.10.28.39.563482
2005.264.10.28.39.564456 Status_PLM_OnLine is 1 (extracted from TLM YM018942)
2005.264.10.28.39.565465 Status_PLM_PSU1_Master is currently 1 (extracted from TLM YM129942)
2005.264.10.28.39.566499 Status_PLM_PSU1_Slave is currently 1 (extracted from TLM YM145942)
2005.264.10.28.39.567607 Status_PLM_PSU2_Master is currently 1 (extracted from TLM YM177942)
2005.264.10.28.39.568628 Status_PLM_PSU2_Slave is currently 1 (extracted from TLM YM193942)
2005.264.10.28.39.569699 Status_PLM_LCL1_V is currently 27.8604888916 (extracted from TLM YM228942)
2005.264.10.28.39.570783 Status_PLM_LCL1_I is currently 0.434120982885 (extracted from TLM YM232942)
2005.264.10.28.39.571853 Status_PLM_LCL2_V is currently 0.0650620236993 (extracted from TLM YM244942)
2005.264.10.28.39.572965 Status_PLM_LCL2_I is currently 0.00607919460163 (extracted from TLM YM248942)
2005.264.10.28.39.574054 Status_PLM_LCL3_V is currently 27.9418182373 (extracted from TLM YM260942)
2005.264.10.28.39.575132 Status_PLM_LCL3_I is currently 0.483295977116 (extracted from TLM YM264942)
2005.264.10.28.39.576279 Status_PLM_LCL4_V is currently 27.9418182373 (extracted from TLM YM276942)
2005.264.10.28.39.577412 Status_PLM_LCL4_I is currently 0.72139775753 (extracted from TLM YM280942)
2005.264.10.28.39.579309 Status_PLM_LCL5_V is currently 27.9418182373 (extracted from TLM YM292942)
2005.264.10.28.39.580437 Status_PLM_LCL5_I is currently 0.952407121658 (extracted from TLM YM296942)
2005.264.10.28.39.581552 Status_PLM_LCL6_V is currently 0.079003892839 (extracted from TLM YM308942)
2005.264.10.28.39.582666 Status_PLM_LCL6_I is currently 0.00379949645139 (extracted from TLM YM312942)
2005.264.10.28.39.583774 Status_PLM_LCL7_V is currently 27.7187461853 (extracted from TLM YM324942)
2005.264.10.28.39.584877 Status_PLM_LCL7_I is currently 2.6292514801 (extracted from TLM YM328942)
2005.264.10.28.39.585966 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM YM340942)
2005.264.10.28.39.587053 Status_PLM_LCL8_I is currently 0.0045593958348 (extracted from TLM YM344942)
2005.264.10.28.39.588144 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM YM356942)
2005.264.10.28.39.589244 Status_PLM_LCL9_I is currently 0.00253299763426 (extracted from TLM YM360942)
2005.264.10.28.39.590349 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM YM372942)
2005.264.10.28.39.591429 Status_PLM_LCL10_I is currently 0.00278629735112 (extracted from TLM YM376942)
2005.264.10.28.39.592540 Status_PLM_LCL11_V is currently 0.00929457508028 (extracted from TLM YM388942)
2005.264.10.28.39.593784 Status_PLM_LCL11_I is currently 0.00379949645139 (extracted from TLM YM392942)
2005.264.10.28.39.594959 Status_PLM_LCL12_V is currently 0.00697093131021 (extracted from TLM YM404942)
2005.264.10.28.39.596140 Status_PLM_LCL12_I is currently 0.0116517897695 (extracted from TLM YM408942)
2005.264.10.28.39.597279 Status_PLM_LCL13_V is currently 0.0185891501606 (extracted from TLM YM420942)
2005.264.10.28.39.598404 Status_PLM_LCL13_I is currently 0.00151979865041 (extracted from TLM YM424942)
2005.264.10.28.39.599593 Status_PLM_LCL14_V is currently 0.0952693969011 (extracted from TLM YM436942)
2005.264.10.28.39.600726 Status_PLM_LCL14_I is currently 0.00430609611794 (extracted from TLM YM440942)
2005.264.10.28.39.601415
2005.264.10.28.39.602026

2005.264.10.28.39.603008 PACS Power Off Sequence has ended

2005.264.10.28.39.603730


```

2005.264.13.33.40.025778 LCL 4 has currently a voltage of 27.9418182373.(from YM276942)
2005.264.13.33.40.026184 LCL 4 has currently a current of 0.72139775753.(from YM280942)
2005.264.13.33.40.026817
2005.264.13.33.40.101033 LCL 4 has not been disabled. Repeat this step? : Choose Yes or No
2005.264.13.34.00.938056 User has chosen NO
2005.264.13.34.02.941486
2005.264.13.34.02.997601 Do you want to disable LCL 5? : Choose Yes or No
2005.264.13.34.04.418608 User has chosen YES
2005.264.13.34.06.420905
2005.264.13.34.06.510930 Sending Telecommand YC041942 to Disable Limiter
2005.264.13.34.06.511292 Synchronizing on SEV...
2005.264.13.34.06.533010 Synchronised on SEV for TC(s): YC041942
2005.264.13.34.06.533393
2005.264.13.34.06.533976 >>> Checking
2005.264.13.34.12.536928 LCL 5 has currently a voltage of 0.0325310118496.(from YM292942)
2005.264.13.34.12.537418 LCL 5 has currently a current of 0.000759899325203.(from YM296942)
2005.264.13.34.12.538051
2005.264.13.34.12.653026 ***** USER INFORMATION *****
2005.264.13.34.12.653819 User Info>: Check Successful! LCL 5 has been disabled.
2005.264.13.34.12.654464 *****
2005.264.13.34.13.813788
2005.264.13.34.13.865720 Do you want to disable LCL 7? : Choose Yes or No
2005.264.13.34.15.016365 User has chosen YES
2005.264.13.34.17.020982
2005.264.13.34.17.113227 Sending Telecommand YC041942 to Disable Limiter
2005.264.13.34.17.113596 Synchronizing on SEV...
2005.264.13.34.17.114566 Synchronised on SEV for TC(s): YC041942
2005.264.13.34.17.115186
2005.264.13.34.17.115749 >>> Checking
2005.264.13.34.23.121407 LCL 7 has currently a voltage of 0.034854657948.(from YM324942)
2005.264.13.34.23.121808 LCL 7 has currently a current of 0.00506599526852.(from YM328942)
2005.264.13.34.23.122413
2005.264.13.34.23.156551 ***** USER INFORMATION *****
2005.264.13.34.23.157282 User Info>: Check Successful! LCL 7 has been disabled.
2005.264.13.34.23.157893 *****
2005.264.13.34.26.259301
2005.264.13.34.26.298706 Do you want to disable LCL 3? : Choose Yes or No
2005.264.13.34.27.823666 User has chosen YES
2005.264.13.34.29.827419
2005.264.13.34.29.898042 Sending Telecommand YC041942 to Disable Limiter
2005.264.13.34.29.898411 Synchronizing on SEV...
2005.264.13.34.29.907390 Synchronised on SEV for TC(s): YC041942
2005.264.13.34.29.907805
2005.264.13.34.29.908393 >>> Checking
2005.264.13.34.35.914173 LCL 3 has currently a voltage of 0.00929457508028.(from YM260942)
2005.264.13.34.35.914573 LCL 3 has currently a current of 0.00759899290279.(from YM264942)
2005.264.13.34.35.915188
2005.264.13.34.35.949361 ***** USER INFORMATION *****
2005.264.13.34.35.950064 User Info>: Check Successful! LCL 3 has been disabled.
2005.264.13.34.35.950684 *****
2005.264.13.34.39.017874
2005.264.13.34.39.069900 ***** USER INFORMATION *****
2005.264.13.34.39.070773 User Info>: No LCL is selected to be switched on as fifth
2005.264.13.34.39.071517 *****
2005.264.13.34.39.995578
2005.264.13.34.40.035497 ***** USER INFORMATION *****
2005.264.13.34.40.036264 User Info>: No LCL is selected to be switched on as sixth
2005.264.13.34.40.036896 *****
2005.264.13.34.40.533515
2005.264.13.34.40.572819 Do you want to disable PSU(s)? : Choose Yes or No
2005.264.13.34.42.850889 User has chosen NO
2005.264.13.34.44.853941
2005.264.13.34.44.855224 PSU 1 Master status is currently 1 (from YM129942)
2005.264.13.34.44.856256 PSU 1 Slave status is currently 1 (from YM145942)
2005.264.13.34.44.857712 PSU 2 Master status is currently 1 (from YM177942)
2005.264.13.34.44.858363 PSU 2 Slave status is currently 1 (from YM193942)
2005.264.13.34.44.858980
2005.264.13.34.44.859573 Power down of HIFI is done.
2005.264.13.34.44.860165
2005.264.13.34.44.899764 Do you want to power down another instrument? : Choose Yes or No
2005.264.13.35.12.153799 User has chosen YES

```


2005.264.13.47.51.490466 Status_PLM_LCL1_I is currently 0.000101930265373 (extracted from TLM YM232942)

2005.264.13.47.51.491591 Status_PLM_LCL2_V is currently 0.0650620236993 (extracted from TLM YM244942)

2005.264.13.47.51.492828 Status_PLM_LCL2_I is currently 0.000506599550135 (extracted from TLM YM248942)

2005.264.13.47.51.493920 Status_PLM_LCL3_V is currently 0.00929457508028 (extracted from TLM YM260942)

2005.264.13.47.51.495020 Status_PLM_LCL3_I is currently 0.000506599550135 (extracted from TLM YM264942)

2005.264.13.47.51.496109 Status_PLM_LCL4_V is currently 0.0371783003211 (extracted from TLM YM276942)

2005.264.13.47.51.497217 Status_PLM_LCL4_I is currently 0.000506599550135 (extracted from TLM YM280942)

2005.264.13.47.51.498302 Status_PLM_LCL5_V is currently 0.0302073694766 (extracted from TLM YM292942)

2005.264.13.47.51.499408 Status_PLM_LCL5_I is currently 0.000253299775068 (extracted from TLM YM296942)

2005.264.13.47.51.500519 Status_PLM_LCL6_V is currently 0.0766802430153 (extracted from TLM YM308942)

2005.264.13.47.51.501627 Status_PLM_LCL6_I is currently 0.000253299775068 (extracted from TLM YM312942)

2005.264.13.47.51.502741 Status_PLM_LCL7_V is currently 0.0325310118496 (extracted from TLM YM324942)

2005.264.13.47.51.503854 Status_PLM_LCL7_I is currently 0.000506599550135 (extracted from TLM YM328942)

2005.264.13.47.51.504956 Status_PLM_LCL8_V is currently 0.00929457508028 (extracted from TLM YM340942)

2005.264.13.47.51.506087 Status_PLM_LCL8_I is currently 0.000506599550135 (extracted from TLM YM344942)

2005.264.13.47.51.507201 Status_PLM_LCL9_V is currently 0.00697093131021 (extracted from TLM YM356942)

2005.264.13.47.51.508325 Status_PLM_LCL9_I is currently 0.00101319910027 (extracted from TLM YM360942)

2005.264.13.47.51.509443 Status_PLM_LCL10_V is currently 0.00929457508028 (extracted from TLM YM372942)

2005.264.13.47.51.510533 Status_PLM_LCL10_I is currently 0.000253299775068 (extracted from TLM YM376942)

2005.264.13.47.51.511631 Status_PLM_LCL11_V is currently 0.00929457508028 (extracted from TLM YM388942)

2005.264.13.47.51.512746 Status_PLM_LCL11_I is currently 0.000253299775068 (extracted from TLM YM392942)

2005.264.13.47.51.513926 Status_PLM_LCL12_V is currently 0.00697093131021 (extracted from TLM YM404942)

2005.264.13.47.51.515057 Status_PLM_LCL12_I is currently 0.000506599550135 (extracted from TLM YM408942)

2005.264.13.47.51.516379 Status_PLM_LCL13_V is currently 0.0209127943963 (extracted from TLM YM420942)

2005.264.13.47.51.517578 Status_PLM_LCL13_I is currently 0.000506599550135 (extracted from TLM YM424942)

2005.264.13.47.51.518743 Status_PLM_LCL14_V is currently 0.0975930392742 (extracted from TLM YM436942)

2005.264.13.47.51.519997 Status_PLM_LCL14_I is currently 0.000253299775068 (extracted from TLM YM440942)

2005.264.13.47.51.521158 Disconnect and detach from CDMU DFE and PLM SCOE

2005.264.13.47.51.521936

2005.264.13.47.51.522587

2005.264.13.47.51.523218 Disconnecting from CDMU DFE

2005.264.13.47.53.526758 Detaching from CMDU DFE

2005.264.13.47.54.530250

2005.264.13.47.54.530614 Disconnecting from PLM SCOE

2005.264.13.47.56.533680 Detaching from PLM SCOE

2005.264.13.47.57.537265

Appendix 11: HP-111000-ASED-NC-1282 - Wrong MIB definition of command PC162420

Monday September 19 2005 6:51 PM

Company ESTEC	Project Name HERSCHEL-PANCK	NCR-No: HP-113000-ASED-NC-1482 Related internal NCR-No: Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Revision: 0 Page 1 of 1
Nonconformance Report		
NCR Title: Wrong MIB definition of command PC162420		
NC Item Identification: PACS		
Next Higher Assembly: HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)		
Drawing No	Sr No.	
Procedure No		
Supplier: MPE	Purchase Order	
Subsystem	Model	EQM
NC Observation Date: 19-SEP-05 Location: ASED OTN		NC Detected During: Test
Description of Nonconformance: During the IMT, the command PC162420 was rejected. The reason is that this command allows 8 times a value for parameter PP067420. The PACS TCL script included 9 times a value for this parameter. Solution: Change definition in MIB. For now, this is done manually (since IMT should continue). PACS will update MIB and send changes to ASP (HPSDB).		Requirements Violated
Initiator: Date, Name and Signature: 19-SEP-05 S.ILSEN		
Date: Name: Signature:		

Appendix 12: HP-111000-ASED-NC-1491 – PACS DPU power anomaly

Wednesday September 21 2005 4:56 PM

Company ESTEC		Project Name HERSCHEL-PLANCK		NCR-No: HP-113000-ASED-NC-1491 Related Internal NCR-No: Critical Item: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Revision 0 Page 1 of 2							
Nonconformance Report											
NCR Title PACS DPU power anomaly											
NC Item Identification PACS											
Next Higher Assembly HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)											
Drawing No						Sr No.					
Procedure No											
Supplier MPE				Purchase Order							
Subsystem						Model		EQM			
NC Observation Date: 21-SEP-05 Location: ASEDTN						NC Detected During Test					
Description of Nonconformance										Requirements Violated	
<p>During PACS IMT testing 2 power anomalies were seen as follows: 1) DPU rebooted itself during testing -> No power surge was identified on PLM SCOE 2) DPU's power consumption dropped to zero during test. PACS (all modules) were powered down on request of PACS instrument team. DPU was restarted after 40 minutes, power consumption stayed at 0 A.</p> <p>Power cable was checked with breakout box. Result: 28 V is available at the end of the PLM SCOE cable.</p> <p>NRB to be held, to decide on further investigations.</p>											
Initiator: Date, Name and Signature 21-SEP-05 D. HENDRY											
Internal NRB Dispositions 21.09.05 Internal NRB, ASEDTN, PACS, ASP, ESA Perform initial investigations as follows: Disconnect cable DB 32 GO1 3-22 and 4-23 measure voltage result 28 volts. Insert break out box in line GO1 and reconnect harness, measure voltage during DPU switch on, result initial current peak of 150 ma then zero current. Disconnect GO1 and connect 50 ohm load and measure switch on current and voltage, result 28v ok and 250 ma current ok Initial conclusion power SCOE is operating ok and fault is within the DPU. Convene customer NRB Ref. to MoMs										Classification: Major <input checked="" type="checkbox"/> Minor <input type="checkbox"/>	
										Customer Notification	
Cause of NC				Corrective/Preventative Actions				Verification			
Ref to Failure Report											
Date:	PA	Engineering									
Name:	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05	21-SEP-05
Signature:	D.Hendry	S.Idler	D.Hendry	S.Ilsert	C.Schlosser	A.Heske	W.Pinter-Kraimer	G.Doubrovik	H.Feuchtneger	E.Wisoznek	

Wednesday September 21 2005 4:55 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1491	
		Related internal NCR-No:	
		Critical Item: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Revision 0
Page 2 of 2			
Nonconformance Report - Continuation Sheet -			
Customer NRB Dispositions (Class Major Only) Ref. to MoMs		Verification	
<p>21.09.05 ESA,ASP,ASED,PACS. Following initial investigations it was considered that the SCOE and harness were not the cause of the failure and PACS recommend to deintegrate the DPU and return to the supplier for failure investigations. PACS state that no similar problem has been seen during any lower level testing, during ILT the instrument was power on for a max of 3 days, during the present IMT phase PACS has been on for max of 5 days (in stand by during HIFI IMT and weekend), Unit temp was 28 degees C. All Instruments use the same design of DPU I/F power circuit PACS have a replacement unit model CFM at MPI which can be available at OTN by 09-00 tomorrow, this unit needs to have a OBSW upload with Issue 7.68 ,present unit has 7.65, the new issue is for internal H/W changes and to be compatible with I EGSE. AI/1 PACS The unit will have stand alone test at MPI following OBSW upload. The Mechanical I/F of the CFM is the same as existing AVM. AI/2PACS The electrical I/F (no redundancy)Connector configuration with respect to which redundancy is connected needs to be confirmed by PACS to ensure correct harness length. AI/3 PACS PACS to raise NCR to track the failure investigations of the AVM List of activities: 1)Switch off HIFI and SPIRE 2) Switch off power SCOE and CDMU FE 3)Check grounding of power SCOE and DPU. 4) Electrically disconnect DPU using general ESD protection no specific order for connector removal is required. 5)Mechanically deintegrate unit. 6)Perform SCOE power on electrical check and current and voltage measurement using dummy loads (analogue measurement). 7)Mechanically integrate CFM 8)Electrical integration check of power and isolation. 9)perform DPU power up check. 10)Pack AVM in transport container and return to supplier for failure investigations.</p>			
Finally Determined Cause of NC Ref to Failure Report		Corrective/Preventative Actions	
Request for Waiver Yes <input type="checkbox"/> No <input type="checkbox"/> Reference:		Alert Yes <input type="checkbox"/> No <input type="checkbox"/> Reference:	Other related Documents
			NCR Close Out
NRB Approval			
Organization/ Name			
Date, Signature			

Appendix 13: HP-111000-ASED-NC-1493 - CRC in HK not compliant with CRC in procedure Memory Management Test

Wednesday September 21 2005 4:58 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1493 Related internal NCR-No: Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Revision: 0 Page 1 of 1
Nonconformance Report		
NCR Title: CRC in HK not compliant with CRC in procedure (Memory Management Test)		
NC Item Identification: PACS		
Next Higher Assembly: HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)		
Drawing No:	Sr No.:	
Procedure No:		
Supplier: MPE	Purchase Order:	
Subsystem:	Model:	EQM
NC Observation Date: 21-SEP-05 Location: ASED OTN		NC Detected During: Test
Description of Nonconformance During the PACS IMT, the CRC values in the procedure for the Memory Management Test did not comply with the CRC values in the PACS HK. PACS do decide on further investigation or update of IMT procedure.		Requirements Violated
Initiator: Date, Name and Signature: 21-SEP-05 S ILSEN		
Date: Name: Signature:		

Appendix 14: HP-111000-ASED-NC-1494 - DEC_MEC got blocked and DEC_MEC - DPU comm link dead

Wednesday September 21 2005 5:16 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1494 Related internal NCR-No: Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Revision 0 Page 1 of 1
Nonconformance Report		
NCR Title DEC/MEC got blocked and DEC/MEC - DPU comm link dead.		
NC Item Identification PACS		
Next Higher Assembly HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)		
Drawing No		Sr No.
Procedure No		
Supplier MPE		Purchase Order
Subsystem		Model EQM
NC Observation Date: 21-SEP-05 Location: ASEDTN		NC Detected During Test
Description of Nonconformance		Requirements Violated
<p>During the execution of IMT (testID 404), the DEC/MEC got blocked (according to PACS). The running script is aborted and a manual stack command is executed: PC005380 (DPU_SET_FUNCT) With the following parameter: PP007380 = 103 PP006380 = 1</p> <p>During the cooler recycle, the DEC/MEC - DPU link dead. To recover from this without loosing the cooler recycle, DEC/MEC is manually powered down and up again. After this all DEC/MEC commands in the PACS_POWER_ON.tcl are executed with the manual stack. This was not successful. Another approach is tried: 1) power down SPU, DEC/MEC, DPU (manually from PLM SCOE) 2) Execute PACS_POWER_ON_BOLCout.TCL (see appendix xxx) 3) PC003380 (with PP005380 = PHOT and PP025380 = BOTH Array) This approach was successful.</p> <p>These problems should be investigated further by PACS.</p>		
Initiator: Date, Name and Signature 21-SEP-05 S ILSSEN		
Date: Name: Signature:		

Appendix 15: HP-111000-ASED-NC-1495 - Cooler Recycle Failed

Wednesday September 21 2005 5:12 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1495	
		Related internal NCR-No:	
		Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Revision 0
		Page 1 of 1	
Nonconformance Report			
NCR Title Cooler Recycle Failed			
NC Item Identification PACS			
Next Higher Assembly HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)			
Drawing No		Sr No.	
Procedure No			
Supplier		Purchase Order	
Subsystem		Model	EQM
NC Observation		NC Detected During Test	
Date: 20-SEP-05 Location: ASED OTN			
Description of Nonconformance			Requirements Violated
During the first cooler recycle in the IMT, PACS detected that this step was not successful. PACS will revise the procedure for the cooler operation.			
Initiator: Date, Name and Signature 21-SEP-05 S ILSSEN			
Date: Name: Signature:			

Appendix 16: HP-111000-ASED-NC-1496 – IMT TestID 516 should be run in Burst mode (SPEC_dark_current...tcl)

Wednesday September 21 2005 5:25 PM


Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1496	
		Related internal NCR-No:	
		Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Revision 0
		Page 1 of 1	
Nonconformance Report			
NCR Title IMT TestID 516 should be run in Burst mode (SPEC_dark_current...tcl)			
NC Item Identification PACS			
Next Higher Assembly HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)			
Drawing No		Sr No.	
Procedure No			
Supplier		Purchase Order	
Subsystem		Model	EQM
NC Observation		NC Detected During Test	
Date: 20-SEP-05 Location: ASED OTN			
Description of Nonconformance		Requirements Violated	
<p>During the following script: SPEC_dark_current_spt_eqmimt_obs_shell.tcl a lot of SSC errors were detected on the following packets with APID: 1157, Type 21, Subtype 1.</p> <p>To solve this, during this test, the bus profile is changed to PACS_burst_mode.pst on request of PACS and the following command is sent: PC009380 (DPU_SET_BUS_LIST) ? Enabled. Now both the DPU and the CDMU DFE are configured for PACS burst mode and no SSC errors are reported for the packets mentioned above. After this change 2 more SSC errors were detected, both on HK packets (3,25 ? APID 1152)</p> <p>The script/procedure should be updated so Burst Mode is implemented before the script is executed and SSC errors occur.</p>			
Initiator: Date, Name and Signature: 21-SEP-05 S ILSEN			
Date: Name: Signature:			

Appendix 17: HP-111000-ASED-NC-1497 - DPU packets get corrupted (bad packets)

Wednesday September 21 2005 5:31 PM

Company ESTEC	Project Name HERSCHEL-PLANCK	NCR-No: HP-113000-ASED-NC-1497	
		Related Internal NCR-No:	
		Critical Item: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Revision: 0
		Page 1 of 1	
Nonconformance Report			
NCR Title: DPU packets get corrupted ("bad packets")			
NC Item Identification: PACS			
Next Higher: Assembly: HERSCHEL INSTRUMENTS AND TELESCOPE (CFE)			
Drawing No:		Sr No.:	
Procedure No:			
Supplier:		Purchase Order:	
Subsystem:		Model:	EQM
NC Observation		NC Detected During: Test	
Date: 21-SEP-05 Location: ASED OTN			
Description of Nonconformance			Requirements Violated
During the PACS IMT, suddenly all CRC checks failed on all incoming PACS packets. PACS reacted by sending command PC367380 (DPU_RESET_1553). Apparently this is a known PACS bug which occurs every ~30 hours. Problem should be solved in new DPU versions.			
Initiator: Date, Name and Signature: 21-SEP-05 S ILSEN			
Date:			
Name:			
Signature:			

Appendix 18: Power Profile (from PLM SCOE) during DPU power down



16 Distribution List

	Name	Dep./Comp.		Name	Dep./Comp.
	Alberti von Mathias Dr.	AOE22		Sonn Nico	AOE51
	Barlage Bernhard	AED11		Steininger Eric	AED44
	Bayer Thomas	AOA52	X	Stritter Rene	AED11
	Brune Holger	AOA55		Thörmer Klaus-Horst Dr.	OTN/AED65
	Fehringer Alexander	AOE13		Wagner Klaus	AOE22
X	Fricke Wolfgang Dr.	AED 65	X	Wietbrock Walter	AET12
	Geiger Hermann	AOA52		Wöhler Hans	AOE22
	Gerner Willi	AED11		Wössner Ulrich	ASE442
X	Grasl Andreas	OTN/AOA54			
	Grasshoff Brigitte	AET12			
	Hauser Armin	AOE22			
X	Hendry David	Terma Resid.			
	Hengstler Reinhold	AOA 5			
	Hinger Jürgen	AOE22	X	Alcatel	ASP
	Hofmann Rolf	ASE442	X	ESA/ESTEC	ESA
X	Hohn Rüdiger	AED65		Instruments:	
	Huber Johann	AOA52	X	MPE (PACS)	MPE
	Hund Walter	ASE442	X	RAL (SPIRE)	RAL
X	Idler Siegmund	AED432	X	SRON (HIFI)	SRON
X	Ilsen Stijn	Terma Resid.		Subcontractors:	
	Ivány von András	FAE22		Air Liquide, Space Department	AIR
	Jahn Gerd Dr.	AOE22		Air Liquide, Space Department	AIRS
	Kalde Clemens	APE3		Air Liquide, Orbital System	AIRT
	Kameter Rudolf	OTN/AOA54		Alcatel Bell Space	ABSP
	Kettner Bernhard	AET42		Astrium Sub-Subsyst. & Equipment	ASSE
X	Knoblauch August	AET32		Austrian Aerospace	AAE
X	Koelle Markus	AOA53		Austrian Aerospace	AAEM
X	Kroeker Jürgen	AED65		APCO Technologies S. A.	APCO
	Kunz Oliver Dr.	AOE22		Bieri Engineering B. V.	BIER
X	Lamprecht Ernst	OTN/ASI21		BOC Edwards	BOCE
	Lang Jürgen	ASE442		Dutch Space Solar Arrays	DSSA
	Langenstein Rolf	AED15		EADS CASA Espacio	CASA
	Langfermann Michael	AOA51		EADS CASA Espacio	ECAS
X	Mack Paul	OTN/AOA54		EADS Space Transportation	ASIP
	Müller Jörg	AOA52		Eurocopter	ECD
	Müller Ralf	FAE22		European Test Services	ETS
	Peltz Heinz-Willi	AOE13		HTS AG Zürich	HTSZ
	Pietroboni Karin	AED65		Linde	LIND
	Platzer Wilhelm	AED22		Patria New Technologies Oy	PANT
	Reichle Konrad	AOA52		Phoenix, Volkmarsen	PHOE
	Reuß Friedhelm	AED62		Prototech AS	PROT
X	Rühe Wolfgang	AED65		QMC Instruments Ltd.	QMC
	Runge Axel	OTN/AOA54		Rembe, Brilon	REMB
	Sachsse Bernt	AED21		Rosemount Aerospace GmbH	ROSE
	Schink Dietmar	AED44		RYMSA, Radiación y Microondas	RYM

	Name	Dep./Comp.		Name	Dep./Comp.
X	Schlosser Christian	OTN/AOA54		SENER Ingenieria SA	SEN
	Schmidt Rudolf	FAE22		Stöhr, Königsbrunn	STOE
	Schweickert Gunn	AOE22		Terma A/S, Herlev	TER

END OF DOCUMENT