SUBJECT:	PFM FINAL SIH ELECTRICAL INTEGRATION/CHECKOUT PROCEDURE		
PREPARED BY:	Douglas Griffin		
DOCUMENT No:	SPIRE-RAL-PRC-002951		
ISSUE:	2.0	Date:	28-08-07
APPROVED BY:	Bruce Swinyard	Date:	



PFM Final SIH Electrical Integration/Checkout Procedure

**Ref:** SPIRE-RAL-PRC-002951

Issue: 2.0 Date: 29-08-07 Page: 2 of 74

## **Change Record**

ISSUE	DATE	
1.0		Initial release -
2.0	29/08/07	Change resistor values to 470hm ± 5%
		Include instrument commanding extracted from SFT doc



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-002951

Issue: 2.0 Date: 29-08-07 Page: 3 of 74

### **Table of Contents**

1. Al	PPLICABLE/REFERENCE DOCUMENTS	5
2. SO	COPE AND INTRODUCTION	5
3. PI	ERSONNEL	5
4. M	IATING OF SIH-IS TO CVV-CB AND SVM-CB FOR INITIAL SFT	6
4.1	Prerequisites	6
4.2	END STATE	6
4.3	Notes	
4.4	DETAILED PROCEDURE	8
5. D	E-MATING OF SIH-IS AND SIH-SS FOR LPU INTEGRATION	30
5.1	Prerequisites	30
5.2	END STATE	
5.3	Notes	
5.4	DETAILED PROCEDURE	31
6. M	ATING OF SIH-IS AND SIH-SS AFTER LPU INTEGRATION	34
6.1	Prerequisites	34
6.2	Notes	
6.3	DETAILED PROCEDURE	35
7. Al	PPENDICES	38
7.1	PROCEDURE SPIRE-FM-SFT-DPU-ON-P	38
7.2	PROCEDURE SPIRE-FM-SFT-DRCU-ON-P	
7.3	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-01-P	41
7.4	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-03-P	43
7.5	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-06-P	
7.6	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-07-P	
7.7	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-04-P	
7.8	PROCEDURE SPIRE-FM-SFT-FUNC-SCU-05-P	
7.9	PROCEDURE SPIRE-FM-SFT-FUNC-MCU-01-P	
7.10		
7.11		
7.12		
7.13		
7.14		
7.15		
7.16		
7.17		
7.18 7.19		
7.19		
7.20		
7.21		

### **Procedure**

**Ref:** SPIRE-RAL-PRC-002951

Issue: 2.0 Date: 29-08-07 Page: 4 of 74

PFM Final SIH Electrical Integration/Checkout Procedure

7.23	PROCEDURE: SPIRE-FM-SFT-SPEC-JFET-ON-02	66
7.24	PROCEDURE: SPIRE-FM-SFT-SPEC-JFET-OFF	67
7.25	PROCEDURE: SPIRE-FM-SFT-SLIA-OFF-P	69
7.26	PROCEDURE SPIRE-FM-SFT-MCU-OFF-P	70
7.27	PROCEDURE SPIRE-FM-SFT-SCU-OFF-P	71
7.28	PROCEDURE: SPIRE-FM-SFT-DRCU-OFF-P	72
7.29	PROCEDURE SPIRE-FM-SFT-DPU-OFF-P	73
7.30	SPIRE-SAFE-SWITCH-OFF	74

#### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

**Ref:** SPIRE-RAL-PRC-002951

Issue: 2.0 Date: 29-08-07 Page: 5 of 74

#### 1. APPLICABLE/REFERENCE DOCUMENTS

Number	TITLE	<b>Document Number</b>	Issue
AD 1	SPIRE FPU Handling and Mechanical Integration	SPIRE-RAL-PRC-002802	2
	Procedure		
AD 2	Making SPIRE ESD Safe	SPIRE-RAL-NOT-002028	2
AD 3	SPIRE FM Warm Functional Test Procedures	SPIRE-RAL-PRC-2422	2.2

Number	TITLE	<b>Document Number</b>	Issue
RD1	Cryo Harness Interconnection Diagram	2547-121430-030-01-0B	В
	SPIRE (PFM)		
RD2	SPIRE PFM SIH ELECTRICAL	SPIRE-RAL-PRC-002951	2.0
	INTEGRATION PROCEDURE		
RD3	SPIRE FM Short Functional Test Procedures	SPIRE-RAL-PRC-2494	2.3

#### 2. SCOPE AND INTRODUCTION

This document establishes the detailed procedure to be followed for the final electrical integration of the SIH following completion of RD2.

- §4 Mating of SIH-IS to CVV-CB and SVM-CB covers the following activities:
  - 1. The mating of the SIH-IS and SIH-CS harnesses at the CVV-CB vacuum feedthrus
  - 2. The mating of the SIH-IS and SIH-SS harnesses at the SVM-CB
  - 3. Integration electrical tests whereby the balance of Idd and Iss for the JFET modules is measured
- §5 *De-mating of SIH-IS and SIH-SS for LPU Integration* has been included because it is foreseen that the LPU will have to be integrated after initial electrical integration and UFT of SPIRE. This requires that the SIH-SS-XX be de-mated from the SIH-IS-XX at the SVM-CB and the SPIRE SVM panel be opened.
- §6 *Mating of SIH-IS and SIH-SS after LPU Integration* has been included to document the procedure for the final mating of the SIH-SS-XX and SIH-IS-XX after integration and test of the LPU.

The scripts and procedures to command the instrument are identical to those contained in "SPIRE FM Short Functional Test Procedures" (RD 3).

#### 3. PERSONNEL

SPIRE Engineer EADS Engineer EADS PA



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 6 of 74

#### 4. MATING OF SIH-IS TO CVV-CB AND SVM-CB FOR INITIAL SFT

#### 4.1 Prerequisites

- 1. The DCU, FCU and DPU have been mechanically and electrically integrated to the SVM panel and the SIH-SS harnesses are all integrated but not mated to the SVM-CB (Note: if the LPU is not integrated to the FCU, then dummy LPU simulator plugs are mated to FCU P43/P44)
- 2. The SIH-CS harnesses have been mated to the SPIRE FPU + JFP/JFS
- 3. The SPIRE SVM panel has been closed
- 4. The PLM has been mechanically integrated to the SVM
- 5. The SIH-IS-XX harnesses are mechanically integrated onto the outside of the cryostat.
  - a. They are not mated at the CVV-CB
  - b. They are mechanically integrated to the SVM-CB without electrical termination
- 6. The SPIRE UFT has been successfully completed

#### 4.2 End State

The electrical integration tests have been completed The instrument is ready for SFT

#### 4.3 Notes

- 1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream for > 30 sec to discharge the harness.
- 2. If an anomaly is detected during the integration test, then the instrument can be switched off from any state using the procedure in §7.30 -



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 7 of 74

SPIRE-SAFE-SWITCH-OFF.



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 8 of 74

#### 4.4 Detailed Procedure

No:	Activity	Remarks/Results	Sign off
	Mating of SIH-IS to SIH-CS		
1	Prepare a 128-way BOB to short all contacts to spacecraft		
l	chassis via a 1MOhm resistor		
2	SIH-04		
	Short contacts of 312100 J03 to spacecraft chassis with BOB		
3	Remove Type-VII safeing plug from 211121 J22		
4	Mate 211121 P22 to J22		
5	Demate BOB from 312110 J03		
6	Mate Type-VII safeing plug to 312100 J03		
7	SIH-05		
,	Short contacts of 312100 J02 to spacecraft chassis with BOB		
8	Remove Type-VII safeing plug from 211121 J23		
9	Mate 211121 P23 to J23		
10	Demate BOB from 312100 J02		
11	Mate Type-VII safeing plug to 312100 J02		
12	SIH-06		
12	Short contacts of 312200 J03 to spacecraft chassis with BOB		
13	Remove Type-VII safeing plug from 211121 J24		
14	Mate 211121 P24 to J24		
15	Demate BOB from 312200 J03		
16	Mate Type-VII safeing plug to 312200 J03		
17	SIH-07		
17	Short contacts of 312200 J04 to spacecraft chassis with BOB		
18	Remove Type-VII safeing plug from 211121 J25		
19	Mate 211121 P25 to J25		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 9 of 74

No:	Activity	Remarks/Results	Sign off
20	Demate BOB from 312200 J04		
21	Mate Type-VII safeing plug to 312200 J04		
22	SIH-08		
	Short contacts of 312200 J01 to spacecraft chassis with BOB		
23	Remove Type-VII safeing plug from 211121 J27		
24	Mate 211121 P27 to J27		
25	Demate BOB from 312200 J01		
26	Mate Type-VII safeing plug to 312200 J01		
27	SIH-09		
21	Short contacts of 312200 J02 to spacecraft chassis with BOB		
28	Remove Type-VII safeing plug from 211121 J28		
29	Mate 211121 P28 to J28		
30	Demate BOB from 312200 J02		
31	Mate Type-VII safeing plug to 312200 J02		
32	SIH-10		
32	Short contacts of 312300 J06 to spacecraft chassis with BOB		
33	Remove Type-VII safeing plug from 211121 J34		
34	Mate 211121 P34 to J34		
35	Demate BOB from 312300 J06		
36	Mate Type-VII safeing plug to 312300 J06		
37	SIH-12		
31	Short contacts of 312300 J05 to spacecraft chassis with BOB		
38	Remove Type-VII safeing plug from 211121 J33		
39	Mate 211121 P33 to J33		
40	Demate BOB from 312300 J05		
41	Mate Type-VII safeing plug to 312300 J05		
42	SIH-02		
44	Short contacts of 312200 J05 to spacecraft chassis with BOB		
43	Remove Type-VII safeing plug from 211121 J31		
44	Mate 211121 P31 to J31		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 10 of 74

No:	Activity	Remarks/Results	Sign off
45	Demate BOB from 312200 J05		
46	Mate Type-VII safeing plug to 312200 J05		
47	SIH-11		
47	Short contacts of 312300 J04 to spacecraft chassis with BOB		
48	Remove Type-VIII safeing plug from 211121 J30		
49	Mate 211121 P30 to J30		
50	Demate BOB from 312300 J04		
51	Mate Type-VIII safeing plug to 312300 J04		
52	SIH-13		
32	Short contacts of 312300 J03 to spacecraft chassis with BOB		
53	Remove Type-VIII safeing plug from 211121 J29		
54	Mate 211121 P29 to J29		
55	Demate BOB from 312300 J03		
56	Mate Type-VIII safeing plug to 312300 J03		
57	SIH-01		
37	Short contacts of 312200 J06 to spacecraft chassis with BOB		
58	Remove Type-VI safeing plug from 211121 J32		
59	Mate 211121 P32 to J32		
60	Demate BOB from 312200 J06		
61	Mate Type-VI safeing plug to 312200 J06		
62	SIH-03		
02	Short contacts of 312100 J04 to spacecraft chassis with BOB		
63	Remove Type-V safeing plug from 211121 J26		
64	Mate 211121 P26 to J26		
65	Demate BOB from 312100 J04		
66	Mate Type-V safeing plug to 312100 J04		
	Idd/Iss measurement Preparation		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 11 of 74

No:	Activity		Remarks/Results		Sign off
	Prepare a 128-way BOB for inl P06/J06 with $47\Omega(5\%)$ inline so contacts:				
67	Function  PTC JFETV Bias_A +ve  PTC JFETV Bias_A -ve  SLW_JFETV_A1 +ve  SLW_JFETV_A1 -ve  SLW_JFETV_A2 +ve  SLW_JFETV_A2 -ve  SSW_JFETV_A +ve  SSW_JFETV_A - ve	24 35 92 91 103 113 68 57			
	SSW_JFETV2_A +ve SSW_JFETV2_A -ve  The remaining contacts have in Temporarily label BOB as SPIR				
68	Measure and record the resistar BOB prepared for CB312200 P resistance is to be $47\pm2.3~\Omega$		Function  24  35  92  91  103  113  68  57  70  81	Resistance (Ohm)	

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 12 of 74

No:	Activity		Remarks/Results	Sign off
	Prepare a 128-way BOB for	inline insertion in CB312100		
		e series resistors in the following		
	` '	e series resistors in the following		
	contacts:			
	Function	Contact number		
	PSW_JFETV1_A +	26		
	PSW_JFETV1_A -	37		
	PSW_JFETV2_A +	38		
	PSW_JFETV2_A -	49		
	PSW_JFETV3_A +	48		
	PSW_JFETV3_A -	60	4	
	PSW_JFETV4_A +	59		
	PSW_JFETV4_A -	71		
	PSW_JFETV5_A +	50		
	PSW_JFETV5_A -	61	4	
00	PSW_JFETV6_A +	62		
69	PSW_JFETV6_A -	51	4	
	PMW_JFETV1_A +	86		
	PMW_JFETV1_A -	87	4	
	PMW_JFETV2_A +	97	4	
	PMW_JFETV2_A -	98		
	PMW_JFETV3_A +	108	4	
	PMW_JFETV3_A -	109	4	
	PMW_JFETV4_A +	116	4	
		117		
	PMW_JFETV4_A -			
	PLW_JFETV1_A +	99		
	PLW_JFETV1_A + PLW_JFETV1_A -	99 100		
	PLW_JFETV1_A +	99		

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

**Issue:** 2.0

Date:	29-08-0
Page:	13 of 74

No:	Activity	Remarks/Results	Sign off
70	Measure and record the resistance of the inline resistors in the BOB prepared for CB312200 P06/J06. The measured resistance is to be $47\pm2.3~\Omega$	Contact number         Resistance           26         37           38         49           48         60           59         71           50         61           62         51           86         87           97         98           108         109           116         117           99         100           110         111	
	Grounding Check		
71	Remove SPIRE Safeing Plug Type-V from SVM-CB 312100 J04		
72	Remove SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06.		
73	Remove SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J04.		

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 14 of 74

No:	Activity	Remarks/Results	Sign off
74	Remove SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J03.		
75	Prepare a 128-way BOB and short contacts to remove charge		
76	Mate BOB to 312200 J06		
77	Verify FPU Isolation from OBA by measuring Pin 5 to Chassis: s.b. > 1 MOhm		
78	Verify Analogue Ground Isolation from OBA by measuring Pin 93 to Chassis: s.b. > 1 MOhm		
79	Demate BOB from 312200 J06		
80	Mate BOB to 312100 J04		
81	Verify FPU Isolation from OBA by measuring Pin 2 to Chassis: s.b. > 1 MOhm		
82	Verify Analogue Ground Isolation from OBA by measuring Pin 36 to Chassis: s.b. > 1 MOhm		
83	Demate BOB from 312100 J04		
84	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
85	Mate SPIRE Safeing Plug Type-VI to SVM-CB 312200 J06.		
86	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J04.		
87	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J03.		
	Subsystem harness mating		
88	Verify that CB 312300 J01 is mated with CB 312300 P01		
89	Verify that CB 312300 J02 is mated with CB 312300 P02		
90	Remove and store protective cover from CB 312300 P06		
91	Remove and store SPIRE Safeing Plug Type-VII from CB 312300 J06		
92	Mate CB 312300 P06 to 312300 J06		
93	Remove and store protective cover from CB 312300 P05		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 15 of 74

No:	Activity	Remarks/Results	Sign off
94	Remove and store SPIRE Safeing Plug Type-VII from CB 312300 J05		
95	Mate CB 312300 P05 to 312300 J05		
96	Remove and store protective cover from CB 312300 P04		
97	Remove and store SPIRE Safeing Plug Type-VIII from CB 312300 J04		
98	Mate CB 312300 P04 to 312300 J04		
99	Remove and store protective cover from CB 312300 P03		
100	Remove and store SPIRE Safeing Plug Type-VIII from CB 312300 J03		
101	Mate CB 312300 P03 to 312300 J03		
	Spectrometer Initial Mating		
102	Short the contacts of the BOB for 312200 J06/P06 to chassis to remove any charge		
103	Remove and store the protective cover from 312200 P06		
104	Mate the BOB prepared for 312200 J06/P06 to 312200 P06		
105	Demate and store the SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06		
106	Mate the inline BOB prepared for 312200 J06/P06 to 312200 J06		
107	Remove and store the protective cover from 312200 P05		
108	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J05		
109	Mate 312200 P05 to 312200 J05		
110	Mate 312100 P01A to J01A		
	Photometer Initial Mating		
	SIH-03		
111	Short the contacts of the BOB for 312100 J04/P04 to chassis to remove any charge		
112	Remove and store the protective cover from 312100 P04		

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 16 of 74

No:	Activity	Remarks/Results	Sign off
113	Mate the BOB prepared for 312100 J04/P04 to 312200 P04		
114	Demate the SPIRE Safeing Plug Type-V from SVM-CB 3122100 J04		
115	Mate the inline BOB prepared for 312100 J04/P04 to 312100 J04		
	SIH-04		
116	Remove and store the protective cover from 312100 P03		
117	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312100 J03		
118	Mate 312100 P03 to 312200 J03		
119	Mate 312100 P01B to J01B		
	SIH-05		
120	Remove and store the protective cover from 312100 P02		
121	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312100 J02		
122	Mate 312100 P02 to 312200 J02		
	SIH-06		
123	Remove and store the protective cover from 312200 P03		
124	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J03		
125	Mate 312200 P03 to 312200 J03		
	SIH-07		
126	Remove and store the protective cover from 312200 P04		
127	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J04		
128	Mate 312200 P04 to 312200 J04		
	SIH-08		
129	Remove and store the protective cover from 312200 P01		
130	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J01		



Ref: SPIRE-RAL-PRC-

002951 **Issue:** 2.0

PFM Final SIH Electrical Integration/Checkout Procedure

**Date:** 29-08-07 **Page:** 17 of 74

No:	Activity	Remarks/Results	Sign off
131	Mate 312200 P01 to 312200 J01		
	SIH-09		
132	Remove and store the protective cover from 312200 P02		
133	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J02		
134	Mate 312200 P02 to 312200 J02		
	Instrument switch-on (Phot. JFETs)		
135	Execute Procedure: SPIRE-FM-SFT-DPU-ON-P (§7.1, p. 38)	Nominal HK packets: Critical HK packets: THSK refresh: TM2N refresh: TM1N refresh: SPIRE/CCS time sync: SCOS/THSK/QLA sync:	
136	Execute Procedure: SPIRE-FM-SFT-DRCU-ON-P (§7.2, p. 40)	THSK stop: TM2N stop: THSK start: TM2N start: SCUP5V (~ $5.2 \pm 0.5$ V): SCUP9V (~ $9.0 \pm 0.2$ V): SCUM9V (~ $-9.0 \pm 0.2$ V): BIASP5V (~ $5.1 \pm 0.5$ V): BIASP9V (~ $9.0 \pm 0.2$ V): BIASM9V (~ $-9.0 \pm 0.2$ V):	
137	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-01-P (§7.3, p.41)	SCUFRAMECNT: TM5N:	

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 18 of 74

No:	Activity	Remarks/Results	Sign off
		SCUTEMPSTAT:	
		PUMPHTRTEMP:	
		PUMPHSTEMP:	
		EVAPHSTEMP:	
		SHUNTTEMP:	
		EMCFILTEMP:	
		SLOTEMP:	
	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-03-P (§7.4,	PLOTEMP:	
138	p.43)	OPTTEMP:	
	p. <del>4</del> 3)	BAFTEMP:	
		BSMIFTEMP:	
		SCAL2TEMP:	
		SCAL4TEMP:	
		SCALTEMP:	
		SMECIFTEMP:	
		SMECTEMP:	
		BSMTEMP:	
139	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-06-P (§7.5,	SUBKSTAT:	
139	p.45)	SUBKTEMP:	
	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-07-P (§7.6,	SPHSV:	
140	p.46)	EVHSV:	
		SPHTRV:	
141	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-04-P (§7.7,	PCALV:	
141	p. 47)	PCALCURR:	
		SCAL4CURR:	
142	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-05-P (§7.8,	SCAL4V:	
142	p.48)	SCAL2CURR:	
		SCAL2V:	

### Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 19 of 74

PFM Final SIH Electrical Integration/Checkout Procedure

No:	Activity	Remarks/Results	Sign off
143	Execute Procedure: SPIRE-FM-SFT-FUNC-MCU-01-P (§7.9, p. 49)	MCUBITSTAT: MCUP5V: MCUP14V: MCUM14V: MCUP15V: MCUM15V:	
		MCUMACTEMP: MCUSMECTEMP: MCUBSMTEMP:	
144	Execute Procedure: SPIRE-FM-SFT-FUNC-MCU-02-P (§7.10 p.50)	MCUFRAMECNT:	
145	Execute Procedure: SPIRE-FM-SFT-FUNC-BSM-01-P (§7.11 p.51)	CHOPSENSPWR: JIGGSENSPWR:	
146	Execute Procedure: SPIRE-FM-SFT-BSM-OFF (§7.12, p.52)	CHOPSENSPWR: JIGGSENSPWR:	
147	Execute Procedure: SPIRE-FM-SFT-FUNC-SMEC-01-P (§7.13, p.53)	SMECENCPWR: SMECLVDTPWR:	
148	Execute Procedure: SPIRE-FM-SFT-SMEC-OFF-P (§7.14, p.54)	SMECENCPWR: SMECLVDTPWR:	
149	Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-01-P (§7.15, p.55)	DCUFRAMECNT:	
150	Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P (§7.16, p.56)	PLIABITSTAT: PLIAP5V: PLIAP9V: PLIAM9V: LIAP1TEMP to LIAP9TEMP:	



Ref: SPIRE-RAL-PRC-

002951 **Issue:** 2.0

PFM Final SIH Electrical Integration/Checkout Procedure

**Date:** 29-08-07 **Page:** 20 of 74

No:	Activity	Remarks/Results	Sign off
151	Execute Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-01 (§7.17, p.57)	PSWJFETSTAT: PMLWJFETSTAT: PSWJFET1V: PSWJFET2V: PSWJFET3V: PSWJFET5V: PSWJFET6V: PSWJFET6V: PMWJFET1V: PMWJFET1V: PMWJFET2V: PMWJFET3V: PMWJFET4V: PLWJFET1V: PLWJFET1V:	
	Photometer and PTC Idd/Iss		

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

24 35

002951

Issue: 2.0 Date: 29-08-07 Page: 21 of 74

No:	Activity	Remarks/Results		Sign off
		Contact number	Voltage drop	
		26		
		37		
		38		
		49		
		48		
	60			
	59			
	71			
		50		
	Measure the voltage drop with a DVM across the inline	61		
		62		
	resistors in the BOB prepared for CB312100 P04/J04. The	51		
52	expected values should lie between 55 and 100mV	86		
		87		
	(DI W. DCW and DMW)	97		
	(PLW, PSW and PMW)	98		
		108		
		109		
		116		
		117		
		99		
		100		
		110		
		111		
	Measure the voltage drop with a DVM across the inline			
	resistors in the BOB prepared for CB312200 P06/J06. The	Contact number	Voltage drop	<del>-  </del>

Last printed: 21:42:26 04/09/2007

(PTC)

expected values should lie between 55 and 100mV

153

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 22 of 74

No:	Activity	Remarks/Results			Sign off
		Contact A	Contact B	Voltage Drop	
		26	42		
		37	54		11
		38	53		
		49	52		
		48	41		
		60	30		
		59	10		
		71	11		
		50	19		
		61	29		
		62	16		
	Measure the voltage drop along the cryoharness for the	51	27		
154	PMW/PSW/PLW arrays using the contacts form the BOB	86	7		
104		87	14		
	prepared for CB312100 P04/J04	97	24		
		98	35		
		108	23		
		109	34		
		116	33		
		117	45		
		99	70		
		100	81		
		110	69		
		111	80		
	Measure the voltage drop along the cryoharness for the PTC	Contact A	Contact B	Voltage Drop	٦ I
155	arrays using the contacts form the BOB prepared for	24	3		71
.00	CB312200 P06/J06	35	2		
	CD312200 F00/J00		1	ı	_



002951

Ref: SPIRE-RAL-PRC-

**Issue:** 2.0

**Date:** 29-08-07

PFM Final SIH Electrical Integration/Checkout Procedure **Page:** 23 of 74

No:	Activity	Remarks/Results	Sign off
156	Execute Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-02 (§7.18, p. 59)	PSWJFETSTAT: PMLWJFETSTAT: PSWJFET1V: PSWJFET2V: PSWJFET3V: PSWJFET5V: PSWJFET5V: PSWJFET6V: PMWJFET1V: PMWJFET1V: PMWJFET2V: PMWJFET2V: PMWJFET4V: PLWJFET1V: PLWJFET2V: TCJFETV:	

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 24 of 74

No:	Activity	Remarks/Results		Sign off
157	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312100 P04/J04. The expected values should lie between 55 and 100mV (PLW, PSW and PMW)	Contact number           26           37           38           49           48           60           59           71           50           61           62           51           86           87           97           98           108           109           116           117           99           100           110           111	Voltage drop	
158	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 55 and 100mV	Contact number  24  35	Voltage drop	
	(PTC)			

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 25 of 74

No:	Activity	Remarks/Results			Sign off
	· ·	Contact A	Contact B	Voltage Drop	
		26	42		71
		37	54		71
		38	53		
		49	52		71
		48	41		
		60	30		71
		59	10		
		71	11		
		50	19		71
		61	29		71
		62	16		71
	Measure the voltage drop along the cryoharness for the	51	27		7
159	PMW/PSW/PLW arrays using the contacts form the BOB	86	7		
133		87	14		7
	prepared for CB312100 P04/J04	97	24		
		98	35		71
		108	23		
		109	34		
		116	33		71
		117	45		71
		99	70		
		100	81		
		110	69		71
		111	80		71
			•	•	
	Measure the voltage drop along the cryoharness for the PTC	Contact A	Contact B	Voltage Drop	7
160	arrays using the contacts form the BOB prepared for	24	3		<b>1</b> 1
.00	CB312200 P06/J06	35	2		11

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 26 of 74

Activity	Remarks/Results	Sign off
	PSWJFETSTAT:	
	PMLWJFETSTAT:	
	PSWJFET1V:	
	PSWJFET2V:	
	PSWJFET3V:	
	PSWJFET4V:	
Evacuta Dragadura: SDIDE EM SET DUOT IEET OEE	PSWJFET5V:	
	PSWJFET6V:	
(37.19, p. 61)	PMWJFET1V:	
	PMWJFET2V:	
	PMWJFET3V:	
	PMWJFET4V:	
	PLWJFET1V:	
	PLWJFET2V:	
	TCJFETV:	
	PLIABITSTAT:	
Evacuta Dragadura: SDIDE EM SET DI IA OEE D (\$7.20)	PLIAP5V:	
<u> </u>	PLIAP9V:	
p.03)	PLIAM9V:	
	LIAP1TEMP to LIAP9TEMP:	
	SLIABITSTAT:	
Evacuta Dragadura: SDIDE EM SET EUNC DOU 04 SDEC D	SLIAP5V:	
	SLIAP9V:	
(§7.21, p. 04)	SLIAM9V:	
	LIAS1TEMP to LIAS3TEMP:	
Measure Spect. Idd/Iss		
	SPECJFETSTAT:	
Evacuta Procedura: SDIDE EM SET SDEC IEET ON 01	SSWJFET1V:	
(§7.22, p. 65)	SSWJFET2V:	
	SLWJFET1V:	
	Execute Procedure: SPIRE-FM-SFT-PHOT-JFET-OFF (§7.19, p. 61)  Execute Procedure: SPIRE-FM-SFT-PLIA-OFF-P (§7.20, p.63)  Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P (§7.21, p. 64)  Measure Spect. Idd/Iss  Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-01	PSWJFETSTAT: PMLWIFETSTAT: PSWJFETIV: PSWJFETIV: PSWJFET3V: PSWJFET3V: PSWJFET4V: PSWJFET5V: PSWJFET5V: PSWJFET5V: PSWJFET5V: PSWJFET6V: PSWJFET5V: PSWJFET1V: PSWJFET1V: PMWJFET1V: PMWJFET1V: PMWJFET2V: PMWJFET2V: PMWJFETAV: PLWJFET1V: PLWJFET1V: PLJABITSTAT: PLIABITSTAT: PLIAP5V: PLIAP9V: PLIAP9V: PLIAP9V: LIAP1TEMP to LIAP9TEMP: SLIAP5V: SLIAP9V: SLIAPPV: SLIAPPV: SLIAPPV: SLIAPPV: SLIAPPV: SLIAPPV: SSWJFET1V: SSWJFET1V: SSWJFET1V: SSWJFET1V: SSWJFET1V:

## Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07

**Page:** 27 of 74

No:	Activity	Remarks/Results			Sign off
165	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 25 and 50mV for contacts 91, 92, 103 and 113 and between 55 and 100mV for contacts 57, 68, 70 and 81	Function  92  91  103  113  68  57  70  81		Voltage drop	
166	Measure the voltage drop with a DVM between the contacts indicated on the BOB prepared for CB312200 P06/J06.	Contact A  92  91  103  113  68  57  70  81	Contact B  31  43  42  54  19  29  53  52	Voltage Drop	
167	Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-02 (§7.23, p. 66)	SPECJFETSTAT: SSWJFET1V: SSWJFET2V: SLWJFET1V:			

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 28 of 74

No:	Activity	Remarks/Results			Sign off
168	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 25 and 50mV for contacts 91, 92, 103 and 113 and between 55 and 100mV for contacts 57, 68, 70 and 81	Function  92  91  103  113  68  57  70  81		Voltage drop	
169	Measure the voltage drop with a DVM between the contacts indicated on the BOB prepared for CB312200 P06/J06.	Contact A  92  91  103  113  68  57  70  81	Contact B  31  43  42  54  19  29  53  52	Voltage Drop	
170	Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-OFF (§7.24, p. 67)	SPECJFETSTAT: SSWJFET1V: SSWJFET2V: SLWJFET1V:			
171	Execute Procedure: SPIRE-FM-SFT-SLIA-OFF-P (§7.25, p.69)	SLIABITSTAT SLIAP5V SLIAP9V SLIAM9V			
172	Execute Procedure SPIRE-FM-SFT-MCU-OFF-P, (§7.26, p.70)	MCUBITSTAT			



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

**Issue:** 2.0 **Date:** 29-08-07

**Page:** 29 of 74

No:	Activity	Remarks/Results	Sign off
173	Execute Procedure SPIRE-FM-SFT-SCU-OFF-P (§7.27, p. 71)	SCUTEMPSTAT	
173		SUBKSTAT	
174	Execute Procedure: SPIRE-FM-SFT-DRCU-OFF-P (§7.28,	THSK:	
174	p.72)	TM2N:	
175	Execute Procedure SPIRE-FM-SFT-DPU-OFF-P, (§7.29,		
175	p.73)		
176	Carry out near real time analysis of the data to verify that:		
170	0% < (Idd-Iss) / Idd < 8%		
	<b>Final Spectrometer Connection</b>		
177	Demate the 128-way BOB from CB 312200 P06		
178	Demate the 128-way BOB from CB 312200 J06		
179	Mate CB 312200 J06/P06		
180	<b>Final Photometer Connection</b>		
181	Demate the 128-way BOB from CB 312100 P04		
182	Demate the 128-way BOB from CB 312100 J04		
183	Mate CB 312100 J04/P04		
184	End of procedure		



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 30 of 74

#### 5. DE-MATING OF SIH-IS AND SIH-SS FOR LPU INTEGRATION

#### 5.1 Prerequisites

1. The procedure outlined in §4 of this procedure has been completed.

#### 5.2 End State

The SIH is broken at the SVM-CB
The FPU is protected from ESD damage by the safeing plugs on SVM-CB connectors
The SPIRE SVM panel may be opened

#### 5.3 Notes

1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream for > 30 sec to discharge the harness.



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 31 of 74

#### **5.4 Detailed Procedure**

No:	Activity	Remarks/Results	Sign off
	De-mating of SIH-IS and SIH-SS		
	SIH-03		
1	Demate 312100 P04		
2	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
3	Cover 312100 P04 with ESD dust cover		
	SIH-01		
4	Demate 312200 P06		
5	Mate SPIRE Safeing Plug Type-VI to SVM-CB 312200 J06		
6	Cover 312200 P06 with ESD dust cover		
	SIH-11		
7	Demate 312300 P04		
8	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J04		
9	Cover 312300 P04 with ESD dust cover		
10	Demate 312300 P01		
11	Cover 312300 P01 with ESD dust cover		
12	SIH-13		
13	Demate 312300 P03		
14	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J03		
15	Cover 312300 P03 with ESD dust cover		
16	Demate 312300 P02		
17	Cover 312300 P02 with ESD dust cover		
18	SIH-02		
19	Demate 312200 P05		
20	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J05		
21	Cover 312200 P05 with ESD dust cover		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 32 of 74

No:	Activity	Remarks/Results	Sign off
22	Demate 312100 P01A		
23	Cover 312100 P01A with ESD dust cover		
24	SIH-04		
25	Demate 312100 P01B		
26	Cover 312100 P01B with ESD dust cover		
27	Demate 312100 P03		
28	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312100 J03		
29	Cover 312100 P03 with ESD dust cover		
30	SIH-05		
31	Demate 312100 P02		
32	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312100 J02		
33	Cover 312100 P02 with ESD dust cover		
34	SIH-06		
35	Demate 3121200 P03		
36	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J03		
37	Cover 312200 P03 with ESD dust cover		
38	SIH-07		
39	Demate 3121200 P04		
40	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J04		
41	Cover 312200 P04 with ESD dust cover		
42	SIH-08		
43	Demate 3121200 P01		
44	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J01		
45	Cover 312200 P01 with ESD dust cover		
46	SIH-09		
47	Demate 3121200 P02		
48	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J02		
49	Cover 312200 P02 with ESD dust cover		
50	SIH-10		



Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0

PFM Final SIH Electrical Integration/Checkout Procedure	Date:	29-08-07
-	Page:	33 of 74

No:	Activity	Remarks/Results	Sign off
51	Demate 3121300 P06		
52	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312300 J06		
53	Cover 312300 P06 with ESD dust cover		
54	SIH-12		
55	Demate 3121300 P05		
56	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312300 J05		
57	Cover 312300 P05 with ESD dust cover		
	End of procedure		

#### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 34 of 74

#### 6. MATING OF SIH-IS AND SIH-SS AFTER LPU INTEGRATION

#### 6.1 Prerequisites

- 1. The DCU, FCU and DPU have been mechanically and electrically integrated to the SVM panel and the SIH-SS-XX harnesses are all integrated but not mated to the SVM-CB
- 2. The SIH-CS harnesses have been mated to the SPIRE FPU + JFP/JFS
- 3. The SPIRE SVM panel has been closed
- 4. The PLM has been mechanically integrated to the SVM
- 5. The SIH-IS-XX harnesses are mechanically integrated onto the outside of the cryostat.
  - a. They are mated at the CVV-CB
  - b. They are mechanically integrated to the SVM-CB with the designated ESD safeing plugs
- 6. The LPU Integration has been successfully completed

#### 6.2 Notes

1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream for > 30 sec to discharge the harness.



PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 35 of 74

#### **6.3 Detailed Procedure**

No:	Activity	Remarks/Results	Sign off
	Mating of SIH-SS to SIH-IS		
1	SIH-12		
2	Remove ESD dust cover from 312300 P05		
3	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312300 J05		
4	Mate 312300 J05 to P05		
5	SIH-10		
6	Remove ESD dust cover from 3121300 P06		
7	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312300 J06		
8	Mate 312300 J06 to P06		
9	SIH-11		
10	Remove ESD dust cover from 312300 P04		
11	Demate SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J04		
12	Mate 312300 P04 to J04		
13	Remove ESD dust cover from 312300 P01		
14	Mate 312300 P01 to J01		
15	SIH-13		
16	Remove ESD dust cover from 312300 P03		
17	Demate SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J03		
18	Mate 312300 P03 to J03		
19	Remove ESD dust cover from 312300 P02		
20	Mate 312300 P02 to J01		
21	SIH-04		
22	Remove ESD dust cover from 312100 P01B		
23	Mate 312100 P01B to J01B		

### Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 36 of 74

No:	Activity	Remarks/Results	Sign off
24	Remove ESD dust cover from 312100 P03		
25	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312100 J03		
26	Mate 312100 P03 to J03		
27	SIH-02		
28	Remove ESD dust cover from 312200 P05		
29	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J05		
30	Mate 312200 P05 to J05		
31	Remove ESD dust cover from 312100 P01A		
32	Mate 312100 P01A to J01A		
33	SIH-01		
34	Remove ESD dust cover from 312200 P06		
35	Demate SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06		
36	Mate 312200 P06 to J06		
37	SIH-05		
38	Remove ESD dust cover from 312100 P02		
39	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312100 J02		
40	Mate 312100 P02 to J02		
41	SIH-06		
42	Remove ESD dust cover from 3121200 P03		
43	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J03		
44	Mate 312200 P03 to J03		
45	SIH-07		
46	Remove ESD dust cover from 3121200 P04		
47	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J04		
48	Mate 312200 P04 to J04		
49	SIH-08		
50	Remove ESD dust cover from 3121200 P01		
51	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J01		
52	Mate 312200 P01 to J01		



# Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

**Issue:** 2.0 **Date:** 29-08-07

**Page:** 37 of 74

No:	Activity	Remarks/Results	Sign off
53	SIH-09		
54	Remove ESD dust cover from 3121200 P02		
55	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J02		
56	Mate 312200 P02 to J02		
57	SIH-03		
58	Demate 312100 P04		
59	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
60	Mate 312100 P04 to J04		
61	End of procedure		

### **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 38 of 74

# 7. APPENDICES

#### 7.1 Procedure SPIRE-FM-SFT-DPU-ON-P

Version	2.3		
Date	28 Aug 2007		
Purpose	To switch on the SPIRE DPU PRIME and start generating housekeeping		
Initial configuration	SPIRE DPU and DRCU PRIME are switched off		
Final configuration	SPIRE DPU PRIME is ON and SPIRE HK is being produced, SPIRE DRCU		
	PRIME is OFF		
Preconditions	• SPIRE FM DPU is electrically integrated with the Herschel Satellite		
	SPIRE MIB PRIME is imported in the CCS database.		
	CCS is up and running		
	<ul> <li>FUNCTIONAL TEST PARAMETERS display is selected on the CCS</li> </ul>		
Duration	5 minutes		
Pass/Fail Criteria	Nominal and critical HK reports start being generated at their nominal rates of		
	1Hz and 0.5Hz respectively.		

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/ Fail
1	Select DPU AND OBS PARAMETERS display is on the CCS	_		_	
2	Power ON the SPIRE DPU PRIME unit using the dedicated spacecraft LCL line and configure 1553 Spacecraft bus for SPIRE DPU PRIME (RT = 21)	_	_	_	
3	Wait for the boot software to produce at least 2 event packets (5,1)				
4	Execute TCL script SPIRE-FM-SFT-DPU-START-P-SP.tcl	_	_	_	
5	Check that Nominal and Critical HK packets are arriving at the CCS:  SPIRE Nominal HK:  • (type ,subtype) : (3,25)  • APID : 0x502  SPIRE Critical HK:  • (type ,subtype) : (3,25)  • APID: 0x500				
6	Check that THSK parameter is refreshing every second	THSK	Refreshing @ 1 Hz	_	
7	Check that TM2N parameter is incrementing by 1 every second	TM2N	Incrementing by 1 @ 1Hz	_	



### **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 39 of 74

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/ Fail
8	Check that TM1N parameter is incrementing by 1 every 2 second	TM1N	Incrementing by 1 @ 0.5Hz		
9	On CCS check the consistency of the SPIRE on board time to the HCDMU time and the CCS. *	_			
10	On IEGSE check the consistency between SCOS time and THSK and QLA time.	THSK	Incrementing once per second		
Test 1	Result (Pass/Fail):		•		•

<sup>\*</sup> Assuming that OBT is provided by the HCDMU is TAI, there should be a 33 second difference between OBS and CCS time (assuming CCS is using UTC). In the case the HCDMU is using UTC to specify the on board time, there should be no difference between THSK and the CCS/IEGSE system time.

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

**Issue:** 2.0 29-08-07 Date: Page: 40 of 74

#### 7.2 Procedure SPIRE-FM-SFT-DRCU-ON-P

Version	2.2		
Date	2 <sup>nd</sup> January 2007		
Purpose	To switch on the SPIRE DRCU PRIME and start generating housekeeping		
Initial configuration	SPIRE DPU PRIME is ON and DRCU PRIME is switched OFF		
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
Preconditions	SPIRE FM DRCU is electrically integrated with the Herschel Satellite		
	SPIRE DRCU is switched OFF		
	SPIRE MIB PRIME is imported in the CCS database.		
	CCS is up and running		
	<ul> <li>FUNCTIONAL TEST PARAMETERS display is selected on the CCS</li> </ul>		
Duration	5 minutes		
Pass/Fail Criteria	DRCU voltages show expected 'ON' values		

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-DRCU-START-P-STEP1.tcl		_	_	
2	Check that THSK parameter is not refreshing anymore	THSK	Not refreshing	_	
3	Check that TM2N parameter is not incrementing anymore	TM2N	Not incrementing		
4	Power ON the SPIRE DRCU PRIME unit using the dedicated spacecraft LCL line.	_		_	
5	Execute TCL script SPIRE- FM-SFT-DRCU-START- P-STEP2.tcl	_	_	_	
6	Check that THSK parameter is again refreshing every second	THSK	Refreshing @ 1Hz		
7	Check that TM2N parameter is again incrementing every second	TM2N	Incrementing by 1 @ 1Hz	_	
8	Check that the SCU/DCU voltages show nominal values	SCUP5V SCUP9V SCUM9V BIASP5V BIASP9V BIASM9V	$ \sim 5.2 \pm 0.5V  \sim 9.0 \pm 0.2V  \sim -9.0 \pm 0.2V  \sim 5.1 \pm 0.5V  \sim 9.0 \pm 0.2V  \sim -9.0 \pm 0.2V $		
Test F	Result (Pass/Fail): nted: 21:42:26 04/09/2007		l		

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 41 of 74

#### 7.3 Procedure SPIRE-FM-SFT-FUNC-SCU-01-P

Version	2.2		
Date	2 <sup>nd</sup> January 2007		
Purpose	SCU science packet generation check		
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
Final configuration	Unchanged		
Constraints	SPIRE DRCU PRIME is switched ON		
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>		
	CCS is up and running		
	SFT PARAMETERS display is selected on the CCS		
Duration	on 5 minutes		
Pass/Fail Criteria	Specified SCU HK parameters show expected increment.		

### **Procedure Steps:**

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-01-P.tcl	SCUFRAMECNT TM5N	0/31 0x3FFF/1		
Test I	Test Result (Pass/Fail):				

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 42 of 74

#### 7.4 Procedure SPIRE-FM-SFT-FUNC-SCU-03-P

Version	2.2		
Date	2 <sup>nd</sup> January 2007		
Purpose	SCU DC thermometry check		
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and		
	DC thermometry is ON		
Constraints	• SPIRE DRCU PRIME is switched ON		
	SPIRE MIB PRIME is imported in the CCS database.		
	CCS is up and running		
	SFT PARAMETERS display is selected on the CCS		
Duration	5 minutes		
Pass/Fail Criteria	a DC Thermometry channels show temperature readings according to the actual		
	instrument temperature*		
	*: At warm temperatures all channels should show short circuit RAW readings		
	of -32768		

### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-03-P.tcl		_		_
2	Wait for the parameter BBFULLTYPE to get set to SCU_DC_Therm				
3	A few seconds later record the value of parameter SCUTEMPSTAT	SCUTEMPSTAT	0/FFFF/FFF		
5	If the instrument is warm, record the values of SCU DC thermometry channels. Nominal values should show a short circuit status (or RAW -32768)	PUMPHTRTEMP PUMPHSTEMP EVAPHSTEMP SHUNTTEMP EMCFILTEMP SLOTEMP PLOTEMP	— — — — — —		
	Non Nominal (Open Circuit Criterion): RAW reading in the range [0, -100]	OPTTEMP BAFTEMP BSMIFTEMP SCAL2TEMP SCAL4TEMP SCALTEMP SMECIFTEMP	— — — — — —		



# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 43 of 74

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure	
		SMECTEMP	_			
		BSMTEMP	_			
Test I	Test Result (Pass/Fail):					

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: 44 of 74 Page:

#### 7.5 Procedure SPIRE-FM-SFT-FUNC-SCU-06-P

Version	2.2		
Date	2 <sup>nd</sup> January 2007		
Purpose	SCU AC thermometry check		
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and		
	DC thermometry is ON		
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and		
	AC/DC thermometry is ON		
Constraints	• SPIRE DRCU PRIME is switched ON		
	• SPIRE MIB PRIME is imported in the CCS database.		
	• CCS is up and running		
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>		
Duration	5 minutes		
Pass/Fail Criteria	AC Thermometry channel shows temperature readings according to the actual		
	instrument temperature		

#### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-06-P.tcl			_	_
2	Wait for the parameter BBFULLTYPE to get set to SCU_AC_Therm				
3	A few seconds later record the value of parameter SUBKSTAT	SUBKSTAT	0/1/1		
4	If the instrument is warm, only record the values of SCU AC thermometry channel if it indicates an open circuit.  Open Circuit Criterion: RAW reading in the range [0, -100]	SUBKTEMP			
Test R	Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 45 of 74

#### 7.6 Procedure SPIRE-FM-SFT-FUNC-SCU-07-P

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	Sorption Cooler Heater Check	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	DC thermometry is ON	
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON	
Constraints	Constraints • SPIRE DRCU PRIME is switched ON	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail Criteria	Sorption cooler heat switches and pump heater show expected voltages	

#### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM- SFT-FUNC-SCU-07-P.tcl	_	_	_	_
2	Wait for the parameter BBFULLTYPE to get set to Cooler_Htr_Chk	BBFULLTYPE	Cooler_Htr_C hk		
3	Record the value of parameter SPHSV – the Sorption Pump Heat Switch Voltage.  This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.	SPHSV - mV	0/~323/0		
4	Record the value of parameter EVHSV – the Evaporator Heat Switch Voltage.  This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.	EVHSV - mV	0/~323/0		
5	Record the value of parameter SPHTRV – the Sorption Pump Heater Voltage.  This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.	SPHTRV - V	0/~8.8/0		
Test 1	Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 46 of 74

#### 7.7 Procedure SPIRE-FM-SFT-FUNC-SCU-04-P

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	Photometer Calibration Check (PRIME)	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON	
Final configuration	Unchanged	
Constraints	SPIRE DRCU PRIME is switched ON	
	SPIRE MIB PRIME is imported in the CCS database.	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail Criteria	PCAL voltage and current agree with expected values	

### **Procedure Steps:**

Step	Description	Parameter Name - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-04-P.tcl  The expected values during the test should be monitored when parameter BBFULLTYPE in the SFT PARAMETERS display is set to PCAL_Check This usually happens about 30 seconds from the start of test execution.	PCALCURR - mA PCALV – V  BBFULLTYPE	0.0/0.1/0.0 0.0/0.026/0.0 PCAL_Check		
Test I	Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 47 of 74

#### 7.8 Procedure SPIRE-FM-SFT-FUNC-SCU-05-P

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	Spectrometer Calibration Check (PRIME)	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON	
Final configuration	Unchanged	
Constraints	SPIRE DRCU PRIME is switched ON	
	SPIRE MIB PRIME is imported in the CCS database.	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail criteria	SCAL2 and SCAL4 voltage and currents agree with expected values	

#### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-05-P.tcl	_	_	_	
2	Wait for the parameter BBFULLTYPE to get set to SCAL4_Check	BBFULLTYPE	SCAL4_Chec k		
3	A few seconds later record the value of parameters SCAL4CURR and SCAL4V These parameters are set back to 0 after ~30 seconds	SCAL4CURR – mA SCAL4V – V	0.0/0.10/0.0 0.0/0.05/0.0		
4	Wait for the parameter BBFULLTYPE to get set to SCAL2_Check	BBFULLTYPE	SCAL2_Chec k		
5	A few seconds later record the values of parameters SCAL2CURR and SCAL2V These parameters are set back to 0 after ~30 seconds	SCAL2CURR – mA SCAL2V – V	0.0/0.10/0.0 0.0/0.05/0.0		
Test F	Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 48 of 74

#### 7.9 Procedure SPIRE-FM-SFT-FUNC-MCU-01-P

Version	2.3	
Date	28 <sup>th</sup> August 2007	
Purpose	MCU (PRIME) Boot Check	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON	
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted.	
Constraints	Constraints • SPIRE DRCU PRIME is switched ON	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail criteria	MCU voltages and board temperatures show expected 'ON' values	

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-MCU-01-P.tcl				
2	Check that the MCU is booted up successfully	MCUBITSTAT	0/1/1		
3	Check MCU HK parameter values and ensure that the values are refreshing	MCUP5V MCUP14V MCUM14V MCUP15V MCUM15V  MCUMACTEMP MCUSMECTEMP MCUBSMTEMP	~ 5.0 ± 0.2V ~ 14.0 ± 0.5V ~ -14.0 ± 0.5V ~ 15.0 ± 0.5V ~ -15.0 ± 0.7V ~300K ~300K ~300K		

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 49 of 74

#### 7.10 Procedure: SPIRE-FM-SFT-FUNC-MCU-02-P

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	MCU Nominal Frame Generation Check	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted.	
Final configuration	Unchanged.	
Constraints	SPIRE DRCU PRIME is switched ON	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	CCS is up and running	
	SFT PARAMETERS display is selected on the CCS	
Duration	5 minutes	
Pass/Fail criteria	5 minutes Specified MCU HK parameters show expected increment	

#### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-MCU-02-P.tcl	MCUFRAMECNT	<b>FM</b> : 0/297		_
Test 1	Test Result (Pass/Fail):				

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 50 of 74

#### 7.11 Procedure SPIRE-FM-SFT-FUNC-BSM-01-P

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	BSM (PRIME) Chop/Jiggle Sensor Check.	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted.	
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle	
	sensors are ON.	
Constraints	SPIRE DRCU PRIME is switched ON	
	SPIRE MCU PRIME is booted.	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	• CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutess	
Pass/Fail criteria	HK Parameters CHOPSENSPWR and JIGGSENSPWR show expected ON	
	values.	

### **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM- SFT-FUNC-BSM-01-P.tcl	_		_	
2	Check that the Chop and Jiggle sensors have switched on	CHOPSENSPWR JIGGSENSPWR	0/1/1 0/1/1		
Test I	Test Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 51 of 74

#### 7.12 Procedure SPIRE-FM-SFT-BSM-OFF

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	BSM (PRIME) Switch OFF	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle	
	sensors are ON.	
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle	
	sensors are OFF.	
Constraints	Constraints • SPIRE DRCU PRIME is switched ON	
	• SPIRE MCU PRIME is booted.	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail criteria	HK Parameters CHOPSENSPWR and JIGGSENSPWR show expected OFF	
	values.	

#### **Procedure Steps:**

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure	
1	Execute SPIRE-FM-SFT-BSM-OFF-P.tcl	_		_	_	
2	Check that the power to the BSM sensors is switched off	CHOPSENSPWR JIGGSENSPWR	1/-/0 1/-/0			
Test I	Test Result (Pass/Fail):					

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 52 of 74

#### 7.13 Procedure SPIRE-FM-SFT-FUNC-SMEC-01-P

Version	2.3
Date	28 <sup>th</sup> August 2007
Purpose	SMEC (PRIME) Encoder/LVDT Sensor Check.
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and
	LVDT are ON.
Constraints • SPIRE DRCU PRIME is switched ON	
SPIRE MCU PRIME is booted.	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	CCS is up and running
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>
Duration	5 minutes
Pass/Fail criteria	HK Parameters SMECENCPWR and SMECLVDTPWR show expected ON
	values.

### **Procedure Steps:**

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM- SFT-FUNC-SMEC-01-P.tcl	_	_		_
2	Check that power to the SMEC LED and LVDT sensor is on	SMECENCPWR	0/-/1		
		SMECLVDTPWR	0/1/1		

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 53 of 74

#### 7.14 Procedure SPIRE-FM-SFT-SMEC-OFF-P

Version	2.3	
Date	28 <sup>th</sup> August 2007	
Purpose	SMEC (PRIME) Switch OFF	
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and	
	LVDT are ON.	
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and	
	AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and	
	LVDT are OFF.	
Constraints	straints • SPIRE DRCU PRIME is switched ON	
	• SPIRE MCU PRIME is booted.	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>	
	CCS is up and running	
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>	
Duration	5 minutes	
Pass/Fail criteria	HK Parameters SMECENCPWR and SMECLVDTPWR show expected OFF	
	values.	

#### **Procedure Steps:**

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute SPIRE-FM-SFT-SMEC-OFF-P.tcl	_	_	_	_
2	Check that the power to the SMEC sensors is switched off	SMECENCPWR	1/-/0		
		SMECLVDTPWR	1/-/0		
Test Result (Pass/Fail):					

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 54 of 74

#### 7.15 Procedure SPIRE-FM-SFT-FUNC-DCU-01-P

Version	2.2
Date	2 <sup>nd</sup> January 2007
Purpose	DCU science packet generation check for all Photometer and Spectrometer packet types (PF, PSW, PMW, PLW, SF, SSW and SLW)
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	Unchanged
Constraints • SPIRE DRCU PRIME is switched ON	
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	CCS is up and running
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>
Duration	5 minutes
Pass/Fail criteria	Specified DCU HK parameter shows expected increment

### **Procedure Steps:**

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-DCU-01-P.tcl	DCUFRAMECNT	0/700		
Test I	Test Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 55 of 74

#### 7.16 Procedure: SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P

Version	2.3
Date	28 <sup>th</sup> August 2007
Purpose	Photometer LIAs PRIME Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are
	ON
Constraints • SPIRE DRCU PRIME is switched ON	
	Photometer LIAs are OFF
SPIRE MIB PRIME is imported in the CCS database.	
^	
	CCS is up and running
	•
	CCS is up and running
Duration	<ul> <li>CCS is up and running</li> <li>DCU PARAMETERS &amp; SFT PARAMETERS displays are selected on the CCS</li> </ul>

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P.tcl	PLIABITSTAT	0/1/1		
2	Check Photometer LIA HK parameter values and ensure that the values are refreshing	PLIAP5V PLIAP9V PLIAM9V	$-/5.2 \pm 0.2V$ $-/11.5 \pm 0.5V$ $-/-11.5 \pm 0.5V$		
3	On the DCU PARAMETERS display check that the LIA temperatures are slowly warming up.  At switch-on it is possible that some of the LIA temperatures will be in soft or even hard limits. No action is required.	LIAP1TEMP to LIAP9TEMP	~ 290-300 K		
4	Wait for ~3 minutes before continuing with the SFTs	_	_	_	_

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 56 of 74

#### 7.17 Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-01

Version	1.0			
Date	29 <sup>th</sup> August 2007			
Purpose	Photometer JFETs Switch On			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Photometer LIAs are ON			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Photometer LIAs are ON			
	Photometer JFETs are ON			
Constraints	SPIRE DRCU PRIME is switched ON			
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>			
	CCS is up and running			
	<ul> <li>DCU PARAMETERS display is selected on the CCS</li> </ul>			
Duration	5 minutes			
Pass/Fail criteria	Photometer JFET HK parameters show expected ON values			

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-ON.tcl  Wait for the script to finish executing before proceeding with the next step	_	_	_	_

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 57 of 74

Step	Description	Parameter	Expected	Actual	Success/
			Values	Values	Failure
			Before/	Before	
			After	/After	
2	On the DCU PARAMETERS	PSWJFETSTAT	0x3F		
	display check the JFET HK	<b>PMLWJFETSTAT</b>	0x7F		
	parameters				
	_	PSWJFET1V	$-1.49 \pm 0.1 \text{ V}$		
		PSWJFET2V	$-1.49 \pm 0.1 \text{ V}$		
		PSWJFET3V	$-1.49 \pm 0.1 \text{ V}$		
		PSWJFET4V	$-1.49 \pm 0.1 \text{ V}$		
		PSWJFET5V	$-1.49 \pm 0.1 \text{ V}$		
		PSWJFET6V	$-1.49 \pm 0.1 \text{ V}$		
		PMWJFET1V	$-1.49 \pm 0.1 \text{ V}$		
		PMWJFET2V	$-1.49 \pm 0.1 \text{ V}$		
		PMWJFET3V	$-1.49 \pm 0.1 \text{ V}$		
		PMWJFET4V	$-1.49 \pm 0.1 \text{ V}$		
		PLWJFET1V	$-1.49 \pm 0.1 \text{ V}$		
		PLWJFET2V	$-1.49 \pm 0.1 \text{ V}$		
		TCJFETV	$-1.49 \pm 0.1 \text{ V}$		
	<b>Check with Instrument Team</b>				
	before proceeding with the next				
	test.				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

**Issue:** 2.0 29-08-07 Date: Page: 58 of 74

#### 7.18 Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-02

Version	1.0
Date	29 <sup>th</sup> August 2007
Purpose	Photometer JFETs Switch On
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
	AC/DC thermometry is ON
	MCU PRIME is booted
	Photometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
	AC/DC thermometry is ON
	MCU PRIME is booted
	Photometer LIAs are ON
	Photometer JFETs are ON
Constraints	SPIRE DRCU PRIME is switched ON
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	• CCS is up and running
	DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Photometer JFET HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-ON.tcl  Wait for the script to finish executing before proceeding with the next step	_	_	_	_

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 59 of 74

Step	Description	Parameter	Expected	Actual	Success/
_	-		Values	Values	Failure
			Before/	Before	
			After	/After	
2	On the DCU PARAMETERS	PSWJFETSTAT	0x3F		
	display check the JFET HK	PMLWJFETSTAT	0x7F		
	parameters				
		PSWJFET1V	$-1.68 \pm 0.02 \text{ V}$		
		PSWJFET2V	$-1.59 \pm 0.02 \text{ V}$		
		PSWJFET3V	$-1.59 \pm 0.02 \text{ V}$		
		PSWJFET4V	$-1.68 \pm 0.02 \text{ V}$		
		PSWJFET5V	$-1.78 \pm 0.02 \text{ V}$		
		PSWJFET6V	$-1.68 \pm 0.02 \text{ V}$		
		PMWJFET1V	$-1.68 \pm 0.02 \text{ V}$		
		PMWJFET2V	$-1.88 \pm 0.02 \text{ V}$		
		PMWJFET3V	$-1.59 \pm 0.02 \text{ V}$		
		PMWJFET4V	$-1.88 \pm 0.02 \text{ V}$		
		PLWJFET1V	$-1.78 \pm 0.02 \text{ V}$		
		PLWJFET2V	$-1.59 \pm 0.02 \text{ V}$		
		TCJFETV	$-1.49 \pm 0.02 \text{ V}$		
	<b>Check with Instrument Team</b>				
	before proceeding with the next				
	test.				
Test F	Result (Pass/Fail):				

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 60 of 74

#### 7.19 Procedure: SPIRE-FM-SFT-PHOT-JFET-OFF

Version	1.0
Date	29 <sup>th</sup> August 2007
Purpose	Photometer JFETs Switch Off
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
	AC/DC thermometry is ON
	MCU PRIME is booted
	Photometer LIAs are ON
	Photometer JFETs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
	AC/DC thermometry is ON
	MCU PRIME is booted
	Photometer LIAs are ON
	Photometer JFETs are OFF
Constraints	SPIRE DRCU PRIME is switched ON
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	• CCS is up and running
	DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Photometer JFET HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-OFF.tcl  Wait for the script to finish executing before proceeding with the next step				

# **Procedure**

Ref: SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 61 of 74

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
2	On the DCU PARAMETERS display check the JFET HK parameters	PSWJFETSTAT PMLWJFETSTAT  PSWJFET1V PSWJFET2V PSWJFET3V PSWJFET5V PSWJFET5V PSWJFET6V  PMWJFET1V PMWJFET2V PMWJFET3V PMWJFET4V  PLWJFET1V PLWJFET1V	0 0 0 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V	Alter	
Tast I	Check with Instrument Team before proceeding with the next test.  Result (Pass/Fail):	TCJFETV	0.0 V		

# **Procedure**

**Ref:** SPIRE-RAL-PRC-

002951

2.0 **Issue:** 29-08-07 Date: Page: 62 of 74

#### 7.20 Procedure: SPIRE-FM-SFT-PLIA-OFF-P

Version	2.2
Date	2 <sup>nd</sup> January 2007
Purpose	Photometer LIAs PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are
	ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and
	AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are
	OFF
Constraints	SPIRE DRCU PRIME is switched ON
	Photometer LIAs are ON
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	CCS is up and running
	SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Specified Photometer LIA HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PLIA-OFF-P.tcl	PLIABITSTAT	1/-/0		
2	Check Photometer LIA HK parameter values	PLIAP5V PLIAP9V PLIAM9V	$5.2 \pm 0.2$ V/- $11.5 \pm 0.5$ V/- $-11.5 \pm 0.5$ V/-		
Test I	Result (Pass/Fail):				

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 63 of 74

#### 7.21 Procedure: SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P

Version	2.3
Date	28 <sup>th</sup> August 2007
Purpose	Spectrometer LIAs PRIME Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer LIAs are ON
Constraints	<ul> <li>SPIRE DRCU PRIME is switched ON</li> <li>Spectrometer LIAs are OFF</li> <li>SPIRE MIB PRIME is imported in the CCS database.</li> <li>CCS is up and running</li> <li>SFT PARAMETERS &amp; DCU PARAMETERS displays are selected on the CCS</li> </ul>
Duration	5 minutes
Pass/Fail criteria	Specified Spectrometer LIA HK parameters show expected ON values

#### **Procedure Steps for FM:**

Execute TCL script SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P.tcl Check Spectrometer LIA HK	SLIABITSTAT	0/1/1		
Check Spectrometer LIA HK				
parameter values and ensure that the values are refreshing	SLIAP5V SLIAP9V SLIAM9V	$\begin{array}{c} \text{-/} 5.2 \pm 0.2 V \\ \text{-/} 11.5 \pm 0.5 V \\ \text{-/-} 11.5 \pm 0.5 V \end{array}$		
On the DCU PARAMETERS lisplay check that the LIA emperatures are slowly varming up. At switch-on it is possible that ome of the LIA temperatures vill be in soft or even hard imits. No action is required.	LIAS1TEMP to LIAS3TEMP	~ 290-300 K		
Wait for ~3 minutes before	_		_	_
i	t switch-on it is possible that ome of the LIA temperatures rill be in soft or even hard mits. No action is required.  Vait for ~3 minutes before ontinuing with the SFTs	t switch-on it is possible that ome of the LIA temperatures rill be in soft or even hard mits. No action is required.  Vait for ~3 minutes before ontinuing with the SFTs	t switch-on it is possible that ome of the LIA temperatures rill be in soft or even hard mits. No action is required.  Vait for ~3 minutes before ontinuing with the SFTs	t switch-on it is possible that ome of the LIA temperatures will be in soft or even hard mits. No action is required.  Wait for ~3 minutes before — — — —

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 64 of 74

#### 7.22 Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-01

Version	1.0			
Date	29 <sup>th</sup> August 2007			
Purpose	Spectrometer JFETs Switch On			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Spectrometer LIAs are ON			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Spectrometer LIAs are ON			
	Spectrometer JFETs are ON			
Constraints	SPIRE DRCU PRIME is switched ON			
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>			
	• CCS is up and running			
	DCU PARAMETERS display is selected on the CCS			
Duration	5 minutes			

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-ON.tcl	_	_	_	
	Wait for the script to finish executing before proceeding with				
	the next step				
2	On the DCU PARAMETERS display check the JFET HK parameters	SPECJFETSTAT	7		
	1	SSWJFET1V	$-1.49 \pm 0.1 \text{ V}$		
		SSWJFET2V	$-1.49 \pm 0.1 \text{ V}$		
		SLWJFET1V	-1.49 ± 0.1 V		
	Check with Instrument Team				
	before proceeding with the next				
	test.				
Test F	Result (Pass/Fail):	·			

Pass/Fail criteria | Spectrometer JFET HK parameters show expected ON values

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 65 of 74

# 7.23 Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-02

Version	1.0			
Date	29 <sup>th</sup> August 2007			
Purpose	Spectrometer JFETs Switch On			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Spectrometer LIAs are ON			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	AC/DC thermometry is ON			
	MCU PRIME is booted			
	Spectrometer LIAs are ON			
	Spectrometer JFETs are ON			
Constraints	SPIRE DRCU PRIME is switched ON			
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>			
	CCS is up and running			
	DCU PARAMETERS display is selected on the CCS			
Duration	5 minutes			
Pass/Fail criteria	Spectrometer JFET HK parameters show expected ON values			

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-ON.tcl  Wait for the script to finish executing before proceeding with the next step				
2	On the DCU PARAMETERS display check the JFET HK parameters  Check with Instrument Team	SPECJFETSTAT  SSWJFET1V SSWJFET2V  SLWJFET1V	7 $-1.68 \pm 0.02 \text{ V}$ $-2.07 \pm 0.02 \text{ V}$ $-1.59 \pm 0.02 \text{ V}$		
	Check with Instrument Team before proceeding with the next test.				

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 66 of 74

# 7.24 Procedure: SPIRE-FM-SFT-SPEC-JFET-OFF

Version	1.0		
Date	29 <sup>th</sup> August 2007		
Purpose	Spectrometer JFETs Switch Off		
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
	AC/DC thermometry is ON		
	MCU PRIME is booted		
	Spectrometer LIAs are ON		
	Spectrometer JFETs are ON		
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
	AC/DC thermometry is ON		
	MCU PRIME is booted		
	Spectrometer LIAs are ON		
	Spectrometer JFETs are OFF		
Constraints	SPIRE DRCU PRIME is switched ON		
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>		
	CCS is up and running		
	DCU PARAMETERS display is selected on the CCS		
Duration	5 minutes		
Pass/Fail criteria	Spectrometer JFET HK parameters show expected OFF values		

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-OFF.tcl		_		
	Wait for the script to finish executing before proceeding with the next step				

# Procedure

Ref: SPIRE-RAL-PRC-002951

2.0

**Issue:** 29-08-07 Date: Page: 67 of 74

PFM Final SIH Electrical Integration/Checkout Procedure

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
2	On the DCU PARAMETERS display check the JFET HK parameters  Check with Instrument Team	SPECJFETSTAT  SSWJFET1V SSWJFET2V SLWJFET1V	0 0.0 V 0.0 V 0.0 V		
	before proceeding with the next test.				
Test I	Test Result (Pass/Fail):				

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 68 of 74

#### 7.25 Procedure: SPIRE-FM-SFT-SLIA-OFF-P

Version	2.2			
Date	2 <sup>nd</sup> January 2007			
Purpose	Spectrometer LIAs PRIME Switch OFF			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer			
	LIAs are ON			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer			
	LIAs are OFF			
Constraints	SPIRE DRCU PRIME is switched ON			
	Spectrometer LIAs are ON			
	SPIRE MIB PRIME is imported in the CCS database.			
	CCS is up and running			
	SFT PARAMETERS display is selected on the CCS			
Duration	5 minutes			
Pass/Fail criteria	Specified Spectrometer LIA HK parameters show expected OFF values			

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SLIA-OFF-P.tcl	SLIABITSTAT	1/-/0		
2	Check Photometer LIA HK parameter values	SLIAP5V SLIAP9V SLIAM9V	$5.2 \pm 0.2$ V/- $11.5 \pm 0.5$ V/- $-11.5 \pm 0.5$ V/-		
Test F	Result (Pass/Fail):				_

# **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 69 of 74

# 7.26 Procedure SPIRE-FM-SFT-MCU-OFF-P

Version	2.2			
Date	2 <sup>nd</sup> January 2007			
Purpose	MCU PRIME Switch OFF			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is ON and MCU PRIME is booted.			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is ON and MCU PRIME is OFF.			
Constraints	SPIRE DRCU PRIME is switched ON			
	SPIRE MCU PRIME is ON.			
	SPIRE MIB PRIME is imported in the CCS database.			
	CCS is up and running			
	SFT PARAMETERS display is selected on the CCS			
Duration	5 minutes			
Pass/Fail criteria	Specified MCU HK Parameter shows expected value.			

#### **Procedure Steps:**

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute SPIRE-FM-SFT-MCU-OFF-P.tcl		_		
2	Check that the MCU is switched off	MCUBITSTAT	1/-/0		
Test I	Test Result (Pass/Fail):				

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 70 of 74

# 7.27 Procedure SPIRE-FM-SFT-SCU-OFF-P

Version	2.2			
Date	2 <sup>nd</sup> January 2007			
Purpose	SCU PRIME Switch OFF			
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is ON.			
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced			
	and AC/DC thermometry is OFF			
Constraints	SPIRE DRCU PRIME is switched ON			
	• SPIRE MIB PRIME is imported in the CCS database.			
	CCS is up and running			
	• SFT PARAMETERS display is selected on the CCS			
Duration	5 minutes			
Pass/Fail criteria	Specified SCU HK Parameters show expected value.			

# **Procedure Steps:**

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SCU-OFF-P.tcl		_		_
2	A few seconds later record the value of parameter SCUTEMPSTAT	SCUTEMPSTAT	FFFF/-/0		
3	A few seconds later record the value of parameter SUBKSTAT	SUBKSTAT	1/-/0		
Test Result (Pass/Fail):					

# **Procedure**

Ref: SPIRE-RAL-PRC-002951

2.0 **Issue:** 29-08-07 Date: Page: 71 of 74

PFM Final SIH Electrical Integration/Checkout Procedure

# 7.28 Procedure: SPIRE-FM-SFT-DRCU-OFF-P

Version	2.2		
Date	2 <sup>nd</sup> January 2007		
Purpose	DRCU PRIME Switch OFF		
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced		
	and AC/DC thermometry is ON.		
Final configuration	SPIRE DPU PRIME is ON, SPIRE DRCU PRIME is OFF and SPIRE HK		
	is not being produced.		
Constraints	SPIRE-FM-SFT-SCU-OFF has been executed.		
	SPIRE DRCU PRIME is switched ON		
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>		
	CCS is up and running		
	SFT PARAMETERS display is selected on the CCS		
Duration	5 minutes		
Pass/Fail criteria	THSK and TM2N stop refreshing/incrementing		

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-DRCU-OFF.tcl		_		
2	Check that THSK parameter is not refreshing anymore	THSK	Not refreshing		
3	Check that TM2N parameter is not incrementing anymore	TM2N	Not incrementing	_	
4	Power OFF the SPIRE DRCU PRIME unit.	_	_	_	
Test Result (Pass/Fail):					

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0 Date: 29-08-07 Page: 72 of 74

#### 7.29 Procedure SPIRE-FM-SFT-DPU-OFF-P

Version	2.2
Date	2 <sup>nd</sup> January 2007
Purpose	DPU PRIME Switch OFF
Initial configuration	SPIRE DPU PRIME is ON but not generating HK.
Final configuration	SPIRE DPU PRIME is OFF.
Constraints	SPIRE-FM-SFT-DRCU-OFF has been executed.
	<ul> <li>SPIRE DPU PRIME is switched ON</li> </ul>
	<ul> <li>SPIRE MIB PRIME is imported in the CCS database.</li> </ul>
	CCS is up and running
	<ul> <li>SFT PARAMETERS display is selected on the CCS</li> </ul>
Duration	5 minutes
Pass/Fail criteria	Power to SPIRE DPU PRIME is OFF

### **Procedure Steps:**

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure	
1	Power OFF the SPIRE DPU PRIME unit.	_	_	_		
Test I	Test Result (Pass/Fail):					

### **Procedure**

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 73 of 74

#### 7.30 SPIRE-SAFE-SWITCH-OFF

Version	2.2	
Date	2 <sup>nd</sup> January 2007	
Purpose	To switch OFF the SPIRE instrument if an anomaly should occur	
<b>Initial configuration</b>	SPIRE can be on ANY configuration as specified on the procedure steps	
Final configuration	SPIRE is OFF	
Preconditions	SPIRE FM DPU is electrically integrated with the Herschel Satellite	
	SPIRE MIB PRIME is imported in the CCS database.	
	CCS is up and running	
	FUNCTIONAL TEST PARAMETERS display is selected on the CCS	
Duration	5 minutes	
Pass/Fail Criteria	SPIRE is OFF.	
	All instrument subsystems are completely powered OFF.	

#### Note: All HK parameters relevant to this procedure can be located on the FUNCTIONAL TEST PARAMETERS CCS display

Step	Description	Parameter - Unit	Display	Expected value before/ after	Actual value before/ after
1	Check the current instrument configuration	MODE	See above	One of: PHOTSBY SPECSTBY REDY DRCU_ON	
2	If the current value of MODE HK parameter is:  PHOTSBY → Go to step 3  SPECSTBY → Go to step 4  REDY → Go to step 5  DRCU_ON → Go to step 6				
3	Execute Procedures:  SPIRE-FM-SFT-PDET-OFF-P/R SPIRE-FM-SFT-BSM-OFF-P/R Then Go to step 5	PLIABITSAT CHOPSENSPWR		1/0 1/0	
4	Execute Procedures:  SPIRE-FM-SFT-SDET-OFF-P/R SPIRE-FM-SFT-SMEC-OFF-P/R Then Go to step 5	SLIABITSAT SMECENCPWR		1/0 1/0	

# Procedure

PFM Final SIH Electrical Integration/Checkout Procedure

Ref: SPIRE-RAL-PRC-

002951

Issue: 2.0
Date: 29-08-07
Page: 74 of 74

Step	Description	Parameter - Unit	Display	Expected value before/ after	Actual value before/ after
5	Execute Procedure:  SPIRE-FM-SFT-MCU-OFF-P/R SPIRE-FM-SFT-SCU-OFF-P/R Go to step 6	MCUBITSTAT SCUTEMPSTAT		1/0 0xFFFF/0	
6	Execute Procedure:  SPIRE-FM-SFT-DRCU-OFF-P/R Go to step 7	TM2N THSK		Updating/ Not updating	
7	Execute Procedure: SPIRE-FM-SFT-DPU-OFF-P/R	n/a		n/a	