



Test Procedure

Herschel


Title:

SPIRE PFM Final Electrical Integration Procedure

CI-No:

125 200

Prepared by:


 A. Koppe & S. Hamer

Date:



10.09.2007

Checked by:


 S. Idler


12.09.2007

Product Assurance:



 R. Stritter


12.09.2007

Configuration Control:


 W. Wietbrock

12.09.2007

Project Management:


 Dr. W. Fricke

12/09/2007

Distribution:

See Distribution List (last page)

Copying of this document, and giving it to others and the use or communication of the contents thereof, are forbidden without express authority. Offenders are liable to the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design.

Issue	Date	Sheet	Description of Change	Release
1	10.09.07	all	Initial issue	

Table of Content

1	Scope	7
2	Documents/Drawings	8
2.1	Applicable Documents	8
2.2	Reference Documents	8
2.3	Other Documents	8
3	Personnel	9
4	Mating of SIH-IS to CVV-CB and SVM-CB	10
4.1	Prerequisites	10
4.2	End State	10
4.3	Notes	10
5	Conditions	11
5.1	Personnel	11
5.2	Environmental	11
5.3	General Precautions and Safety	11
5.4	Special Equipment	12
5.5	Test Configuration	12
6	Verification Requirements and Test Criteria	13
7	Step by Step Procedure	14
8	De-mating of SIH-IS and SIH-SS for LPU Integration	39
8.1	Prerequisites	39
8.2	End State	39
8.3	Notes	39
9	Step by Step Procedure for Mating of SIH-IS and SIH-SS after LPU Integration	43
9.1	Prerequisites	43
9.2	Notes	43

10	Summary Sheets	49
10.1	Procedure Variation Summary	49
10.2	Non Conformance Report (NCR) Summary	50
10.3	Sign-off Sheet	50
11	APPENDICES	51
11.1	Procedure SPIRE Power On	51
11.2	Procedure SPIRE-FM-SFT-DPU-ON-P	51
11.3	Procedure SPIRE-FM-SFT-DRCU-ON-P	53
11.4	Procedure SPIRE-FM-SFT-FUNC-SCU-01-P	55
11.5	Procedure SPIRE-FM-SFT-FUNC-SCU-03-P	56
11.6	Procedure SPIRE-FM-SFT-FUNC-SCU-06-P	58
11.7	Procedure SPIRE-FM-SFT-FUNC-SCU-07-P	60
11.8	Procedure SPIRE-FM-SFT-FUNC-SCU-04-P	62
11.9	Procedure SPIRE-FM-SFT-FUNC-SCU-05-P	63
11.10	Procedure SPIRE-FM-SFT-FUNC-MCU-01-P	64
11.11	Procedure: SPIRE-FM-SFT-FUNC-MCU-02-P	65
11.12	Procedure SPIRE-FM-SFT-FUNC-BSM-01-P	66
11.13	Procedure SPIRE-FM-SFT-BSM-OFF-P	67
11.14	Procedure SPIRE-FM-SFT-FUNC-SMEC-01-P	68
11.15	Procedure SPIRE-FM-SFT-SMEC-OFF-P	69
11.16	Procedure SPIRE-FM-SFT-FUNC-DCU-01-P	70
11.17	Procedure: SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P	71
11.18	Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-01	72
11.19	Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-02	74
11.20	Procedure: SPIRE-FM-SFT-PHOT-JFET-OFF	76
11.21	Procedure: SPIRE-FM-SFT-PLIA-OFF-P	78
11.22	Procedure: SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P	79
11.23	Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-01	80
11.24	Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-02	81
11.25	Procedure: SPIRE-FM-SFT-SPEC-JFET-OFF	82
11.26	Procedure: SPIRE-FM-SFT-SLIA-OFF-P	84
11.27	Procedure SPIRE-FM-SFT-MCU-OFF-P	85

11.28	Procedure SPIRE-FM-SFT-SCU-OFF-P	86
11.29	Procedure SPIRE Power OFF	87
11.30	Procedure: SPIRE-FM-SFT-DRCU-OFF-P	87
11.31	Procedure: SPIRE-FM-SFT-DPU-OFF-P	88
11.32	SPIRE-SAFE-SWITCH-OFF	89

List of Tables

Table 1: Applicable Documents	8
Table 2: Reference Documents	8
Table 10.1-1: Procedure Variation Sheet	49
Table 10.2-1: Non-Conformance Record Sheet	50

1 Scope

This document establishes a cover procedure which incorporates the detailed step-by-step procedure, prerequisites and conditions, copied from RD1, to be followed for the final electrical integration of the SPIRE Warm Units and their associated harness on the SVM panel with the SPIRE FPU and its SIH at the CVV CB.

It should be noted that the LPU integration is performed later during the HERSCHEL PFM AIT flow. Therefore, a separate chapter is given for the integration once this unit is available.

The following activities are to be performed:

- Mating of the SIH-IS to CVV-CB and SVM-CB covers the following activities:

1. The mating of the SIH-IS and SIH-CS harnesses at the CVV-CB vacuum feedthrus
2. The mating of the SIH-IS and SIH-SS harnesses at the SVM-CB
3. Integration electrical tests whereby the balance of I_{dd} and I_{ss} for the JFET modules is measured

- De-mating of SIH-IS and SIH-SS for LPU Integration has been included because it is foreseen that the LPU will have to be integrated after initial electrical integration and UFT of SPIRE. This requires that the SIH-SS-11 is de-mated from the SIH-IS-11 and SIH-SS-13 is de-mated from the SIH-IS-13 at the SVM-CB and the SPIRE SVM panel is opened.

- Step by Step Procedure for Mating of SIH-IS and SIH-SS after LPU Integration has been included to document the procedure for the final mating of the SIH-SS-XX and SIH-IS-XX after integration and test of the LPU.

2 Documents/Drawings

2.1 Applicable Documents

No.	Document Name	Document Number	Iss./Rev.
AD1	SPIRE FPU Handling and Mechanical Integration Procedure	SPIRE-RAL-PRC-002802	2
AD2	Making SPIRE ESD Safe	SPIRE-RAL-NOT-002028	2
AD3	ESD Regeln für HERSCHEL PLM und Integrations-Aktivitäten	HP-2-ASED-PR-0062	1
AD3	PA Plan	HP-2-ASED-PL-0007	2.1

Table 1: Applicable Documents

2.2 Reference Documents

No.	Document Name	Document Number	Iss./Rev.
RD1	PFM FINAL SIH ELECTRICAL INTEGRATION/CHECKOUT PROCEDURE	SPIRE-RAL-PRC-2951	2.1
RD2	SPIRE FM SHORT FUNCTIONAL TEST PROCEDURE	SPIRE-RAL-PRC-2494	2.4
RD3	PFM CVV INTERNAL SPIRE-SIH ELECTRICAL INTEGRATION PROCEDURE	HP-2-ASED-TP-0150	1.0
RD4	PFM CVV EXTERNAL CHH AND SIH RE-MATING	HP-2-ASED-TP-0158	1.0

Table 2: Reference Documents

2.3 Other Documents

None

3 Personnel

The attendance of the following personnel is requested for the SPIRE PFM final electrical integration:

- SPIRE Engineer
- ASED Engineer
- ASED PA

4 Mating of SIH-IS to CVV-CB and SVM-CB

4.1 Prerequisites

1. The DCU, FCU and DPU have been mechanically and electrically integrated to the SVM panel and the SIH-SS harnesses are all integrated but not mated to the SVM-CB.
2. If the LPU is not integrated to the FCU, **make sure that the dummy LPU simulator plugs are mated to FCU P43/P44** once the harness modifications on the SPIRE panel has been made.
3. The SIH-CS harnesses have been mated to the SPIRE FPU + JFP/JFS
4. The SPIRE SVM panel has been closed
5. The PLM has been mechanically integrated to the SVM
6. The SIH-IS-XX harnesses (XX = 1.....13) are mechanically integrated onto the outside of the cryostat.
 - a. They are mated at the CVV internal FTTH connectors
 - b. They are temporary mechanically integrated to the SVM-CB without electrical termination
7. The SPIRE UFT has been successfully completed.
8. The Ground strap (red tag) from the FPU shall be removed.

4.2 End State

The electrical integration tests have been completed

The instrument is ready for SFT

4.3 Notes

1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream continuously to discharge the harness.
2. If an anomaly is detected during the integration test, then the instrument can be switched off from any state using the procedure in §11.32 – SPIRE-SAFE-SWITCH-OFF.

5 Conditions

5.1 Personnel

The treatment process will be conducted by the following personnel:

<i>Personnel</i>	<i>Date</i>	<i>Name</i>
AIT Manager		
AIT Engineer		
Harness Engineer		
SPIRE Representative		
Product Assurance		

The performers are requested to follow the procedure step-by step and mark the execution of each test step in the allocated column. Results shall be plotted and marked by the concerned test step and figure number. Any deviations which may be necessary shall be described on the assigned pages in chapter 10.1 with a reference at the concerned position in the text where the deviation occurred.

All mating shall be recorded in the test procedure ref. HP-2-ASED-TP-0158 (RD4) too!

5.2 Environmental

There are no specific environmental conditions for treatment process other than in the step by step procedure

5.3 General Precautions and Safety

All safety precautions concerning the personnel and the hardware and must be observed during the whole test.

All operations have to be in accordance to the ESD rules as per AD2 and AD3.

The test responsible confirms with his signature in chapter 5.1 above that all participants are aware of these precautions.

5.4 Special Equipment

Qty.	Equipment	Supplier
1	BoB, 128 way	ASED
1	Resistor, 1 MOhm (5%)	SPIRE
As required	Resistors, 47 Ohm (5%)	SPIRE

5.5 Test Configuration

The following test configuration on the HERSCHEL EGSE shall be selected:

CDMU:

- The Bus IF selected on the HCDMU should be for SPIRE PRIME Instrument, (i.e., 27 TM slots allocated for SPIRE telemetry). For the PRIME side tests the BUS Configuration should be SPIRE Prime (i.e. RT=21) and for the REDUNDANT side test the BUS Configuration should be SPIRE Redundant (i.e. RT=22)
- The HCDMU and CCS should be interconnected.

CCS & IEGSE:

- The CCS and the IEGSE should be interconnected via the Pipe GW.
- The SPIRE MIB should be imported on the CCS.
- The CCS Handler application software should be running on the IEGSE.
- IEGSE system is up and running.(Database, SCOS , QLA, EGSE Router and Gateway, TM ingestion)

6 Verification Requirements and Test Criteria

As per step-by-step procedure

7 Step by Step Procedure

Step-No.	Integration-Step-Description	Results/Remarks	Sign Off
	Mating of SIH-IS to SIH-CS		
1	Prepare a 128-way BOB to short all contacts to spacecraft chassis via a 1MOhm resistor	Alternatively a IDAS shorting plug with 1 MOhm to GND can be used	
2	SIH-04 Short contacts of 312100 J03 to spacecraft chassis with BOB		
3	Remove Type-VII safeing plug from 211121 J22		
4	Mate 211121 P22 to J22		
5	Demate BOB from 312110 J03		
6	Mate Type-VII safeing plug to 312100 J03		
7	SIH-05 Short contacts of 312100 J02 to spacecraft chassis with BOB		
8	Remove Type-VII safeing plug from 211121 J23		
9	Mate 211121 P23 to J23		
10	Demate BOB from 312100 J02		
11	Mate Type-VII safeing plug to 312100 J02		
12	SIH-06 Short contacts of 312200 J03 to spacecraft chassis with BOB		
13	Remove Type-VII safeing plug from 211121 J24		
14	Mate 211121 P24 to J24		
15	Demate BOB from 312200 J03		
16	Mate Type-VII safeing plug to 312200 J03		
17	SIH-07 Short contacts of 312200 J04 to spacecraft chassis with BOB		
18	Remove Type-VII safeing plug from 211121 J25		
19	Mate 211121 P25 to J25		

20	Demate BOB from 312200 J04		
21	Mate Type-VII safeing plug to 312200 J04		
22	SIH-08 Short contacts of 312200 J01 to spacecraft chassis with BOB		
23	Remove Type-VII safeing plug from 211121 J27		
24	Mate 211121 P27 to J27		
25	Demate BOB from 312200 J01		
26	Mate Type-VII safeing plug to 312200 J01		
27	SIH-09 Short contacts of 312200 J02 to spacecraft chassis with BOB		
28	Remove Type-VII safeing plug from 211121 J28		
29	Mate 211121 P28 to J28		
30	Demate BOB from 312200 J02		
31	Mate Type-VII safeing plug to 312200 J02		
32	SIH-10 Short contacts of 312300 J06 to spacecraft chassis with BOB		
33	Remove Type-VII safeing plug from 211121 J34		
34	Mate 211121 P34 to J34		
35	Demate BOB from 312300 J06		
36	Mate Type-VII safeing plug to 312300 J06		
37	SIH-12 Short contacts of 312300 J05 to spacecraft chassis with BOB		
38	Remove Type-VII safeing plug from 211121 J33		
39	Mate 211121 P33 to J33		
40	Demate BOB from 312300 J05		
41	Mate Type-VII safeing plug to 312300 J05		
42	SIH-02 Short contacts of 312200 J05 to spacecraft chassis with BOB		
43	Remove Type-VII safeing plug from 211121 J31		

44	Mate 211121 P31 to J31		
45	Demate BOB from 312200 J05		
46	Mate Type-VII safeing plug to 312200 J05		
47	SIH-11 Short contacts of 312300 J04 to spacecraft chassis with BOB		
48	Remove Type-VIII safeing plug from 211121 J30		
49	Mate 211121 P30 to J30		
50	Demate BOB from 312300 J04		
51	Mate Type-VIII safeing plug to 312300 J04		
52	SIH-13 Short contacts of 312300 J03 to spacecraft chassis with BOB		
53	Remove Type-VIII safeing plug from 211121 J29		
54	Mate 211121 P29 to J29		
55	Demate BOB from 312300 J03		
56	Mate Type-VIII safeing plug to 312300 J03		
57	SIH-01 Short contacts of 312200 J06 to spacecraft chassis with BOB		
58	Remove Type-VI safeing plug from 211121 J32		
59	Mate 211121 P32 to J32		
60	Demate BOB from 312200 J06		
61	Mate Type-VI safeing plug to 312200 J06		
62	SIH-03 Short contacts of 312100 J04 to spacecraft chassis with BOB		
63	Remove Type-V safeing plug from 211121 J26		
64	Mate 211121 P26 to J26		
65	Demate BOB from 312100 J04		
66	Mate Type-V safeing plug to 312100 J04		
	Idd/Iss measurement Preparation		

67	<p>Prepare a 128-way BOB for inline insertion in CB312200 P06/J06 with 47Ω(5%) inline series resistors in the following contacts:</p>	
	Function	Contact number
	PTC_JFETV_Bias_A +ve	24
	PTC_JFETV_Bias_A -ve	35
	SLW_JFETV_A1 +ve	92
	SLW_JFETV_A1 -ve	91
	SLW_JFETV_A2 +ve	103
	SLW_JFETV_A2 -ve	113
	SSW_JFETV1_A +ve	68
	SSW_JFETV1_A -ve	57
	SSW_JFETV2_A +ve	70
	SSW_JFETV2_A -ve	81
<p>The remaining contacts have inline “bridges” Temporarily label BOB as SPIRE Spect Test</p>		

68	Measure and record the resistance of the inline resistors in the BOB prepared for CB312200 P06/J06. The measured resistance is to be $47 \pm 2.3 \Omega$		
		Function	Resistance (Ohm)
		24	
		35	
		92	
		91	
		103	
		113	
		68	
		57	
		70	
		81	

Prepare a 128-way BOB for inline insertion in CB312100 P04/J04 with 47Ω(5%) inline series resistors in the following contacts:

Function	Contact number
PSW_JFETV1_A +	26
PSW_JFETV1_A -	37
PSW_JFETV2_A +	38
PSW_JFETV2_A -	49
PSW_JFETV3_A +	48
PSW_JFETV3_A -	60
PSW_JFETV4_A +	59
PSW_JFETV4_A -	71
PSW_JFETV5_A +	50
PSW_JFETV5_A -	61
PSW_JFETV6_A +	62
PSW_JFETV6_A -	51
PMW_JFETV1_A +	86
PMW_JFETV1_A -	87
PMW_JFETV2_A +	97
PMW_JFETV2_A -	98
PMW_JFETV3_A +	108
PMW_JFETV3_A -	109
PMW_JFETV4_A +	116
PMW_JFETV4_A -	117
PLW_JFETV1_A +	99
PLW_JFETV1_A -	100
PLW_JFETV2_A +	110
PLW_JFETV2_A -	111

69

The remaining contacts have inline “bridges”

Doc. No: HP-2-ASED-TP-0066

Issue: 1

Date: 10/2007 File: SPIRE PFM Final Electrical Integration Procedure HP-2-ASED-TP-0066_1.doc

Temporarily label BOB as SPIRE PFM Test

70	<p>Measure and record the resistance of the inline resistors in the BOB prepared for CB312200 P06/J06. The measured resistance is to be $47 \pm 2.3 \Omega$</p>																																																				
		<table border="1"> <thead> <tr> <th>Contact number</th> <th>Resistance</th> </tr> </thead> <tbody> <tr><td>26</td><td></td></tr> <tr><td>37</td><td></td></tr> <tr><td>38</td><td></td></tr> <tr><td>49</td><td></td></tr> <tr><td>48</td><td></td></tr> <tr><td>60</td><td></td></tr> <tr><td>59</td><td></td></tr> <tr><td>71</td><td></td></tr> <tr><td>50</td><td></td></tr> <tr><td>61</td><td></td></tr> <tr><td>62</td><td></td></tr> <tr><td>51</td><td></td></tr> <tr><td>86</td><td></td></tr> <tr><td>87</td><td></td></tr> <tr><td>97</td><td></td></tr> <tr><td>98</td><td></td></tr> <tr><td>108</td><td></td></tr> <tr><td>109</td><td></td></tr> <tr><td>116</td><td></td></tr> <tr><td>117</td><td></td></tr> <tr><td>99</td><td></td></tr> <tr><td>100</td><td></td></tr> <tr><td>110</td><td></td></tr> <tr><td>111</td><td></td></tr> </tbody> </table>	Contact number	Resistance	26		37		38		49		48		60		59		71		50		61		62		51		86		87		97		98		108		109		116		117		99		100		110		111		
		Contact number	Resistance																																																		
		26																																																			
		37																																																			
		38																																																			
		49																																																			
		48																																																			
		60																																																			
		59																																																			
		71																																																			
		50																																																			
		61																																																			
		62																																																			
		51																																																			
		86																																																			
		87																																																			
		97																																																			
		98																																																			
		108																																																			
109																																																					
116																																																					
117																																																					
99																																																					
100																																																					
110																																																					
111																																																					

	Grounding Check		
71	Remove SPIRE Safeing Plug Type-V from SVM-CB 312100 J04		
72	Remove SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06.		
73	Remove SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J04.		
74	Remove SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J03.		
75	Prepare a 128-way BOB and short contacts to remove charge		
76	Mate BOB to 312200 J06		
77	Verify FPU Isolation from OBA by measuring Pin 5 to Chassis: s.b. > 1 MOhm		
78	Verify Analogue Ground Isolation from OBA by measuring Pin 93 to Chassis: s.b. > 1 MOhm		
79	Demate BOB from 312200 J06		
80	Mate BOB to 312100 J04		
81	Verify FPU Isolation from OBA by measuring Pin 2 to Chassis: s.b. > 1 MOhm		
82	Verify Analogue Ground Isolation from OBA by measuring Pin 36 to Chassis: s.b. > 1 MOhm		
83	Demate BOB from 312100 J04		
84	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
85	Mate SPIRE Safeing Plug Type-VI to SVM-CB 312200 J06.		
86	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J04.		
87	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J03.		
	Subsystem harness mating		
88	Verify that CB 312300 J01 is mated with CB 312300 P01		
89	Verify that CB 312300 J02 is mated with CB 312300 P02		
90	Remove and store protective cover from CB 312300 P06		

91	Remove and store SPIRE Safeing Plug Type-VII from CB 312300 J06		
92	Mate CB 312300 P06 to 312300 J06		
93	Remove and store protective cover from CB 312300 P05		
94	Remove and store SPIRE Safeing Plug Type-VII from CB 312300 J05		
95	Mate CB 312300 P05 to 312300 J05		
96	Remove and store protective cover from CB 312300 P04		
97	Remove and store SPIRE Safeing Plug Type-VIII from CB 312300 J04		
98	Mate CB 312300 P04 to 312300 J04		
99	Remove and store protective cover from CB 312300 P03		
100	Remove and store SPIRE Safeing Plug Type-VIII from CB 312300 J03		
101	Mate CB 312300 P03 to 312300 J03		
	Spectrometer Initial Mating		
102	Short the contacts of the BOB for 312200 J06/P06 to chassis to remove any charge		
103	Remove and store the protective cover from 312200 P06		
104	Mate the BOB prepared for 312200 J06/P06 to 312200 P06		
105	Demate and store the SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06		
106	Mate the inline BOB prepared for 312200 J06/P06 to 312200 J06		
107	Remove and store the protective cover from 312200 P05		
108	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J05		
109	Mate 312200 P05 to 312200 J05		
110	Mate 312100 P01A to J01A		
	Photometer Initial Mating		

	<i>SIH-03</i>		
111	Short the contacts of the BOB for 312100 J04/P04 to chassis to remove any charge		
112	Remove and store the protective cover from 312100 P04		
113	Mate the BOB prepared for 312100 J04/P04 to 312200 P04		
114	Demate the SPIRE Safeing Plug Type-V from SVM-CB 3122100 J04		
115	Mate the inline BOB prepared for 312100 J04/P04 to 312100 J04		
	<i>SIH-04</i>		
116	Remove and store the protective cover from 312100 P03		
117	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312100 J03		
118	Mate 312100 P03 to 312200 J03		
119	Mate 312100 P01B to J01B		
	<i>SIH-05</i>		
120	Remove and store the protective cover from 312100 P02		
121	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312100 J02		
122	Mate 312100 P02 to 312200 J02		
	<i>SIH-06</i>		
123	Remove and store the protective cover from 312200 P03		
124	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J03		
125	Mate 312200 P03 to 312200 J03		
	<i>SIH-07</i>		
126	Remove and store the protective cover from 312200 P04		
127	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J04		

128	Mate 312200 P04 to 312200 J04		
	<i>SIH-08</i>		
129	Remove and store the protective cover from 312200 P01		
130	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J01		
131	Mate 312200 P01 to 312200 J01		
	<i>SIH-09</i>		
132	Remove and store the protective cover from 312200 P02		
133	Demate the SPIRE Safeing Plug Type-VII from SVM-CB 312200 J02		
134	Mate 312200 P02 to 312200 J02		
	Instrument switch-on (Phot. JFETs)		
135	Execute Procedure: SPIRE-FM-SFT-DPU-ON-P	Nominal HK packets: Critical HK packets: THSK refresh: TM2N refresh: TM1N refresh: SPIRE/CCS time sync: SCOS/THSK/QLA sync:	

136	Execute Procedure: SPIRE-FM-SFT-DRCU-ON-P	THSK stop: TM2N stop: THSK start: TM2N start: SCUP5V (~ 5.2 ± 0.5V): SCUP9V (~ 9.0 ± 0.2V): SCUM9V (~ -9.0 ± 0.2V): BIASP5V (~ 5.1 ± 0.5V): BIASP9V (~ 9.0 ± 0.2V): BIASM9V (~ -9.0 ± 0.2V):	
137	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-01-P	SCUFRAMECNT: TM5N:	
138	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-03-P	SCUTEMPSTAT: PUMPHTRTEMP: PUMPHSTEMP: EVAPHSTEMP: SHUNTTEMP: EMCFILTEMP: SL0TEMP: PL0TEMP: OPTTEMP: BAFTEMP: BSMIFTEMP: SCAL2TEMP: SCAL4TEMP: SCALTEMP: SMECIFTEMP: SMECTEMP: BSMTEMP:	

139	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-06-P	SUBKSTAT: SUBKTEMP:	
140	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-07-P	SPHSV: EVHSV: SPHTRV:	
141	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-04-P	PCALV: PCALCURR:	
142	Execute Procedure: SPIRE-FM-SFT-FUNC-SCU-05-P	SCAL4CURR: SCAL4V: SCAL2CURR: SCAL2V:	
143	Execute Procedure: SPIRE-FM-SFT-FUNC-MCU-01-P	MCUBITSTAT: MCUP5V: MCUP14V: MCUM14V: MCUP15V: MCUM15V: MCUMACTEMP: MCUSMECTEMP: MCUBSMTEMP:	
144	Execute Procedure: SPIRE-FM-SFT-FUNC-MCU-02-P	MCUFRAMECNT:	
145	Execute Procedure: SPIRE-FM-SFT-FUNC-BSM-01-P	CHOPSENSPWR: JIGGSENSPWR:	
146	Execute Procedure: SPIRE-FM-SFT-BSM-OFF-P	CHOPSENSPWR: JIGGSENSPWR:	
147	Execute Procedure: SPIRE-FM-SFT-FUNC-SMEC-01-P	SMECENCPWR: SMECLVDTPWR:	
148	Execute Procedure: SPIRE-FM-SFT-SMEC-OFF-P	SMECENCPWR: SMECLVDTPWR:	

149	Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-01-P	DCUFRAMECNT:	
150	Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P	PLIABITSTAT: PLIAP5V: PLIAP9V: PLIAM9V: LIAP1TEMP to LIAP9TEMP:	
151	Execute Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-01	PSWJFETSTAT: PMLWJFETSTAT: PSWJFET1V: PSWJFET2V: PSWJFET3V: PSWJFET4V: PSWJFET5V: PSWJFET6V: PMWJFET1V: PMWJFET2V: PMWJFET3V: PMWJFET4V: PLWJFET1V: PLWJFET2V: TCJFETV:	
Photometer and PTC Idd/Iss			

152	<p>Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312100 P04/J04. The expected values should lie between 55 and 100mV</p> <p>(PLW, PSW and PMW)</p>	Contact number	Voltage drop
		26	
		37	
		38	
		49	
		48	
		60	
		59	
		71	
		50	
		61	
		62	
		51	
		86	
		87	
		97	
		98	
		108	
		109	
		116	
117			
99			
100			
110			
111			

153	<p>Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 55 and 100mV</p> <p>(PTC)</p>		
		Contact number	Voltage drop
		24	
		35	

154	Measure the voltage drop along the cryoharness for the PMW/PSW/PLW arrays using the contacts form the BOB prepared for CB312100 P04/J04		Contact A 26 37 38 49 48 60 59 71 50 61 62 51 86 87 97 98 108 109 116 117 99 100 110 111	Contact B 42 54 53 52 41 30 10 11 19 29 16 27 7 14 24 35 23 34 33 45 70 81 69 80	Voltage Drop	
155	Measure the voltage drop along the cryoharness for the PTC arrays using the contacts form the BOB prepared for CB312200 P06/J06		Contact A 24 35	Contact B 3 2	Voltage Drop	

156	Execute (§0, p. 75)	PSWJFETSTAT: PMLWJFETSTAT: PSWJFET1V: PSWJFET2V: PSWJFET3V: PSWJFET4V: PSWJFET5V: PSWJFET6V: PMWJFET1V: PMWJFET2V: PMWJFET3V: PMWJFET4V: PLWJFET1V: PLWJFET2V: TCJFETV:	
-----	---------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--

157	<p>Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312100 P04/J04. The expected values should lie between 55 and 100mV</p> <p>(PLW, PSW and PMW)</p>	Contact number	Voltage drop
		26	
		37	
		38	
		49	
		48	
		60	
		59	
		71	
		50	
		61	
		62	
		51	
		86	
		87	
		97	
		98	
		108	
		109	
		116	
117			
99			
100			
110			
111			

158	<p>Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 55 and 100mV</p> <p>(PTC)</p>		
		Contact number	Voltage drop
		24	
		35	

159	Measure the voltage drop along the cryoharness for the PMW/PSW/PLW arrays using the contacts form the BOB prepared for CB312100 P04/J04		Contact A 26 37 38 49 48 60 59 71 50 61 62 51 86 87 97 98 108 109 116 117 99 100 110 111	Contact B 42 54 53 52 41 30 10 11 19 29 16 27 7 14 24 35 23 34 33 45 70 81 69 80	Voltage Drop
160	Measure the voltage drop along the cryoharness for the PTC arrays using the contacts form the BOB prepared for CB312200 P06/J06		Contact A 24 35	Contact B 3 2	Voltage Drop

161	Execute Procedure: SPIRE-FM-SFT-PHOT-JFET-OFF	PSWJFETSTAT: PMLWJFETSTAT: PSWJFET1V: PSWJFET2V: PSWJFET3V: PSWJFET4V: PSWJFET5V: PSWJFET6V: PMWJFET1V: PMWJFET2V: PMWJFET3V: PMWJFET4V: PLWJFET1V: PLWJFET2V: TCJFETV:	
162	Execute Procedure: SPIRE-FM-SFT-PLIA-OFF-P	PLIABITSTAT: PLIAP5V: PLIAP9V: PLIAM9V: LIAP1TEMP to LIAP9TEMP:	
163	Execute Procedure: SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P	SLIABITSTAT: SLIAP5V: SLIAP9V: SLIAM9V: LIAS1TEMP to LIAS3TEMP:	
Measure Spect. Idd/Iss			

164	Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-01	SPECJFETSTAT: SSWJFET1V: SSWJFET2V: SLWJFET1V:																														
165	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 25 and 50mV for contacts 91, 92, 103 and 113 and between 55 and 100mV for contacts 57, 68, 70 and 81	<table border="1"> <thead> <tr> <th data-bbox="1090 520 1464 560">Function</th> <th data-bbox="1464 520 1830 560">Voltage drop</th> </tr> </thead> <tbody> <tr> <td data-bbox="1090 560 1464 600">92</td> <td data-bbox="1464 560 1830 600"></td> </tr> <tr> <td data-bbox="1090 600 1464 639">91</td> <td data-bbox="1464 600 1830 639"></td> </tr> <tr> <td data-bbox="1090 639 1464 679">103</td> <td data-bbox="1464 639 1830 679"></td> </tr> <tr> <td data-bbox="1090 679 1464 719">113</td> <td data-bbox="1464 679 1830 719"></td> </tr> <tr> <td data-bbox="1090 719 1464 759">68</td> <td data-bbox="1464 719 1830 759"></td> </tr> <tr> <td data-bbox="1090 759 1464 799">57</td> <td data-bbox="1464 759 1830 799"></td> </tr> <tr> <td data-bbox="1090 799 1464 839">70</td> <td data-bbox="1464 799 1830 839"></td> </tr> <tr> <td data-bbox="1090 839 1464 879">81</td> <td data-bbox="1464 839 1830 879"></td> </tr> </tbody> </table>			Function	Voltage drop	92		91		103		113		68		57		70		81											
Function	Voltage drop																															
92																																
91																																
103																																
113																																
68																																
57																																
70																																
81																																
166	Measure the voltage drop with a DVM between the contacts indicated on the BOB prepared for CB312200 P06/J06.	<table border="1"> <thead> <tr> <th data-bbox="1090 951 1375 991">Contact A</th> <th data-bbox="1375 951 1570 991">Contact B</th> <th data-bbox="1570 951 1830 991">Voltage Drop</th> </tr> </thead> <tbody> <tr> <td data-bbox="1090 991 1375 1031">92</td> <td data-bbox="1375 991 1570 1031">31</td> <td data-bbox="1570 991 1830 1031"></td> </tr> <tr> <td data-bbox="1090 1031 1375 1070">91</td> <td data-bbox="1375 1031 1570 1070">43</td> <td data-bbox="1570 1031 1830 1070"></td> </tr> <tr> <td data-bbox="1090 1070 1375 1110">103</td> <td data-bbox="1375 1070 1570 1110">42</td> <td data-bbox="1570 1070 1830 1110"></td> </tr> <tr> <td data-bbox="1090 1110 1375 1150">113</td> <td data-bbox="1375 1110 1570 1150">54</td> <td data-bbox="1570 1110 1830 1150"></td> </tr> <tr> <td data-bbox="1090 1150 1375 1190">68</td> <td data-bbox="1375 1150 1570 1190">19</td> <td data-bbox="1570 1150 1830 1190"></td> </tr> <tr> <td data-bbox="1090 1190 1375 1230">57</td> <td data-bbox="1375 1190 1570 1230">29</td> <td data-bbox="1570 1190 1830 1230"></td> </tr> <tr> <td data-bbox="1090 1230 1375 1270">70</td> <td data-bbox="1375 1230 1570 1270">53</td> <td data-bbox="1570 1230 1830 1270"></td> </tr> <tr> <td data-bbox="1090 1270 1375 1310">81</td> <td data-bbox="1375 1270 1570 1310">52</td> <td data-bbox="1570 1270 1830 1310"></td> </tr> </tbody> </table>			Contact A	Contact B	Voltage Drop	92	31		91	43		103	42		113	54		68	19		57	29		70	53		81	52		
Contact A	Contact B	Voltage Drop																														
92	31																															
91	43																															
103	42																															
113	54																															
68	19																															
57	29																															
70	53																															
81	52																															

167	Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-02	SPECJFETSTAT: SSWJFET1V: SSWJFET2V: SLWJFET1V:																														
168	Measure the voltage drop with a DVM across the inline resistors in the BOB prepared for CB312200 P06/J06. The expected values should lie between 25 and 50mV for contacts 91, 92, 103 and 113 and between 55 and 100mV for contacts 57, 68, 70 and 81	<table border="1"> <thead> <tr> <th data-bbox="1093 518 1467 558">Function</th> <th data-bbox="1467 518 1832 558">Voltage drop</th> </tr> </thead> <tbody> <tr><td data-bbox="1093 558 1467 598">92</td><td data-bbox="1467 558 1832 598"></td></tr> <tr><td data-bbox="1093 598 1467 638">91</td><td data-bbox="1467 598 1832 638"></td></tr> <tr><td data-bbox="1093 638 1467 678">103</td><td data-bbox="1467 638 1832 678"></td></tr> <tr><td data-bbox="1093 678 1467 718">113</td><td data-bbox="1467 678 1832 718"></td></tr> <tr><td data-bbox="1093 718 1467 758">68</td><td data-bbox="1467 718 1832 758"></td></tr> <tr><td data-bbox="1093 758 1467 798">57</td><td data-bbox="1467 758 1832 798"></td></tr> <tr><td data-bbox="1093 798 1467 837">70</td><td data-bbox="1467 798 1832 837"></td></tr> <tr><td data-bbox="1093 837 1467 877">81</td><td data-bbox="1467 837 1832 877"></td></tr> </tbody> </table>			Function	Voltage drop	92		91		103		113		68		57		70		81											
Function	Voltage drop																															
92																																
91																																
103																																
113																																
68																																
57																																
70																																
81																																
169	Measure the voltage drop with a DVM between the contacts indicated on the BOB prepared for CB312200 P06/J06.	<table border="1"> <thead> <tr> <th data-bbox="1093 949 1377 989">Contact A</th> <th data-bbox="1377 949 1579 989">Contact B</th> <th data-bbox="1579 949 1832 989">Voltage Drop</th> </tr> </thead> <tbody> <tr><td data-bbox="1093 989 1377 1029">92</td><td data-bbox="1377 989 1579 1029">31</td><td data-bbox="1579 989 1832 1029"></td></tr> <tr><td data-bbox="1093 1029 1377 1069">91</td><td data-bbox="1377 1029 1579 1069">43</td><td data-bbox="1579 1029 1832 1069"></td></tr> <tr><td data-bbox="1093 1069 1377 1109">103</td><td data-bbox="1377 1069 1579 1109">42</td><td data-bbox="1579 1069 1832 1109"></td></tr> <tr><td data-bbox="1093 1109 1377 1149">113</td><td data-bbox="1377 1109 1579 1149">54</td><td data-bbox="1579 1109 1832 1149"></td></tr> <tr><td data-bbox="1093 1149 1377 1189">68</td><td data-bbox="1377 1149 1579 1189">19</td><td data-bbox="1579 1149 1832 1189"></td></tr> <tr><td data-bbox="1093 1189 1377 1228">57</td><td data-bbox="1377 1189 1579 1228">29</td><td data-bbox="1579 1189 1832 1228"></td></tr> <tr><td data-bbox="1093 1228 1377 1268">70</td><td data-bbox="1377 1228 1579 1268">53</td><td data-bbox="1579 1228 1832 1268"></td></tr> <tr><td data-bbox="1093 1268 1377 1308">81</td><td data-bbox="1377 1268 1579 1308">52</td><td data-bbox="1579 1268 1832 1308"></td></tr> </tbody> </table>			Contact A	Contact B	Voltage Drop	92	31		91	43		103	42		113	54		68	19		57	29		70	53		81	52		
Contact A	Contact B	Voltage Drop																														
92	31																															
91	43																															
103	42																															
113	54																															
68	19																															
57	29																															
70	53																															
81	52																															

170	Execute Procedure: SPIRE-FM-SFT-SPEC-JFET-OFF	SPECJFETSTAT: SSWJFET1V: SSWJFET2V: SLWJFET1V:	
171	Execute Procedure: SPIRE-FM-SFT-SLIA-OFF-P	SLIABITSTAT SLIAP5V SLIAP9V SLIAM9V	
172	Execute Procedure SPIRE-FM-SFT-MCU-OFF-P	MCUBITSTAT	
173	Execute Procedure SPIRE-FM-SFT-SCU-OFF-P	SCUTEMPSTAT SUBKSTAT	
174	Execute SPIRE-FM-SFT-DRCU-OFF-P	THSK: TM2N:	
175	Execute		
176	Carry out near real time analysis of the data to verify that: 0% < (Idd-Iss) / Idd < 8%		
	Final Spectrometer Connection		
177	Demate the 128-way BOB from CB 312200 P06		
178	Demate the 128-way BOB from CB 312200 J06		
179	Mate CB 312200 J06/P06		
180	Final Photometer Connection		
181	Demate the 128-way BOB from CB 312100 P04		
182	Demate the 128-way BOB from CB 312100 J04		
183	Mate CB 312100 J04/P04		
184	End of procedure		

8 De-mating of SIH-IS and SIH-SS for LPU Integration

8.1 Prerequisites

1. The pre-requisites outlined in chapter 4.1 of this procedure have been completed.

8.2 End State

The SIH is disconnected at the SVM-CB.

The FPU is protected from ESD damage by the safeing plugs on SVM-CB connectors.

The SPIRE SVM panel has been opened.

8.3 Notes

1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream continuously to discharge the harness.

Step-No.	Integration-Step-Description	Results/Remarks	Sign Off
1	De-mating of SIH-IS and SIH-SS		
	SIH-SH-03		
	Demate 312100 P04		
	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
	Cover 312100 P04 with ESD dust cover		
	SIH-SH-01		
	Demate 312200 P06		
	Mate SPIRE Safeing Plug Type-VI to SVM-CB 312200 J06		

	Cover 312200 P06 with ESD dust cover		
	SIH-SH-11		
	Demate 312300 P04		
	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J04		
	Cover 312300 P04 with ESD dust cover		
	Demate 312300 P01		
	Cover 312300 P01 with ESD dust cover		
	SIH-SH-13		
	Demate 312300 P03		
	Mate SPIRE Safeing Plug Type-VIII to SVM-CB 312300 J03		
	Cover 312300 P03 with ESD dust cover		
	Demate 312300 P02		
	Cover 312300 P02 with ESD dust cover		
	SIH-SH-02		
	Demate 312200 P05		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J05		
	Cover 312200 P05 with ESD dust cover		
	Demate 312100 P01A		
	Cover 312100 P01A with ESD dust cover		
	SIH-SH-04		

	Demate 312100 P01B		
	Cover 312100 P01B with ESD dust cover		
	Demate 312100 P03		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312100 J03		
	Cover 312100 P03 with ESD dust cover		
	SIH-SH-05		
	Demate 312100 P02		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312100 J02		
	Cover 312100 P02 with ESD dust cover		
	SIH-SH-06		
	Demate 3121200 P03		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J03		
	Cover 312200 P03 with ESD dust cover		
	SIH-SH-07		
	Demate 3121200 P04		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J04		
	Cover 312200 P04 with ESD dust cover		
	SIH-SH-08		
	Demate 3121200 P01		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J01		

	Cover 312200 P01 with ESD dust cover		
	SIH-SH-09		
	Demate 3121200 P02		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312200 J02		
	Cover 312200 P02 with ESD dust cover		
	SIH-SH-10		
	Demate 3121300 P06		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312300 J06		
	Cover 312300 P06 with ESD dust cover		
	SIH-SH-12		
	Demate 3121300 P05		
	Mate SPIRE Safeing Plug Type-VII to SVM-CB 312300 J05		
	Cover 312300 P05 with ESD dust cover		
	End of procedure		

9 Step by Step Procedure for Mating of SIH-IS and SIH-SS after LPU Integration

9.1 Prerequisites

1. The DCU, FCU and DPU have been mechanically and electrically integrated to the SVM panel and the SIH-SS-XX harnesses are all integrated but not mated to the SVM-CB.
2. The SIH-CS harnesses are still mated to the SPIRE FPU + JFP/JFS.
3. The SPIRE SVM panel has been closed.
4. The PLM has been mechanically integrated to the SVM
5. The SIH-IS-XX harnesses (XX= 1...13) are mechanically integrated onto the outside of the cryostat.
 - a. They are mated at the CVV internal FTHR connectors.
 - b. They are mated at the CVV-CB.
 - c. They are mechanically integrated to the SVM-I/F-CB's with the designated ESD safeing plugs and the UFT has been successfully completed.
6. The LPU Integration has been successfully completed.

9.2 Notes

1. SPIRE is ESD sensitive. Handling of these units is to be carried out by personnel suitably trained and equipped. Prior to carrying out the mating operations detailed below, the Pxx and Jxx connectors are to put in an ionized air stream for > 30 sec to discharge the harness.

No:	Activity	Remarks/Results	Sign off
	Mating of SIH-SS to SIH-IS		
1	SIH-SS-12		
2	Remove ESD dust cover from 312300 P05		

No:	Activity	Remarks/Results	Sign off
3	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312300 J05		
4	Mate 312300 J05 to P05		
5	SIH-SS-10		
6	Remove ESD dust cover from 3121300 P06		
7	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312300 J06		
8	Mate 312300 J06 to P06		
9	SIH-SS-11		
10	Remove ESD dust cover from 312300 P04		
11	Demate SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J04		
12	Mate 312300 P04 to J04		
13	Remove ESD dust cover from 312300 P01		
14	Mate 312300 P01 to J01		

No:	Activity	Remarks/Results	Sign off
15	SIH-SS-13		
16	Remove ESD dust cover from 312300 P03		
17	Demate SPIRE Safeing Plug Type-VIII from SVM-CB 312300 J03		
18	Mate 312300 P03 to J03		
19	Remove ESD dust cover from 312300 P02		
20	Mate 312300 P02 to J01		
21	SIH-SS-04		
22	Remove ESD dust cover from 312100 P01B		
23	Mate 312100 P01B to J01B		
24	Remove ESD dust cover from 312100 P03		
25	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312100 J03		
26	Mate 312100 P03 to J03		

No:	Activity	Remarks/Results	Sign off
27	SIH-SS-02		
28	Remove ESD dust cover from 312200 P05		
29	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J05		
30	Mate 312200 P05 to J05		
31	Remove ESD dust cover from 312100 P01A		
32	Mate 312100 P01A to J01A		
33	SIH-01		
34	Remove ESD dust cover from 312200 P06		
35	Demate SPIRE Safeing Plug Type-VI from SVM-CB 312200 J06		
36	Mate 312200 P06 to J06		
37	SIH-SS-05		
38	Remove ESD dust cover from 312100 P02		

No:	Activity	Remarks/Results	Sign off
39	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312100 J02		
40	Mate 312100 P02 to J02		
41	SIH-SS-06		
42	Remove ESD dust cover from 3121200 P03		
43	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J03		
44	Mate 312200 P03 to J03		
45	SIH-SS-07		
46	Remove ESD dust cover from 3121200 P04		
47	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J04		
48	Mate 312200 P04 to J04		
49	SIH-SS-08		
50	Remove ESD dust cover from 3121200 P01		

No:	Activity	Remarks/Results	Sign off
51	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J01		
52	Mate 312200 P01 to J01		
53	SIH-SS-09		
54	Remove ESD dust cover from 3121200 P02		
55	Demate SPIRE Safeing Plug Type-VII from SVM-CB 312200 J02		
56	Mate 312200 P02 to J02		
57	SIH-SS-03		
58	Demate 312100 P04		
59	Mate SPIRE Safeing Plug Type-V to SVM-CB 312100 J04		
60	Mate 312100 P04 to J04		
61	End of procedure		

10 Summary Sheets

10.1 Procedure Variation Summary

Herein are all changes of the procedure are shown.

No.	Para.	Variation Description	Action req.

Table 10.1-1: Procedure Variation Sheet

10.2 Non Conformance Report (NCR) Summary

NCR - No.	NCR - Title	Date	Open Closed	PA sig.

Table 10.2-1: Non-Conformance Record Sheet

10.3 Sign-off Sheet

This test has been successfully performed and all open issues are covered by NCR's or Procedure Variations.

	Date	Signature
Test Manager		
Operator		
PA Responsible		

11 APPENDICES

11.1 Procedure SPIRE Power On

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/Fail
1	Execute TCL script S102999SCVT005_ASDFSFTSPIR_P WR_ON_P.tcl	—	—	—	

Note: This script powers up the instrument DPU and DRCU prime. Therefore, the next two procedures, 11.2 and 11.3, are not executed manually.

11.2 Procedure SPIRE-FM-SFT-DPU-ON-P

Version	2.3
Date	28 Aug 2007
Purpose	To switch on the SPIRE DPU PRIME and start generating housekeeping
Initial configuration	SPIRE DPU and DRCU PRIME are switched off
Final configuration	SPIRE DPU PRIME is ON and SPIRE HK is being produced , SPIRE DRCU PRIME is OFF
Preconditions	<ul style="list-style-type: none"> • SPIRE FM DPU is electrically integrated with the Herschel Satellite • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • FUNCTIONAL TEST PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail Criteria	Nominal and critical HK reports start being generated at their nominal rates of 1Hz and 0.5Hz respectively.

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/Fail
1	Select DPU AND OBS PARAMETERS display is on the CCS	—	—	—	
2	Power ON the SPIRE DPU PRIME unit using the dedicated spacecraft LCL line and configure 1553 Spacecraft bus for SPIRE DPU PRIME (RT = 21)	—	—	—	
3	Wait for the boot software to produce at least 2 event packets (5,1)				

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/Fail
4	Execute TCL script SPIRE-FM-SFT-DPU-START-P-SP.tcl	—	—	—	
5	Check that Nominal and Critical HK packets are arriving at the CCS: SPIRE Nominal HK: <ul style="list-style-type: none"> • (type ,subtype) : (3,25) • APID : 0x502 SPIRE Critical HK: <ul style="list-style-type: none"> • (type ,subtype) : (3,25) • APID: 0x500 				
6	Check that THSK parameter is refreshing every second	THSK	Refreshing @ 1 Hz	—	
7	Check that TM2N parameter is incrementing by 1 every second	TM2N	Incrementing by 1 @ 1Hz	—	
8	Check that TM1N parameter is incrementing by 1 every 2 second	TM1N	Incrementing by 1 @ 0.5Hz		
Test Result (Pass/Fail):					

* Assuming that OBT is provided by the HCDMU is TAI, there should be a 33 second difference between OBS and CCS time (assuming CCS is using UTC). In the case the HCDMU is using UTC to specify the on board time, there should be no difference between THSK and the CCS/IEGSE system time.

11.3 Procedure SPIRE-FM-SFT-DRCU-ON-P

Version	2.3
Date	28 nd August 2007
Purpose	To switch on the SPIRE DRCU PRIME and start generating housekeeping
Initial configuration	SPIRE DPU PRIME is ON and DRCU PRIME is switched OFF
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
Preconditions	<ul style="list-style-type: none"> • SPIRE FM DRCU is electrically integrated with the Herschel Satellite • SPIRE DRCU is switched OFF • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • FUNCTIONAL TEST PARAMETERS display is selected on the CCS
Duration	4 minutes
Pass/Fail Criteria	DRCU voltages show expected 'ON' values

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Success/Failure
1	Execute TCL script SPIRE-FM-SFT-DRCU-START-P-STEP1.tcl	—	—	—	
2	Check that THSK parameter is not refreshing anymore	THSK	Not refreshing	—	
3	Check that TM2N parameter is not incrementing anymore	TM2N	Not incrementing	—	
4	Power ON the SPIRE DRCU PRIME unit using the dedicated spacecraft LCL line.	—	—	—	
5	Execute TCL script SPIRE-FM-SFT-DRCU-START-P-STEP2.tcl	—	—	—	
6	Check that THSK parameter is again refreshing every second	THSK	Refreshing @ 1Hz		
7	Check that TM2N parameter is again incrementing every second	TM2N	Incrementing by 1 @ 1Hz	—	
8	Check that the SCU/DCU voltages show nominal values	SCUP5V SCUP9V SCUM9V BIASP5V BIASP9V BIASM9V	~ 5.2 ± 0.5V ~ 9.0 ± 0.2V ~ -9.0 ± 0.2V ~ 5.1 ± 0.5V ~ 9.0 ± 0.2V ~ -9.0 ± 0.2V	—	
Test Result (Pass/Fail):					

11.4 Procedure SPIRE-FM-SFT-FUNC-SCU-01-P

Version	2.3
Date	28 nd August 2007
Purpose	SCU science packet generation check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
Final configuration	Unchanged
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail Criteria	Specified SCU HK parameters show expected increment.

Procedure Steps:

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-01-P.tcl	SCUFRAMECNT TM5N	0/31 0x3FFF/1		
Test Result (Pass/Fail):					

11.5 Procedure SPIRE-FM-SFT-FUNC-SCU-03-P

Version	2.3
Date	28 nd August 2007
Purpose	SCU DC thermometry check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and DC thermometry is ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	8 minutes
Pass/Fail Criteria	DC Thermometry channels show temperature readings according to the actual instrument temperature* *: At warm temperatures all channels should show short circuit RAW readings of -32768

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-03-P.tcl	—	—	—	—
2	Wait for the parameter BBFULLTYPE to get set to SCU_DC_Therm				
3	A few seconds later record the value of parameter SCUTEMPSTAT	SCUTEMPSTAT	0/FFFF/FFFF		
4	If the instrument is warm: Configure the SFT PARAMETERS display to show the RAW values of SCU DC thermometry channels. Record the RAW values of SCU DC thermometry	PUMPHTRTEMP PUMPHSTEMP EVAPHSTEMP SHUNTTEMP EMCFILTEMP SL0TEMP PL0TEMP OPTTEMP BAFTEMP BSMIFTEMP	- - - - - - - - -		

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
	channels. Nominal values should show a short circuit status (or RAW -32768). Non Nominal (Open Circuit Criterion): RAW reading in the range [0,-100]	SCAL2TEMP SCAL4TEMP SCALTEMP SMECIFTEMP SMECTEMP BSMTEMP	- - - - - -		
Test Result (Pass/Fail):					

11.6 Procedure SPIRE-FM-SFT-FUNC-SCU-06-P

Version	2.3
Date	28 nd August 2007
Purpose	SCU AC thermometry check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and DC thermometry is ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	2 minutes
Pass/Fail Criteria	AC Thermometry channel shows temperature readings according to the actual instrument temperature

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-06-P.tcl	—	—	—	—
2	Wait for the parameter BBFULLTYPE to get set to SCU_AC Therm				
3	A few seconds later record the value of parameter SUBKSTAT	SUBKSTAT	0/1/1		
4	<p>If the instrument is warm:</p> <p>Configure the SFT PARAMETERS display to show the RAW values of SCU AC thermometry channel.</p> <p>Only record the values of SCU AC thermometry channel if it indicates an open circuit.</p> <p>Open Circuit Criterion: RAW reading in the range [0, -100]</p>	SUBKTEMP	—		
Test Result (Pass/Fail):					

11.7 Procedure SPIRE-FM-SFT-FUNC-SCU-07-P

Version	2.2
Date	2 nd January 2007
Purpose	Sorption Cooler Heater Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and DC thermometry is ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail Criteria	Sorption cooler heat switches and pump heater show expected voltages

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-07-P.tcl	—	—	—	—
2	Wait for the parameter BBFULLTYPE to get set to Cooler_Htr_Chk	BBFULLTYPE	Cooler_Htr_Chk		
3	Record the value of parameter SPHSV – the Sorption Pump Heat Switch Voltage. <i>This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.</i>	SPHSV - mV	0/~323/0		
4	Record the value of parameter EVHSV – the Evaporator Heat Switch Voltage. <i>This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.</i>	EVHSV - mV	0/~323/0		
5	Record the value of parameter SPHTRV – the Sorption Pump Heater Voltage. <i>This voltage stays on for ~20 seconds. Wait for the voltage to go to zero to continue.</i>	SPHTRV - V	0/~8.8/0		
Test Result (Pass/Fail):					

11.8 Procedure SPIRE-FM-SFT-FUNC-SCU-04-P

Version	2.3
Date	28 nd August 2007
Purpose	Photometer Calibration Check (PRIME)
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON
Final configuration	Unchanged
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail Criteria	PCAL voltage and current agree with expected values

Procedure Steps:

Step	Description	Parameter Name - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	<p>Execute TCL script SPIRE-FM-SFT-FUNC-SCU-04-P.tcl</p> <p>The expected values during the test should be monitored when parameter BBFULLTYPE in the SFT PARAMETERS display is set to PCAL_Check. This usually happens about 30 seconds from the start of test execution.</p>	<p>PCALCARR - mA PCALV – V</p> <p>BBFULLTYPE</p>	<p>0.0/0.1/0.0 0.0/0.026/0.0</p> <p>PCAL_Check</p>		
Test Result (Pass/Fail):					

11.9 Procedure SPIRE-FM-SFT-FUNC-SCU-05-P

Version	2.3
Date	28 nd August 2007
Purpose	Spectrometer Calibration Check (PRIME)
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON
Final configuration	Unchanged
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	SCAL2 and SCAL4 voltage and currents agree with expected values

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SCU-05-P.tcl	—	—	—	
2	Wait for the parameter BBFULLTYPE to get set to SCAL4_Check	BBFULLTYPE	SCAL4_Check		
3	A few seconds later record the value of parameters SCAL4CURR and SCAL4V <i>These parameters are set back to 0 after ~20 seconds</i>	SCAL4CURR – mA SCAL4V – V	0.0/0.10/0.0 0.0/0.05/0.0		
4	Wait for the parameter BBFULLTYPE to get set to SCAL2_Check	BBFULLTYPE	SCAL2_Check		
5	A few seconds later record the values of parameters SCAL2CURR and SCAL2V <i>These parameters are set back to 0 after ~20 seconds</i>	SCAL2CURR – mA SCAL2V – V	0.0/0.10/0.0 0.0/0.05/0.0		
Test Result (Pass/Fail):					

11.10 Procedure SPIRE-FM-SFT-FUNC-MCU-01-P

Version	2.3
Date	28 th August 2007
Purpose	MCU (PRIME) Boot Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	MCU voltages and board temperatures show expected 'ON' values

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-MCU-01-P.tcl	—	—	—	—
2	Check that the MCU is booted up successfully.	MCUBITSTAT	0/1/1		
3	Check MCU HK parameter values and ensure that the values are refreshing.	MCUP5V MCUP14V MCUM14V MCUP15V MCUM15V MCUMACTEMP MCUSMECTEMP MCUBSMTEMP	~ 5.0 ± 0.2V ~ 14.0 ± 0.5V ~ -14.0 ± 0.5V ~ 15.0 ± 0.5V ~ -15.0 ± 0.7V ~300K ~300K ~300K		
Test Result (Pass/Fail):					

11.11 Procedure: SPIRE-FM-SFT-FUNC-MCU-02-P

Version	2.2
Date	2 nd January 2007
Purpose	MCU Nominal Frame Generation Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	Unchanged.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Specified MCU HK parameters show expected increment

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-MCU-02-P.tcl	MCUFRAMECNT	FM : 0/297	—	—
Test Result (Pass/Fail):					

11.12 Procedure SPIRE-FM-SFT-FUNC-BSM-01-P

Version	2.3
Date	28 nd August 2007
Purpose	BSM (PRIME) Chop/Jiggle Sensor Check.
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle sensors are ON.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MCU PRIME is booted. • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail criteria	HK Parameters CHOPSENSPWR and JIGGSENSPWR show expected ON values.

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-BSM-01-P.tcl	—	—	—	—
2	Check that the Chop and Jiggle sensors have switched on	CHOPSENSPWR JIGGSENSPWR	0/1/1 0/1/1		
Test Result (Pass/Fail):					

11.13 Procedure SPIRE-FM-SFT-BSM-OFF-P

Version	2.3
Date	28 nd August 2007
Purpose	BSM (PRIME) Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle sensors are ON.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. BSM Chop/Jiggle sensors are OFF.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MCU PRIME is booted. • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail criteria	HK Parameters CHOPSENSPWR and JIGGSENSPWR show expected OFF values.

Procedure Steps:

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute SPIRE-FM-SFT-BSM-OFF-P.tcl	—	—	—	—
2	Check that the power to the BSM sensors is switched off	CHOPSENSPWR JIGGSENSPWR	1/-/0 1/-/0		
Test Result (Pass/Fail):					

11.14 Procedure SPIRE-FM-SFT-FUNC-SMEC-01-P

Version	2.3
Date	28 th August 2007
Purpose	SMEC (PRIME) Encoder/LVDT Sensor Check.
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and LVDT are ON.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MCU PRIME is booted. • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail criteria	HK Parameters SMECENCPWR and SMECLVDTPWR show expected ON values.

Procedure Steps:

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-SMEC-01-P.tcl	—	—	—	—
2	Check that power to the SMEC LED and LVDT sensor is on	SMECENCPWR	0/-/1		
		SMECLVDTPWR	0/1/1		
Test Result (Pass/Fail):					

11.15 Procedure SPIRE-FM-SFT-SMEC-OFF-P

Version	2.3
Date	28 th August 2007
Purpose	SMEC (PRIME) Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and LVDT are ON.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. SMEC Encoder and LVDT are OFF.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MCU PRIME is booted. • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	3 minutes
Pass/Fail criteria	HK Parameters SMECENCPWR and SMECLVDTPWR show expected OFF values.

Procedure Steps:

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute SPIRE-FM-SFT-SMEC-OFF-P.tcl	—	—	—	—
2	Check that the power to the SMEC sensors is switched off	SMECENCPWR	1/-/0		
		SMECLVDTPWR	1/-/0		
Test Result (Pass/Fail):					

11.16 Procedure SPIRE-FM-SFT-FUNC-DCU-01-P

Version	2.2
Date	2 nd January 2007
Purpose	DCU science packet generation check for all Photometer and Spectrometer packet types (PF, PSW, PMW, PLW, SF, SSW and SLW)
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	Unchanged
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Specified DCU HK parameter shows expected increment

Procedure Steps:

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-DCU-01-P.tcl	DCUFRAMECNT	0/700		
Test Result (Pass/Fail):					

11.17 Procedure: SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P

Version	2.4
Date	10 th September 2007
Purpose	Photometer LIAs PRIME Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • Photometer LIAs are OFF • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS & SFT PARAMETERS displays are selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Specified Photometer LIA HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-DCU-04-PHOT-P.tcl	PLIABITSTAT	0/1/1		
2	Check Photometer LIA HK parameter values and ensure that the values are refreshing	PLIAP5V PLIAP9V PLIAM9V	0.0/-/ 5.2 ± 0.2V 0.0/-/ 11.5 ± 0.5V 0.0/-/-11.5 ± 0.5V		
3	On the DCU PARAMETERS display check that the LIA temperatures are slowly warming up. At switch-on it is possible that some of the LIA temperatures will be in soft or even hard limits. No action is required.	LIAP1TEMP to LIAP9TEMP	~ 290-300 K		
4	Wait for ~3 minutes before continuing with the SFTs	—	—	—	—
Test Result (Pass/Fail):					

11.18 Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-01

Version	1.1
Date	10 th September 2007
Purpose	Photometer JFETs Switch On
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON Photometer JFETs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Photometer JFET HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-ON-01.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—

11.19 Procedure: SPIRE-FM-SFT-PHOT-JFET-ON-02

Version	1.1
Date	10 th September 2007
Purpose	Photometer JFETs Switch On
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON Photometer JFETs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Photometer JFET HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-ON-02.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
2	<p>On the DCU PARAMETERS display check the JFET HK parameters</p> <p>Check with Instrument Team before proceeding with the next test.</p>	PSWJFETSTAT PMLWJFETSTAT PSWJFET1V PSWJFET2V PSWJFET3V PSWJFET4V PSWJFET5V PSWJFET6V PMWJFET1V PMWJFET2V PMWJFET3V PMWJFET4V PLWJFET1V PLWJFET2V TCJFETV	0x3F 0x7F -1.68 ± 0.02 V -1.59 ± 0.02 V -1.59 ± 0.02 V -1.68 ± 0.02 V -1.78 ± 0.02 V -1.68 ± 0.02 V -1.68 ± 0.02 V -1.88 ± 0.02 V -1.59 ± 0.02 V -1.88 ± 0.02 V -1.78 ± 0.02 V -1.59 ± 0.02 V -1.49 ± 0.02 V		
Test Result (Pass/Fail):					

11.20 Procedure: SPIRE-FM-SFT-PHOT-JFET-OFF

Version	1.0
Date	29 th August 2007
Purpose	Photometer JFETs Switch Off
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON Photometer JFETs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Photometer LIAs are ON Photometer JFETs are OFF
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Photometer JFET HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PHOT-JFET-OFF.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
2	<p>On the DCU PARAMETERS display check the JFET HK parameters</p> <p>Check with Instrument Team before proceeding with the next test.</p>	PSWJFETSTAT PMLWJFETSTAT PSWJFET1V PSWJFET2V PSWJFET3V PSWJFET4V PSWJFET5V PSWJFET6V PMWJFET1V PMWJFET2V PMWJFET3V PMWJFET4V PLWJFET1V PLWJFET2V TCJFETV	0 0 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V 0.0 V		
Test Result (Pass/Fail):					

11.21 Procedure: SPIRE-FM-SFT-PLIA-OFF-P

Version	2.4
Date	10 th September 2007
Purpose	Photometer LIAs PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Photometer LIAs are OFF
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • Photometer LIAs are ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	2 minutes
Pass/Fail criteria	Specified Photometer LIA HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-PLIA-OFF-P.tcl	PLIABITSTAT	1/-0		
2	Check Photometer LIA HK parameter values	PLIAP5V PLIAP9V PLIAM9V	5.2 ± 0.2V/-0.0 11.5 ± 0.5V/-0.0 -11.5 ± 0.5V/-0.0		
Test Result (Pass/Fail):					

11.22 Procedure: SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P

Version	2.4
Date	10 th September 2007
Purpose	Spectrometer LIAs PRIME Check
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer LIAs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • Spectrometer LIAs are OFF • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS & DCU PARAMETERS displays are selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Specified Spectrometer LIA HK parameters show expected ON values

Procedure Steps for FM:

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-FUNC-DCU-04-SPEC-P.tcl	SLIABITSTAT	0/1/1		
2	Check Spectrometer LIA HK parameter values and ensure that the values are refreshing	SLIAP5V SLIAP9V SLIAM9V	0.0/-/ 5.2 ± 0.2V 0.0/-/ 11.5 ± 0.5V 0.0/-/11.5 ± 0.5V		
3	On the DCU PARAMETERS display check that the LIA temperatures are slowly warming up. At switch-on it is possible that some of the LIA temperatures will be in soft or even hard limits. No action is required.	LIAS1TEMP to LIAS3TEMP	~ 290-300 K		
4	Wait for ~3 minutes before continuing with the SFTs	—	—	—	—
Test Result (Pass/Fail):					

11.23 Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-01

Version	1.1
Date	10 th September 2007
Purpose	Spectrometer JFETs Switch On
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON Spectrometer JFETs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Spectrometer JFET HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-ON-01.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—
2	On the DCU PARAMETERS display check the JFET HK parameters Check with Instrument Team before proceeding with the next test.	SPECJFETSTAT SSWJFET1V SSWJFET2V SLWJFET1V	7 -1.49 ± 0.1 V -1.49 ± 0.1 V -1.49 ± 0.1 V		
Test Result (Pass/Fail):					

11.24 Procedure: SPIRE-FM-SFT-SPEC-JFET-ON-02

Version	1.1
Date	10 th September 2007
Purpose	Spectrometer JFETs Switch On
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON Spectrometer JFETs are ON
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Spectrometer JFET HK parameters show expected ON values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-ON-02.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—
2	On the DCU PARAMETERS display check the JFET HK parameters Check with Instrument Team before proceeding with the next test.	SPECJFETSTAT SSWJFET1V SSWJFET2V SLWJFET1V	7 -1.68 ± 0.02 V -2.07 ± 0.02 V -1.59 ± 0.02 V		

11.25 Procedure: SPIRE-FM-SFT-SPEC-JFET-OFF

Version	1.0
Date	29 th August 2007
Purpose	Spectrometer JFETs Switch Off
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON Spectrometer JFETs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced AC/DC thermometry is ON MCU PRIME is booted Spectrometer LIAs are ON Spectrometer JFETs are OFF
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • DCU PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Spectrometer JFET HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SPEC-JFET-OFF.tcl Wait for the script to finish executing before proceeding with the next step	—	—	—	—

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
2	<p>On the DCU PARAMETERS display check the JFET HK parameters</p> <p>Check with Instrument Team before proceeding with the next test.</p>	<p>SPECJFETSTAT</p> <p>SSWJFET1V</p> <p>SSWJFET2V</p> <p>SLWJFET1V</p>	<p>0</p> <p>0.0 V</p> <p>0.0 V</p> <p>0.0 V</p>		
Test Result (Pass/Fail):					

11.26 Procedure: SPIRE-FM-SFT-SLIA-OFF-P

Version	2.4
Date	10 th September 2007
Purpose	Spectrometer LIAs PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer LIAs are ON
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted. Spectrometer LIAs are OFF
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • Spectrometer LIAs are ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	2 minutes
Pass/Fail criteria	Specified Spectrometer LIA HK parameters show expected OFF values

Step	Description	Parameter	Expected Values Before/ After	Actual Values Before /After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SLIA-OFF-P.tcl	SLIABITSTAT	1/-/0		
2	Check Photometer LIA HK parameter values	SLIAP5V SLIAP9V SLIAM9V	5.2 ± 0.2V/-/0.0 11.5 ± 0.5V/-/0.0 -11.5 ± 0.5V/-/0.0		
Test Result (Pass/Fail):					

11.27 Procedure SPIRE-FM-SFT-MCU-OFF-P

Version	2.3
Date	28 nd August 2007
Purpose	MCU PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is booted.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON and MCU PRIME is OFF.
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MCU PRIME is ON. • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	2 minutes
Pass/Fail criteria	Specified MCU HK Parameter shows expected value.

Procedure Steps:

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute SPIRE-FM-SFT-MCU-OFF-P.tcl	—	—	—	—
2	Check that the MCU is switched off	MCUBITSTAT	1/-/0		
Test Result (Pass/Fail):					

11.28 Procedure SPIRE-FM-SFT-SCU-OFF-P

Version	2.3
Date	28 nd August 2007
Purpose	SCU PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON.
Final configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is OFF
Constraints	<ul style="list-style-type: none"> • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	2 minutes
Pass/Fail criteria	Specified SCU HK Parameters show expected value.

Procedure Steps:

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-SCU-OFF-P.tcl	—	—	—	—
2	A few seconds later record the value of parameter SCUTEMPSTAT	SCUTEMPSTAT	FFFF/-/0		
3	A few seconds later record the value of parameter SUBKSTAT	SUBKSTAT	1/-/0		
Test Result (Pass/Fail):					

11.29 Procedure SPIRE Power OFF

Step	Description	Parameter	Expected Values Before/After	Actual Values Before/After	Pass/Fail
1	Execute TCL script S102999SCVT007_ASDFSFTSPIR_P WR_OFF_P.tcl	—	—	—	

Note: This script powers down the instrument DPU and DRCU prime. Therefore, the next two procedures, 11.30 and 11.31, are not executed manually.

11.30 Procedure: SPIRE-FM-SFT-DRCU-OFF-P

Version	2.2
Date	2 nd January 2007
Purpose	DRCU PRIME Switch OFF
Initial configuration	SPIRE DPU and DRCU PRIME are ON and SPIRE HK is being produced and AC/DC thermometry is ON.
Final configuration	SPIRE DPU PRIME is ON, SPIRE DRCU PRIME is OFF and SPIRE HK is not being produced .
Constraints	<ul style="list-style-type: none"> • SPIRE-FM-SFT-SCU-OFF has been executed. • SPIRE DRCU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	THSK and TM2N stop refreshing/incrementing

Step	Description	Parameter - Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Execute TCL script SPIRE-FM-SFT-DRCU-OFF.tcl	—	—	—	
2	Check that THSK parameter is not refreshing anymore	THSK	Not refreshing	—	
3	Check that TM2N parameter is not incrementing anymore	TM2N	Not incrementing	—	
4	Power OFF the SPIRE DRCU PRIME unit.	—	—	—	
Test Result (Pass/Fail):					

11.31 Procedure: SPIRE-FM-SFT-DPU-OFF-P

Version	2.2
Date	2 nd January 2007
Purpose	DPU PRIME Switch OFF
Initial configuration	SPIRE DPU PRIME is ON but not generating HK.
Final configuration	SPIRE DPU PRIME is OFF.
Constraints	<ul style="list-style-type: none"> • SPIRE-FM-SFT-DRCU-OFF has been executed. • SPIRE DPU PRIME is switched ON • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • SFT PARAMETERS display is selected on the CCS
Duration	5 minutes
Pass/Fail criteria	Power to SPIRE DPU PRIME is OFF

Procedure Steps:

Step	Description	Parameter – Unit	Expected Values Before/ During/ After	Actual Values Before/ During/ After	Success/ Failure
1	Power OFF the SPIRE DPU PRIME unit.	—	—	—	
Test Result (Pass/Fail):					

11.32 SPIRE-SAFE-SWITCH-OFF

Version	2.3
Date	10 th September 2007
Purpose	To switch OFF the SPIRE instrument if an anomaly should occur
Initial configuration	SPIRE can be on ANY configuration as specified on the procedure steps
Final configuration	SPIRE is OFF
Preconditions	<ul style="list-style-type: none"> • SPIRE FM DPU is electrically integrated with the Herschel Satellite • SPIRE MIB PRIME is imported in the CCS database. • CCS is up and running • FUNCTIONAL TEST PARAMETERS display is selected on the CCS
Duration	~5-8 minutes
Pass/Fail Criteria	SPIRE is OFF. All instrument subsystems are completely powered OFF.

Note:

All HK parameters relevant to this procedure can be located on the **FUNCTIONAL TEST PARAMETERS CCS display**. The exact name of the script to be executed at each step depends on whether the Prime or Redundant instrument is switched on.

Step	Description	Parameter - Unit	Display	Actual value before/ after
1	Check to see if the Photometer LIAs are on If PLIABITSTAT=1 then execute SPIRE-FM-SFT-PLIA-OFF-<P/R>.tcl	PLIABITSTAT	0 or 1	
2	Check to see if the Spectrometer LIAs are on If SLIABITSTAT=1 then execute SPIRE-FM-SFT-SLIA-OFF-<P/R>.tcl	SLIABITSTAT	0 or 1	

Step	Description	Parameter - Unit	Display	Actual value before/ after
3	Switch off the Phot and Spec JFETs: Execute SPIRE-FM-SFT-PHOT-JFET-OFF.tcl Execute SPIRE-FM-SFT-SPEC-JFET-OFF.tcl	-	-	-
4	Check to see if the BSM is on If CHOPSENSPWR=1 or JIGGSENSPWR=1, then execute SPIRE-FM-SFT-BSM-OFF-<P/R>.tcl	CHOPSENSPWR JIGGSENSPWR	0 or 1 0 or 1	
5	Check to see if the SMEC is on If SMECENCPWR=1 or SMECLVDTPWR=1, then execute SPIRE-FM-SFT-SMEC-OFF-<P/R>.tcl	SMECENCPWR SMECLVDTPWR	0 or 1 0 or 1	
6	Check to see if the MCU is on If MCUBITSTAT=1 then execute SPIRE-FM-SFT-MCU-OFF-<P/R>.tcl	MCUBITSTAT	0 or 1	
7	Check to see if the SCU DC/AC thermometry is on If SUBKSTAT=1 or SCUTEMPSTAT≠0, then execute SPIRE-FM-SFT-SCU-OFF-<P/R>.tcl	SUBKSTAT SCUTEMPSTAT	0 or 1 ≠ 0	
8	Execute Procedure SPIRE-FM-SFT-DRCU-OFF-<P/R>.tcl	TM2N THSK	Should stop updating	
9	Execute Procedure SPIRE-FM-SFT-DPU-OFF-<P/R>.tcl	n/a	n/a	



END OF DOCUMENT

	Name	Dep./Comp.		Name	Dep./Comp.
	Alberti von Mathias Dr.	ASG23		Schmidt Thomas	AED15
	Baldock Richard	FAE12		Schuler Günter	ASA42
	Barlage Bernhard	AED13		Schweickert Gunn	ASG23
	Bayer Thomas	ASA42		Sonn Nico	ASG51
	Brune Holger	ASA45		Steininger Eric	AED32
	Edelhoff Dirk	AED2	X	Stritter Rene	AED11
	Fehringer Alexander	ASG13		Suess Rudi	OTN/ASA44
	Fricke Wolfgang Dr.	AED 65		Theunissen Martijn	DSSA
	Geiger Hermann	ASA42		Vascotto Riccardo	AED11
	Grasl Andreas	OTN/ASA44		Wagner Klaus	ASG23
X	Grasshoff Brigitte	AET12	X	Wietbrock Walter	AET12
X	Hamer Simon	Terma		Wöhler Hans	ASG23
	Hendrikse Jeffrey	HE Space		Wössner Ulrich	ASE252
X	Hendry David	Terma		Zumstein Armin	ASQ42
	Hengstler Reinhold	ASA42			
	Hinger Jürgen	ASG23			
	Hohn Rüdiger	AED65			
	Hölzle Edgar Dr.	AED32			
	Hopfgarten Michael	AED32			
	Huber Johann	ASA42			
	Hund Walter	ASE252			
X	Idler Siegmund	AED312			
	Ivány von András	FAE12			
	Jahn Gerd Dr.	ASG23			
	Kalde Clemens	ASM2			
	Kameter Rudolf	OTN/ASA42	X	ESA/ESTEC	ESA
	Kettner Bernhard	AET42	X	Thales Alenia Space Cannes	TAS-F
	Knoblauch August	AET32		Thales Alenia Space Torino	TAS-I
X	Koelle Markus	ASA43			
X	Koppe Axel	AED312		Instruments:	
	Kroeker Jürgen	AED65		MPE (PACS)	MPE
	La Gioia Valentina	Terma	X	RAL (SPIRE)	RAL
	Lang Jürgen	ASE252		SRON (HIFI)	SRON
	Langenstein Rolf	AED15			
	Langfermann Michael	ASA41			
	Martin Olivier	ASA43		Subcontractors:	
X	Maukisch Jan	ASA43		Austrian Aerospace	AAE
	Much Christoph	ASA43		Austrian Aerospace	AAEM
	Müller Jörg	ASA42		BOC Edwards	BOCE
	Müller Martin	ASA43		Dutch Space Solar Arrays	DSSA
	Peltz Heinz-Willi	ASG13		EADS Astrium Sub-Subsyst. & Equipment	ASSE
	Pietroboni Karin	AED65		EADS CASA Espacio	CASA
	Platzer Wilhelm	AED2		EADS CASA Espacio	ECAS
	Reichle Konrad	ASA42		European Test Services	ETS
	Runge Axel	OTN/ASA44		Patria New Technologies Oy	PANT
	Sauer Maximilian Dr.	AED65		SENER Ingenieria SA	SEN
	Schink Dietmar	AED32		Thales Alenia Space, Antwerp	TAS-ETCA