#### SSTD Incoming Inspection Report



#### SSTD Incoming Inspection Report

Spacecraft/Project	HERSCHEL / SPIRE	Document Number	SPIRE-UCF-REP-002203	]	Issue 1
Sub System	Spectrometer Cal Source	Date	8th November 2004	]	Model PFM
		 CONTAINER INSP	ECTION	t	

TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or		
handling provisions		N/A
Security / Locking Fitted		N/A
Markings for destination and description		N/A
Warning labels relating to handling lifting and stacking limits		N/A
Any additional Comments	Delivered By Hand	See Remarks

TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging		N/A
Internal padding / packaging required		N/A
Mounting provisions secure		N/A
Any additional Comments		See
	Double Bagged in a Padded Bag	Remarks

	ENVIROMENTAL M	ONITORS
		Shook Sensors Triggard Information
		5a 10a 15a
Temperature	Condition	X Axis
		Y Axis
Humidity	Condition	Z Axis



CHECK LIST	REMARKS	RESULTS
Contents against shipping list		CORRECT
Instrument label		CORRECT
Note status of external		
contamination		ACCEPTABLE
Degradation of paintwork		
or Coating?		ACCEPTABLE
Fasteners correctly locked?	None	SEE REMARKS
Check protective covers are		
correctly labelled and fitted?		CORRECT
	Peter Hargrave mentioned that one of the rear cover retaining screws had had its head sheared off	
Additional Comments	during assembly, leaving the stud behind, it was agreed that we could use as is. PH to raise NCR. See	
	Photo attached.	SEE REMARKS



CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		PASS
Damaged Sockets		NONE
Internal Debris		NONE
		NONE
Connector Covers fitted		NONE
Connector Savore Fitted		
		NONE
EMC Covers Fitted		NONE
RED Tag Item / Green Tag Items fitted		NONE
Additional Comments	See photo's of both connectors attached	
		See remark



Check	REMARKS	RESULTS
End Item Data Pack	HSO-CDF-EIDP-071 Issue 1.1	YES
Transportaion Documents	Hand Carried	See Remarks
Packing un- Packing instructions	Unpacked by peter Hargrave	N/A
Additional Comments		

Sub System	Spectrometer Cal Source	Date	8th November 2004	Model PFM
		Verification o	f Interfaces	
lechanical interfa	ce: dimensions specified in the int	erface control documents such a	S	
ance flatnose of a	infaces location of fixing balan and		and recorded	
nass, flatness of si ecord Test Report	urfaces, location of fixing holes and Number, or confirm that measure	d overall dimensions should be in ment result is included in delivery	easured accurately and recorded.	
nass, flatness of si ecord Test Report	urfaces, location of fixing holes and Number, or confirm that measure	d overall dimensions should be n ment result is included in delivery	easured accurately and recorded. documentation, (EIDP).	
nass, flatness of si lecord Test Report	urfaces, location of fixing holes and Number, or confirm that measure	d overall dimensions should be n ment result is included in delivery	easured accurately and recorded.	
nass, flatness of si ecord Test Report INSPECTION / TE	urfaces, location of fixing holes and Number, or confirm that measure STREPORT NUMBER	d overall dimensions should be m ment result is included in delivery N/A	easured accurately and recorded. documentation, (EIDP).	on this inspection
mass, flatness of si tecord Test Report	urfaces, location of fixing holes and Number, or confirm that measure ST REPORT NUMBER	d overall dimensions should be m ment result is included in delivery N/A	easured accurately and recorded. documentation, (EIDP).	on this inspection
nass, flatness of su lecord Test Report INSPECTION / TE	urfaces, location of fixing holes and Number, or confirm that measure STREPORT NUMBER	N/A of connectors against interface of	easured accurately and recorded. documentation, (EIDP).	on this inspection
nass, flatness of si tecord Test Report INSPECTION / TE Electrical interface arried as part of me functional testing; f	urfaces, location of fixing holes and Number, or confirm that measure STREPORT NUMBER	N/A of connectors against interface of has been done. should be noted.	CHECKED N/A	on this inspection
mass, flatness of su Record Test Report INSPECTION / TE Electrical interface arried as part of me functional testing: f	urfaces, location of fixing holes and Number, or confirm that measure STREPORT NUMBER es: verifying the location and types echanical verification, confirm this inal functional test report number s	N/A of connectors against interface of has been done. should be noted.	easured accurately and recorded. documentation, (EIDP).	on this inspection

### SSTD Incoming Inspection Report

		Document Number	SPIRE-UCF-REF-002203	issue
Sub System	Spectrometer Cal Source	Date	8th November 2004	Model PFM
		EXTRA COMMENT	SHEET	



Photo 1 SCAL PFM Bagged Prior to Inspection

Photo 2 SCAL Showing Prime & Redundant clearly Marked





Photo 3 & 4 Prime & Redundant Connector Pin Alignment OK





Photo 5 & 6 showing stud in Hole (as stated on External Visual Inspection sheet)





Photo 6 View into end of SCAL.