

Spacecraft/Project	HERSCHEL / SPIRE	Doc	ument Number	SPIRE-RAL-REP-002411	]	Issue	1
Sub System	PCAL	Date	9	21st April 2005	]	Model	PFM
CONTAINER INSPECTION							


TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or handling provisions		N/A
Security / Locking Fitted		N/A
Markings for destination and description		N/A
Warning labels relating to handling lifting and stacking limits		N/A
Any additional Comments	Hand delivered by P Hargrave	See Remarks

TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging		Checked
laternal radding ( nachoning required		Chaolicad
Internal padding / packaging required		Checked
Mounting provisions secure		N/A
Any additional Comments	No Environmental Monitors fitted	See Remarks

ENVIROMENTAL MONITORS						
Temp Monitors Humiditiy Monitors Shock Sensors Triggerd Information						
		5g	10g	15g	25g	50g
Fitted:	X Axis					
	Y Axis					
Condition:	Z Axis		1			1
	Humiditiv Monitors	Humiditiy Monitors Fitted: X Axis Y Axis	Humiditiy Monitors Shock   5g 5g   Fitted: X Axis   Y Axis Y Axis	Humiditiy Monitors Shock Sensors Tristed:   Fitted: X Axis   Y Axis Y Axis	Humiditiy Monitors Shock Sensors Triggerd Info   5g 10g   Fitted: X Axis   Y Axis Y Axis	Humiditiv Monitors   Shock Sensors Triggerd Information     5g   10g   15g   25g     Fitted:

Spacecraft/Project	HERSCHEL / SPIRE	Document Number	SPIRE-RAL-REP-002411	Issue	1
Sub System	PCAL	Date	21st April 2005	Model	PFM
			INSPECTION	, <u> </u>	

CHECK LIST	REMARKS	RESULTS
Contonto againat abinning list		NI/A
Contents against shipping list		N/A
Instrument label		Correct
Note status of external contamination	Staining and marks around the body of the PCAL	See Remarks
Degradation of paintwork or Coating?		See Remarks
Fasteners correctly locked?		N/A
Check protective covers are correctly labelled and fitted?		N/A
Additional Comments	Contamination makes this ITEM unacceptable for Flight.	See Remarks



CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		N/A
Damaged Sockets		N/A
Internal Debris		None
Connector Covers fitted		N/A
Connector Savers Fitted		N/A
EMC Covers Fitted		N/A
RED Tag Item / Green Tag Items fitted		N/A
Additional Comments	Wire Tails protrude from Turret solder connections, Right hand end turret wire entering solder joint Insulation has not been stripped Back enough Solderjoint Fails inspection	See remark

Spacecraft/Project	HERSCHEL / SPIRE	Document Number	SPIRE-RAL-REP-002411	Issue 1
Sub System	PCAL	Date	21st April 2005	Model PF
		EXTRA COMMENT SH	EET	
	L			


Spacecraft/Project	HERSCHEL / SPIRE	Document Number	SPIRE-RAL-REP-002411	Issue 1
Sub System	PCAL	Date	21st April 2005	Model PFM

### **DOCUMENTATION CHECK LIST**

Check	REMARKS	RESULTS
End Item Data Pack	Electronic version of EIDP already available nothing delivered with item	No
Transportaion Documents	See above	No
Packing un- Packing instructions	See above	No
Additional Comments		

Verification of Interfaces

<b>Mechanical interface:</b> dimensions specified in the interface control documents such as mass, flat dimensions should be measured accurately and recorded. Record Test Report Number, or confirm documentation, (EIDP).	
INSPECTION / TEST REPORT NUMBER	CHECKED N/A for this inspection
<b>Electrical interfaces:</b> verifying the location and types of connectors against interface control docu confirm this has been done. Functional testing: final functional test report number should be noted.	
INSPECTION / TEST REPORT NUMBER	CHECKED N/A for this inspection



## FLIGHT MODEL

# PCAL-PFM-000



