Spacecraft/Project HERSCHEL / SPIRE Document Number SPIRE-RAL-REP- 002764 Issue 1.0 Sub System L0 Straps pre Gold Plating PFM Date 30-Oct-06 Model **INCOMING INSPECTION REPORT** FROM TO MSSL Project Mullard Space Science Lab, Surrey Rutherford Appleton Laboratory Space Science and Technology Department Chilton DIDCOT OXON OX11 0QX Applicable sections **Drawings / Documents Attached** Containers Photo's Yes **External Visual Inspection** Yes **External Connector** No **Documentation** Yes **Verification of Interfacess** No **Extra Comments Sheets INSPECTION CONDUCTED BY WITNESS BY** DATE NAME DATE NAME Eric Clark (PA) 30/10/2006 30/10/2006 Alan Pearce

Spacecraft/Project HERSCHEL / SPIRE	Document Number SPIRE-RAL-REP- 002764 Issue	1.0
Sub System L0 Straps pre Gold Plating	Date 30-Oct-06 Model	PFM
	CONTAINER INSPECTION	
TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or handling provisions	See Comments	See Remarks
Security / Locking Fitted	See Comments	See Remarks
Markings for destination and description	See Comments	See Remarks
Warning labels relating to handling lifting and stacking limits	See Comments	See Remarks
Any additional Comments	ITEMS Delivered by Hand from MSSL to Alan Pearce	See Remarks
TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging	See Comments	See Remarks
nternal padding / packaging required	See Comments	See Remarks
Mounting provisions secure	See Comments	See Remarks
Any additional Comments	STAPS are mounted on Carriers to prevent damage or distortion in transit, Ready for Gold Plating. Delivered by hand no environmental Monitors fitted	See Remarks
	ENVIROMENTAL MONITORS	
Temp Monitors Humiditiy Monitors	Shock Sensors Triggerd Information 5g 10g 15g 25g	50g

Spacecraft/Project	HERSCHEL / SPIRE]	Document Number	SPIRE-RAL-REP-002764]	Issue	1.0]
Sub System	L0 Straps pre Gold Plating		Date	30-Oct-06		Model	PFM]
			NSTRIMENT VISUAL	INSPECTION	1			

CHECK LIST	REMARKS	RESULTS
Contents against shipping list	Pump and Evaporator End parts only delivered	See Remarks
Instrument label	Parts were not labeled	See Remarks
Note status of external contamination	Pump strap had one screw not fully screwed in, and mark on one section, see Photos. Evaporator Strap OK	See Remarks
Degradation of paintwork or Coating?	As Above	See Remarks
Fasteners correctly locked?	As Above	See Remarks
Check protective covers are correctly labelled and fitted?		N/A
Additional Comments		None

Sub System L0 Straps pre Gold I	Plating 30-Oct-06	Model PFM
	INSPECTION OF ALL CONNECTORS	
OUEOV LIOT	DEMARKS (LIST CONNECTOR NUMBERS)	DECLU TO
CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		N/A
Damaged Sockets		N/A
Internal Debris		N/A
Connector Covers fitted		N/A
Connector Savers Fitted		
EMC Covers Fitted		N/A
RED Tag Item / Green Tag Items fitted		N/A


Check	REMARKS	RESULTS
nd Item Data Pack	Electronic Data Pack supplied under review	Yes
ransportaion Documents		No
acking un- Packing instructions	With Items including Inspection records (completed at RAL for incoming inspection	Yes
Additional Comments		None
	Verification of Interfaces	
	ified in the interface control documents such as mass, flatness of surfaces, location of fixing holes	
limensions should be measured accurat	ified in the interface control documents such as mass, flatness of surfaces, location of fixing holes ely and recorded. Record Test Report Number, or confirm that measurement result is included in	delivery

Spacecraft/Project HERSCHEL / SPIRE Document Number SPIRE-RAL-REP- 002764 Issue 1.0 Sub System L0 Straps pre Gold Plating Date 30-Oct-06 Model PFM **EXTRA COMMENT SHEET** The Delivery consists of three support frames with the following straps mounted on them. Evaporator Strap Supplied to RAL for Gold Plating. Visual inspection only no electrical measurements were made Pump Strap Supplied to RAL for Gold Plating. Visual inspection only no electrical measurements were made Spectrometer Strap Not Part of this delivery

Pump & Evaporator Lo Straps Transit Box.




Evaporator Strap General View




Evaporator Lower View.




Evaporator Top View



Pump General View



Pump Showing screw not fully down



Pump Showing Mark on lower section.



Pump View from under support Frame

