

Reference : LAM.SSP.SPI.NCR.050829_01

PROJECT : Herschel			NON CONFORMANCE REPORT			
Subsystem : SMECm		Unit : SPIRE				
Model : FM			Identif.			
NCR occured during : Manufacture [] Inspec [] Test [] Integ [] Other [] NCR Title : Thermal sensor cable attachment						
NCR Description : The cable diameter of the thermal sensosr provided by RAL is not compatible with the geometry of the jumpers which were designed to maintain the cable.						
Originator Name : G. Rousset			Date 29/08/2005	Signa	Signature :	
Cause of the NCR : Deviation during manufact			sture	Major []	Minor [X]	
Disposition/Corrective Action :				Corrective acti Name : Date :		
MRB date : 09/08/2005			IRB Minute Ref : No report			
MRB Conclusion: The jumper will not be used no longer and the cable will be binded with cord						
Responsible for corrective Actions :			All Corrective Actions Carried Out :			
			Yes [x]	No []	No [] Signature	
RAL Project manager :		L	Date	Sigi	nature	
RAL PA/QA						
LAM Project manager	29/08/2005			MS		
LAM PA/QA	29/08/2005				Latter.	









