



PROJECT : Herschel		NON CONFORMANCE REPORT	
Subsystem : SMECm		Unit : SPIRE	
Model :		Identif. Motor Coil N° 520312	
NCR occured during : Manufacture [] Inspec [X] Test [] Integ [] Other []			
NCR Title : Wrong location of one of the holes used for the screws of the aluminium frame of the coil			
NCR Description : One of the hole used for the screws is shifted wrt the nominal location and the screws can't be installed			
Originator Name : G. Rousset		Date 03/02/2006	Signature : 
Cause of the NCR : Deviation during manufacture		Major []	Minor [X]
Disposition/Corrective Action :		Corrective action carried out : Name : Date :	
MRB date : 29/06/2005		MRB Minute Ref : No report	
MRB Conclusion: don't use the screw is this location the frame will be attached tyhanks to the 3 other screws			
Responsible for corrective Actions :		All Corrective Actions Carried Out : Yes [] No []	
	Date	Signature	
RAL Project manager :			
RAL PA/QA			
LAM Project manager	03/02/2005		
LAM PA/QA	03/02/2005		

Missing screw

