

PROJECT : Herschel		NON CONFORMANCE REPORT	
Subsystem : SMECm		Unit : SPIRE	
Model :		Identif.: Motor Coil 520312 Drawing ref : SPI-MEC-52-DD-01-D	
NCR occured during : Manufacture [] Inspec [] Test [X] Integ [] Other []			
NCR Title : Thickness of the coil			
NCR Description : The thickness of the coil is higher than the specification : 12,42 mm instead of 12,2 mm			
Originator Name : G. Rousset		Date 03/02/2006	Signature : 
Cause of the NCR : Deviation during manufacture		Major []	Minor [X]
Disposition/Corrective Action :		Corrective action carried out : Name : Date :	
MRB date : 29/06/2005		MRB Minute Ref : No report	
MRB Conclusion: Use as is			
Responsible for corrective Actions :		All Corrective Actions Carried Out : Yes [] No []	
	Date	Signature	
RAL Project manager :			
RAL PA/QA			
LAM Project manager	29/06/2005		
LAM PA/QA	29/06/2005		