Spire SPR/SCR Reporting System

Main | New Report | Search | Help

Search Results

There are 15 matches. Key: Low High Normal

[Display reports on multiple pages] View: [Title only] [Summary] [Full]

Sort by: [Report] [Priority] [Title] [Module] [Modified Date]

SPR-0231	No MCU enginering frames generated	*Module: DRCU Simulator* *Modified: 26-07-06* *Status: Implemented*	view edit
SPR-0230	Event packets generated upon request for fixed number of science frames	*Module: DRCU Simulator* *Modified: 26-07-06* *Status: Implemented*	view edit
SPR-0166	SetPhotoSampFreq command does not appear to work	*Module: DRCU Simulator* *Modified: 26-07-06* *Status: Implemented*	view edit
SPR-0514	DCU telemetry generation config gets reset when data mode is set	*Module: DRCU Simulator* *Modified: 19-07-06* *Status: Issued*	view edit
SPR-0466	Number of BSM and SMEC frames generated does not agree with the expected number	*Module: DRCU Simulator* *Modified: 24-01-06* *Status: Issued*	view edit
SPR-0465	Number of MCU ENG frames generated does not agree with the expected number	*Module: DRCU Simulator* *Modified: 24-01-06* *Status: Issued*	view edit
SPR-	The sampling rate for DCU frames is not consistent	*Module: DRCU Simulator* *Modified: 24-01-*	view edit

0464	with the commanded rate	*06* *Status: Issued*	
SPR-0463	The DRCU simulator configuration changes without direct commanding from the DPU	*Module: DRCU Simulator* *Modified: 24-01-06* *Status: Issued*	view edit
SPR-0458	DRCU simulator generates incorrect number of frames	*Module: DRCU Simulator* *Modified: 23-12-05* *Status: Issued*	view edit
SPR-0457	The SMEC frame times are inconsistent with the requested times	*Module: DRCU Simulator* *Modified: 22-12-05* *Status: Issued*	view edit
SPR-0456	The SCU frame times are inconsistent with the requested times	*Module: DRCU Simulator* *Modified: 22-12-05* *Status: Issued*	view edit
SPR-0455	Photometer Full Array frame times are inconsistent with the requested times	*Module: DRCU Simulator* *Modified: 22-12-05* *Status: Issued*	view edit
SPR-0446	Low-speed links lost	*Module: DRCU Simulator* *Modified: 10-11-05* *Status: Issued*	view edit
SPR-0393	Erroneous DCU frame generation	*Module: DRCU Simulator* *Modified: 09-06-05* *Status: Issued*	view edit
SPR-0351	Mismatch between CID of commands sent to DRCU Sim. and response echo	*Module: DRCU Simulator* *Modified: 18-10-04* *Status: Issued*	view edit