Issue: V1.0 Page 1/12 Date: 10/01/2001

SPIRE-ICS-PRJ-000545

SPIRE ICC

User Requirements Documents Photometer Processing

Written by:

S.J. Oliver W. Gear Marc Sauvage

Comments

Issue 1.0

Wednesday, 10 January 2001

| SPIR | E ICC1 | | | |
|----------------|--|--|--|--|
| User | User Requirements Documents1 | | | |
| Photo | ometer Processing1 | | | |
| 1 I | NTRODUCTION | | | |
| 1.1 | Purpose & Scope | | | |
| 1.2 | Definitions of Terms and Acronyms | | | |
| 1.3 | Related Documents4 | | | |
| 1.4 | Overview4 | | | |
| 2 l | JSER CHARACTERISTICS4 | | | |
| 2.1 2.1 | The Calibration Scientists | | | |
| 2.2 | Interactive Analysis Developer4 | | | |
| 2.3 | Instrument Engineer4 | | | |
| 2.4 | Consortium Astronomers4 | | | |
| 2.5 | Non-Consortium Astronomers4 | | | |
| 2.6 | FSC | | | |
| 3 F | REQUIREMENTS4 | | | |
| 3.1 | Real-Time Analysis5 | | | |
| 3.2 | Quick Look Analysis | | | |
| 3.3 | Interactive Analysis: General | | | |
| 3.3 | | | | |
| 3.3 | .2 Modularity | | | |
| 3.3 | .3 IA consists of different generic types of modules | | | |
| 3.3 | .4 Interfaces | | | |
| 3.3 | | | | |
| 3.3 | .6 Interfaces to other software | | | |
| 3.3 | | | | |
| 3.3 | | | | |
| 3.3 | .9 History | | | |
| 3.4 | Data Products | | | |
| 3.4 | | | | |

| SPIRE ICC | | Issue: V1.0 | Date: 10/01/2001 |
|-----------|---|-------------|------------------|
| User Requ | irements Documents: Photometer | Page 3/12 | |
| | | | |
| 3.4.2 | POF2 : Seven-Point Jiggle Map | | |
| 3.4.3 | POF3 : N-Point Jiggle Map | | 7 |
| 3.4.4 | POF4 : Raster Map | | 7 |
| 3.4.5 | POF5 : Scan Map Without Chopping | | |
| 3.4.6 | POF6 : Scan Map With Chopping | | |
| 3.4.7 | POF7 : Photometer Peak-Up (TBD) | | |
| 3.4.8 | POF8 : Operate photometer internal calibrator | | |
| 3.4.9 | POF9 : Special engineering modes (TBD) | | |
| | | | |
| 3.5 Int | eractive Analysis: Processing of Observing Modes. | ••••• | 8 |
| 3.5.1 | General | | |
| 3.5.2 | POF1: Chop Without Jiggling | | 9 |
| 3.5.3 | POF2: Seven-Point Jiggle Map | | 10 |
| 3.5.4 | POF3: N-Point Jiggle Map | | |
| 3.5.5 | POF4: Raster Map | | |
| 3.5.6 | POF5: Scan Map Without Chopping | | |
| 3.5.7 | POF6: Scan Map With Chopping | | |
| 3.5.8 | POF7: Photometer Peak-Up (TBD) | | |
| 250 | | | 11 |

1 Introduction

1.1 Purpose & Scope

Requirements put on the ICC by the Photometer observing modes. It will describe the form the data is expected to take and the information required to fully characterise it. It also puts requirements on the ICC by the need to produce a data reduction process for the photometer observation modes of SPIRE. These observation modes might have either a purely scientific goal or an engineering purpose. The potential users of the data reduction process might be either members of the SPIRE Consortium, or astronomers having access to the FIRST observations (via the FSC). (This description was taken from RD-1). This document does not cover the requirements from the need to calibrate the modes, nor the need to command the instrument which are covered in RD-3 & RD-4

1.2 Definitions of Terms and Acronyms

Listing of acronyms that are "unusual" to this URD

- FIRST Far InfraRed and Submillimetre Telescope
- SPIRE The Spectral and Photometric Imaging REceiver for FIRST
- ICC Instrument Control Centre
- URD User Requirement Document
- ILT Instrument Level Test
- AVM Avionics Model
- CQM Cryo Qualification Model
- PFM Proto-Flight Model
- PV Performance Verification
- GST Ground Segment Testing

In addition two web pages are available describing terms applicable to SPIRE http://www.ssd.rl.ac.uk/spire/consortium/information/FIRSTacronyms.shtm http://www.ssd.rl.ac.uk/spire/consortium/information/FIRSTacronyms.shtm

1.3 Related Documents

- RD-1 SPIRE ICC URD Scope Document
- RD-2 FIRST Common Science System Development Work Report
- (Neal Todd, Edinburgh 20th October 2000)
- RD-3 SPIRE ICC URD Calibration
- RD-4 SPIRE ICC URD Common Uplink System
- 1.4 Overview

2 <u>User Characteristics</u>

2.1 The Calibration Scientists

The calibration scientist has a strong astronomical background and an in-depth knowledge of the properties and operations of the instrument. He/She plans the necessary calibration observations to characterize the instrument, determines and verifies the calibration parameters of the instrument and specifies how these parameters have to be applied in the standard product generation. [ICC actor v0.4]

2.1.1 Photometer Calibration Scientist

A calibration scientist with special responsibilities for the Photometer

2.2 Interactive Analysis Developer

The IA developer will need to be able to modify IA routines in response to proposed changes in calibration procedures.

2.3 Instrument Engineer

The instrument engineer will provide information about the instrument necessary for the processing. S/he will also be making requirements on what processing steps and outputs are required.

2.4 Consortium Astronomers

The photometer processing is can only be properly assessed when applied to real scientific measurements. Special scientific observations may require special processing. It is the astronomers who will eventually be able to decide whether the processing is achieving the desired results. Those involved with the processing activity need to be closely corresponding with Astronomers, in particular Consortium Astronomers.

2.5 Non-Consortium Astronomers

The photometer processing is can only be properly assessed when applied to real scientific measurements. Special scientific observations may require special processing. Those involved with the processing activity need to be closely corresponding with Astronomers, to a lesser extent non-Consortium Astronomers via the FSC.

2.6 FSC

3 Requirements

3.1 Real-Time Analysis

3.2 Quick Look Analysis

It is hoped that the Quick Look Analysis will be a sub-set of the Interactive Analysis

3.3 Interactive Analysis: General

This section indicates some general requirements of the Interactive Analysis (IA).

3.3.1 Platforms

IA should be multiplatform with goal of platform independence. The platforms that are currently required are Solaris, Linux, DecUltra with a goal of one Windows platform (NT/95/98 or 2000). The list of supported platforms will be subject to change at time scale of one tear (TBC).

- Source RD2
- Importance Essential/Desirable
- Frequency yearly
- Phase AVM

3.3.2 Modularity

The IA should be designed such that new algorithms can be developed and interchanged with ease.

- Source SJO (here)
- Importance Essential
- **Frequency** continuous
- Phase

3.3.3 IA consists of different generic types of modules

(a) interactively processing data

AVM

- (b) visualizing data; at all stages of processing, not just final images
- (c) input/ output of data
- Source RD2
- Importance Essential
- Frequency once
- Phase AVM

3.3.4 Interfaces

Interactive analysis will consist of both GUIs and Command Line interfaces A scripting language can be run within IA

- Source RD2
- Importance Essential
- Frequency continuous
- Phase AVM

3.3.5 Data formats

IA will be able to export/ import data in formats than can be imported/exported to/ from other software – which?

- Source RD2
- Importance Essential
- Frequency once
- Phase AVM

3.3.6 Interfaces to other software

The possibility that the IA will allow the calling of other data reduction packages

| | DUC. NO. | 3FIRE-103-FRJ-000343 |
|---|-------------|----------------------|
| SPIRE ICC | Issue: V1.0 | Date: 10/01/2001 |
| User Requirements Documents: Photometer | Page 6/12 | |

and/ or libraries (possibly in other languages) whilst in IA is an open issue. This is expected to be difficult and so is very much a goal rather than a requirement.

- Source RD2
- Importance DesirableFrequency once
- Phase AVM

3.3.7 User Help

IA will have a help system including reference guides and recipes

- Source RD2
- Importance Essential
- Frequency continuous
- Phase AVM

3.3.8 Source code

Modules will be open source so that the Astronomer can see the algorithms applied and have the facility to locally modify and run code. – dangerous ? **Source** RD2

- Importance Essential
- Frequency once
- Phase AVM

3.3.9 History

The product generation history will be a component part of the products

- Source RD2
 Importance Essential
- Frequency once
- Phase AVM

3.4 Data Products

The data products should be processed to the extent that is required by the quality of the data and by the nature of the observations being carried out. Under each observing mode we specify what the end results of the data processing are expected to be. We do this because the specific processing steps expanded below may not be the only ways of reaching these end-points. N.B. these are all science end points, it may be that there are other engineering/calibration end points which will be of interest.

| ٠ | Source | Here |
|---|------------|-----------|
| ٠ | Importance | Essential |
| ٠ | Frequency | once |
| ٠ | Phase | AVM |

3.4.1 POF1

Chop Without Jiggling

Flux (or upper-limit) of a point source with known position (which is expected to be in centre of central bolometer, but might later be found to be at a known position off centre?) Error in Flux

Measure of Goodness of Fit

Average intensity recorded in each bolometer-sky position Error in intensity

3.4.2 POF2 : Seven-Point Jiggle Map

Detection of previously unknown point sources? Positions of previously unknown point sources? Fluxes for previously unknown point sources?

Issue: V1.0 Date: 10/01/2001 Page 7/12

Significance levels of detections? Errors in positions? Errors in fluxes?

Flux (or upper-limit) of a point source with known position (which could be anywhere within the boundaries of the map) Error in Flux Measure of Goodness of Fit

Map of Intensity Error in Intensity

Average intensity recorded in each bolometer-sky position Error in intensity

3.4.3 POF3 : N-Point Jiggle Map

Detection of previously unknown point sources Positions of previously unknown point sources Fluxes for previously unknown point sources Significance levels of detections Errors in positions Errors in fluxes

Flux (or upper-limit) of a point source with known position (which could be anywhere within the boundaries of the map) Error in Flux Measure of Goodness of Fit

Map of Intensity Error in Intensity

Average intensity recorded in each bolometer-sky position Error in intensity

3.4.4 POF4 : Raster Map

Detection of previously unknown point sources Positions of previously unknown point sources Fluxes for previously unknown point sources Significance levels of detections Errors in positions Errors in fluxes

Flux (or upper-limit) of a point source with known position (which could be anywhere within the boundaries of the map) Error in Flux Measure of Goodness of Fit

Map of Intensity Error in Intensity

Average intensity recorded in each bolometer-sky position Error in intensity

3.4.5 POF5

Scan Map Without Chopping

Detection of previously unknown point sources Positions of previously unknown point sources Fluxes for previously unknown point sources Significance levels of detections Errors in positions Errors in fluxes

:

Flux (or upper-limit) of a point source with known position (which could be anywhere within the boundaries of the map) Error in Flux Measure of Goodness of Fit

Map of Intensity Error in Intensity

3.4.6 POF6 Scan Map With Chopping

Detection of previously unknown point sources Positions of previously unknown point sources Fluxes for previously unknown point sources Significance levels of detections Errors in positions Errors in fluxes

Flux (or upper-limit) of a point source with known position (which could be anywhere within the boundaries of the map) Error in Flux Measure of Goodness of Fit

Map of Intensity Error in Intensity

3.4.7 POF7 Photometer Peak-Up (TBD) :

Position of point source with approximately known position Flux (or upper-limit?) of a point source with determined position Error in Flux Measure of Goodness of Fit

3.4.8 POF8 Operate photometer internal calibrator

Average intensity recorded in each bolometer-sky position Error in intensity

3.4.9 POF9 Special engineering modes (TBD) :

TBD,

3.5 Interactive Analysis: Processing of Observing Modes

The Interactive analysis must be capable of processing all observing modes. This section indicates what we currently expect to be the procedures required for each mode. The procedures described here are currently indicated in a flow chart in the Appendix.

3.5.1 General

The following processes will be required on all data regardless of observing mode (except where explicitly excluded in the observing mode specific sections below)

3.5.1.1 Data from FINDAS

Includes all SPIRE relevant data

3.5.1.2 Injection into SPIRE pipeline

1., 3.,4. are obvious, 5., may not be required, 2 may include real astrometric information as a function of UT but may require a software module which can interpret or reinterpret satellite pointing data as the reconstruction models are improved (these modules could be implemented at any stage in the pipe-line)

3.5.1.3 Construct Inst. Mode/Status history from H/K

Self explanatory. May be checked against requested mode?

3.5.1.4 Flagging missing and Bad data

Self explanatory

3.5.1.5 Converting mechanical data to Physical Units

Physical units would be Volts, x,y, positions in mm, angles in degrees, etc.

3.5.1.6 Validation of mechanical data

Checking e.g. that the position of the chopper mirror is appropriate (dependent on mode?). This includes checks which would not have been trapped by the usual out of limits (hard or soft).

3.5.1.7 Calibration Tables

Required as input to the two conversion processes. Presumably these are likely to be look-up tables or parameters for simple algorithms

3.5.1.8 Reports

Reports are required to indicate where the mode is non-standard in some way, or if there is an anomalously high rate of bad pixels

3.5.1.9 Stored data

There are two points at which data is stored. In general data should be stored at a point in the pipe-line that one may wish to return to (to run new procedures) without having to go further back. So it is likely that data should be stored after time-consuming or stable processes.

The two points indicated here for storage are not cast in stone, but appear after what are presumed to be reasonable stable processes

3.5.1.10 <u>Visualisation</u>

Two points are indicated where QLA visualisation routines would be required. I.e. we would like to be able to examine the most raw of data products, before any real processing has occurred, and we would like to be able to visualise the data in physical units.

3.5.2 POF1: Chop Without Jiggling

3.5.2.1 <u>0th Order Deglitching</u>

Filtering out very high significance, short time-scale spikes in the time-line

3.5.2.2 Demodulation

Differencing on-off chop position

3.5.2.3 Gain Drift correction

Probably requires sensitivity measurements as a function of time and interpolates between. No reason to expect significant drift but I guess useful to have the capability. This is what the internal calibrator is for. The calibrator signal will be demodulated either at the same time as the astronomical signal or periodically, then for each detector the relative gain can be compared to the standard value and if necessary either adjusted or simply flagged.

3.5.2.4 Deglitch 2

Filtering out outliers from "average" of chopped signals at a single jiggle pointing

3.5.2.5 Flat-fielding

Taking out the differing responsivity of the different detectors. This should be a trivial step just multiplying by a lookup table.

3.5.2.6 Cross-talk

Self explanatory if hard. If necessary can in principle be removed by matrix inversion, where the matirix contains the crosstalk of each pixel to every other, messy though.

3.5.2.7 Glitch removal

Deviations between signals from sequential returns to the same jiggle position can be filtered out, iterative with previous step

3.5.2.8 Look at pointing data

Assign astrometric positions to co-added detector images. This doesn't really belong in here with the basic number-crunching algorithmns, it's more of a astronomical processing step.

3.5.2.9 Combine pairs of nod positions

Combine images which are taken at genuinely different telescope pointings, i.e. not different because of the jiggle and chop movements of the mirror

3.5.2.10 <u>Calibration</u>

Self-explanatory

3.5.3 POF2: Seven-Point Jiggle Map

POF2 is a special case of POF3. No special, additional processing steps required.

3.5.4 POF3: N-Point Jiggle Map

Same as for POF1, except for the following:

3.5.4.1 Coadd Jiggle Images

As we return a number of times to each jiggle position within a single nod pointing we need to average the signals within the nod pointing

3.5.4.2 Glitch removal

Deviations between signals from sequential returns to the same jiggle position can be filtered out, iterative with previous step

3.5.4.3 Calibration

Self-explanatory

3.5.5 POF4: Raster Map

This is just an extension of POF3, whereby the telescope makes jiggle maps at a sequence of positions.

Additional requirements:

3.5.5.1 Combining raster positions

3.5.6 POF5: Scan Map Without Chopping

Radically different from jiggle-mapping or photometry. The signal is now spread over a wide-range of frequency bandwidth, rather than in a narrow-band about the chop frequency, so the signal processing is completely different. If the detectors are DC-coupled then it is much simpler but it is not clear to me that they will be. This and POF5 need a proper system analysis by someone who undertsands signal processing.

3.5.7 POF6: Scan Map With Chopping

Again radically different from EITHER the scan-map without chopping OR the jiggle-mapping modes. This time the signal still spread out in bandwidth but contained in sidebands about the chopping frequency. Consecutive samples contain the DIFFERENCE signal between points separated by the chop distance and once the whole scan has been completed these have to be inverted to recover the true signal (known as the "Emerson, Klein" and Haslam, "NOD2" or "EKH" method). In order to avoid Zero-crossings in the window function in spatial frequency space the true sky map can only be recovered by combining scans taken with different chop throws and ideally in difference directions as well, which is the way SCUBA does it for example (the "Emerson2" method). This means an "image" can only be properly made from several "observations".

Despiking is very much more difficult as well

3.5.8 POF7: Photometer Peak-Up (TBD)

Basically just several photometry points done sequentially and then some fitting routine used to find the peak signal position.

3.5.9 POF8: Operate photometer internal calibrator

- 3.5.9.1 Demodulate internal calibrator signal, and then compare to standard values for each pixel.
- 3.5.10 POF9: Special engineering modes (TBD)

| SPIRE ICC | | Date: 10/01/2001 |
|---|------------|------------------|
| User Requirements Documents: Photometer | Page 12/12 | |
| | | |