

3. FINISH: NONE
2. BAG AND TAG INDIVIDUAL PARTS PER JPL SPEC FS500451.
1. REMOVE ALL BURRS AND BREAK SHARP EDGES 0.01 - 0.05 MAX.
NOTES: UNLESS OTHERWISE SPECIFIED

10502803