

1 Filename / CHEKSUM Value / HASH Value for MAIN Section

LCUFM MAIN, LSUFM MAIN, LOUFM		Signature
File Identification MAIN	091216_I2-26_CUS-Table_115-140K_FLIGHT_DISS_MAIN.txt	
Calculated Hash Value Date: 16.12.2009 Time 15:40:30	50bb3a9f9b499e9e181e04c8bc7ef3ec	
LCU On-Board Software Patch		Refer to LCU On-Board Software Release Note: SRC/LCU/PR /2006-077 Issue 1.7 02.July 2007
File Identification	Patch_LCUFM_17.txt	
Calculated CHEKSUM Value after patch upload	STANDBY mode: 0x8E3B	
Calculated CHEKSUM Value with uploaded safe operational table and after patch upload (If command HL_DEF_SAFE followed by command HIFI_check_LCU_memory is send after table upload in STANDBY mode, checksum value changes to its final value which is equal to the stated NORMAL mode value)	STANDBY mode: 0x883E NORMAL mode: 0x8F9D	
LCU on-board software version changes to	0x2977	
Calculated Hash Value	2a85fa30556bfb8297e9859211d5446b	

2 Filename / CHEKSUM Value / HASH Value for Redundant Section

LCUFM REDUNDANT, LSUFM REDUNDANT, LOUFM		Signature
File Identification REDUNDANT	091216_I2-26_CUS-Table_115- 140K_FLIGHT_DISS_RED.txt	
Calculated Hash Value Date: 16.12.2009 Time 15:40:48	80c4e29423308e1f6a8fb318e01538a3	
LCU On-Board Software Patch		Refer to LCU On-Board Software Release Note: SRC/LCU/PR /2006-077 Issue 1.7 02.July 2007
File Identification	Patch_LCUFM_17.txt	
Calculated CHEKSUM Value after patch upload	STANDBY mode: 0x8E3B	
Calculated CHEKSUM Value with uploaded safe operational table and after patch upload (If command HL_DEF_SAFE followed by command HIFI_check_LCU_memory is send after table upload in STANDBY mode, checksum value changes to its final value which is equal to the stated NORMAL mode value)	STANDBY mode: 0x7CDC NORMAL mode: 0x8439	
LCU on-board software version changes to	0x2977	
Calculated Hash Value	2a85fa30556bfb8297e9859211d5446b	