

SSTD Incoming Inspection Report

Spacecraft/Project **HERSCHELL/SPIRE**

Document Number **SPIRE-RAL-REP- 002317**

Issue **1**

Sub System **FPU**

Date **19-Jan-05**

Model **CQM**

INCOMING INSPECTION REPORT

FROM
<p>XXX #N/A</p>

TO
<p>EADS Astrium Ottobrunn</p>

Applicable sections	
Containers	Yes
External Visual Inspection	Yes
External Connector	No
Documentation	Yes
Verification of Interfaces	Yes
Extra Comments Sheets	

Drawings / Documents Attached

INSPECTION CONDUCTED BY

WITNESS BY

NAME
Doug Griffin

DATE
19/01/2005

NAME
Eric Sawyer

DATE
19/01/2005

SSTD Incoming Inspection Report

Spacecraft/Project

Document Number

Issue

Sub System

Date

Model

CONTAINER INSPECTION

TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or handling provisions		Checked
Security / Locking Fitted		Checked
Markings for destination and description		Checked
Warning labels relating to handling lifting and stacking limits		N/A
Any additional Comments		

TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging		Checked
Internal padding / packaging required		Checked
Mounting provisions secure		Checked
Any additional Comments		

ENVIROMENTAL MONITORS								
Temp Monitors		Humidity Monitors		Shock Sensors Triggerd Information				
Fitted:	<input type="text" value="No"/>	Fitted:	<input type="text" value="Yes"/>	5g	10g	15g	25g	50g
Condition:	<input type="text"/>	Condition:	<input type="text" value="Satisfactory"/>	X Axis	Plus	ok	ok	
				Y Axis	OK	ok	ok	
				Z Axis	OK	ok	ok	

SSTD Incoming Inspection Report

Spacecraft/Project **HERSCHELL/SPIRE**

Document Number **SPIRE-RAL-REP-002317**

Issue **1**

Sub System **FPU**

Date **19-Jan-05**

Model **CQM**

INSTRUMENT VISUAL INSPECTION

CHECK LIST	REMARKS	RESULTS
Contents against shipping list		Correct
Instrument label		Correct
Note status of external contamination		Acceptable
Degradation of paintwork or Coating?		Acceptable
Fasteners correctly locked?		N/A
Check protective covers are correctly labelled and fitted?		Correct
Additional Comments		

SSTD Incoming Inspection Report

Spacecraft/Project **HERSCHELL/SPIRE**

Document Number **SPIRE-RAL-REP-002317**

Issue **1**

Sub System **FPU**

Date **19-Jan-05**

Model **CQM**

INSPECTION OF ALL CONNECTORS

CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		Pass
Damaged Sockets		Pass
Internal Debris		Pass
Connector Covers fitted		Pass
Connector Savers Fitted		None
EMC Covers Fitted		Pass
RED Tag Item / Green Tag Items fitted		Pass
Additional Comments		

SSTD Incoming Inspection Report

Spacecraft/Project	HERSCHELL/SPIRE	Document Number	SPIRE-RAL-REP-002317	Issue	1
Sub System	FPU	Date	19-Jan-05	Model	CQM

DOCUMENTATION CHECK LIST

Check	REMARKS	RESULTS
End Item Data Pack		Yes
Transportaion Documents		Yes
Packing un- Packing instructions		Yes
Additional Comments		

Verification of Interfaces

Mechanical interface: dimensions specified in the interface control documents such as mass, flatness of surfaces, location of fixing holes and overall dimensions should be measured accurately and recorded. Record Test Report Number, or confirm that measurement result is included in delivery documentation, (EIDP).

INSPECTION / TEST REPORT NUMBER		CHECKED	No
--	--	----------------	----

Electrical interfaces: verifying the location and types of connectors against interface control document is normally carried as part of mechanical verification, confirm this has been done. Functional testing: final functional test report number should be noted.

INSPECTION / TEST REPORT NUMBER	SPIRE-RAL-NOT-002216	CHECKED	Yes
--	----------------------	----------------	-----

SSTD Incoming Inspection Report

Spacecraft/Project	HERSCHELL/SPIRE
--------------------	-----------------

Document Number	SPIRE-RAL-REP-002317
-----------------	----------------------

Issue	1
-------	---

Sub System	FPU
------------	-----

Date	19-Jan-05
------	-----------

Model	CQM
-------	-----

EXTRA COMMENT SHEET
