

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002389**

Issue    **1**

Sub System    **FCU**

Date    **13th April 2005**

Model    **CQM**

## OUTGOING INSPECTION REPORT

FROM
<b>Project</b> Rutherford Appleton Laboratory Space Science and Technology Department Chilton DIDCOT OXON OX11 0QX

TO
<b>EADS</b> EADS Attn. Mr Paul Mack, Astrium, Ludwig- Boelkow-Allee, Gate 2, 85521 Ottobrunn

Applicable sections	
Containers	Yes
External Visual Inspection	Yes
External Connector	Yes
Documentation	Yes
Verification of Interfaccs	No
Extra Comments Sheets	No

Drawings / Documents Attached
Photo's Attached

**INSPECTION CONDUCTED BY**

**WITNESS BY**

NAME
Eric Clark (PA)

DATE
13th April 2005

NAME
Alan Pearce

DATE
13th April 2005

# SSTD Outgoing Inspection Report

Spacecraft/Project **HERSCHELL/SPIRE**

Document Number **SPIRE-RAL-REP- 002389**

Issue **1**

Sub System **FCU**

Date **13th April 2005**

Model **CQM**

## CONTAINER INSPECTION

TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or handling provisions		
Security / Locking Fitted		
Markings for destination and description		
Warning labels relating to handling lifting and stacking limits		
Any additional Comments		

TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging		Checked
Internal padding / packaging required		Checked
Mounting provisions secure		Checked
Any additional Comments		

ENVIROMENTAL MONITORS						
<b>Temp Monitors</b>		<b>Humidity Monitors</b>		<b>Shock Sensors Triggerd Information</b>		
Fitted:	<input type="text" value="No"/>	Fitted:	<input type="text" value="No"/>	5g	10g	15g
Condition:	<input type="text"/>	Condition:	<input type="text"/>	25g	50g	
				X Axis	OK	
				Y Axis	OK	
				Z Axis	OK	

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002389**

Issue    **1**

Sub System    **FCU**

Date    **13th April 2005**

Model    **CQM**

**INSTRUMENT VISUAL INSPECTION**

CHECK LIST	REMARKS	RESULTS
Contents against shipping list		Correct
All closure procedures		Correct
Instrument label		Correct
Note status of external contamination		Acceptable
Degradation of paintwork or Coating?		Acceptable
Fasteners correctly locked?		Correct
Check protective covers are correctly labelled and fitted?		Correct
Double bagged?	Not required for this Item	See Remarks
Additional Comments		

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002389**

Issue    **1**

Sub System    **FCU**

Date    **13th April 2005**

Model    **CQM**

**INSPECTION OF ALL CONNECTORS**

CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		Pass
Damaged Sockets		None
Internal Debris		None
Connector Covers fitted		Pass
Connector Savers Fitted		N/A
EMC Covers Fitted		N/A
RED Tag Item / Green Tag Items fitted		None
Additional Comments		

# SSTD Outgoing Inspection Report

<b>Spacecraft/Project</b>	HERSCHELL/SPIRE	<b>Document Number</b>	SPIRE-RAL-REP- 002389	<b>Issue</b>	1
<b>Sub System</b>	FCU	<b>Date</b>	13th April 2005	<b>Model</b>	CQM

## DOCUMENTATION CHECK LIST

Check	REMARKS	RESULTS
End Item Data Pack		Yes
Transportaion Documents		Yes
Packing un- Packing instructions	Will be unpacked By RAL SSTD Personnel	See Remarks
Additional Comments		

## Verification of Interfaces

**Mechanical interface:** dimensions specified in the interface control documents such as mass, flatness of surfaces, location of fixing holes and overall dimensions should be measured accurately and recorded. Record Test Report Number, or confirm that measurement result is included in delivery documentation, (EIDP).

<b>INSPECTION / TEST REPORT NUMBER</b>	N/A for this inspection	<b>CHECKED</b>	No
--	-------------------------	----------------	----

**Electrical interfaces:** verifying the location and types of connectors against interface control document is normally carried as part of mechanical verification, confirm this has been done. Functional testing: final functional test report number should be noted.

<b>INSPECTION / TEST REPORT NUMBER</b>	N/A for this inspection	<b>CHECKED</b>	No
--	-------------------------	----------------	----

# SSTD Outgoing Inspection Report

Spacecraft/Project	HERSCHELL/SPIRE
--------------------	-----------------

Document Number	SPIRE-RAL-REP- 002389
-----------------	-----------------------

Issue	1
-------	---

Sub System	FCU
------------	-----

Date	13th April 2005
------	-----------------

Model	CQM
-------	-----

EXTRA COMMENT SHEET
---------------------

