

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002433**

Issue    **1**

Sub System    **BSM SN 070-001**

Date    **29th April 05**

Model    **PFM**

## OUTGOING INSPECTION REPORT

FROM
Project Rutherford Appleton Laboratory Space Science and Technology Department Chilton DIDCOT OXON OX11 0QX

TO
<b>ATC</b> Astronomy Technology Centre Edinburgh

Applicable sections	
Containers	Yes
External Visual Inspection	Yes
External Connector	Yes
Documentation	Yes
Verification of Interfaccs	No
Extra Comments Sheets	No

Drawings / Documents Attached

**INSPECTION CONDUCTED BY**

**WITNESS BY**

NAME
Alan Pearce

DATE
29th April 05

NAME
Eric Clark (PA)

DATE
29th April 05

# SSTD Outgoing Inspection Report

Spacecraft/Project **HERSCHELL/SPIRE**

Document Number **SPIRE-RAL-REP- 002433**

Issue  **1**

Sub System **BSM SN 070-001**

Date **29th April 05**

Model **PFM**

## CONTAINER INSPECTION

TRANSPORT CONTAINERS EXTERNAL CONDITION	REMARKS	Status
Mechanical damage to container fasteners, locks, clips or handling provisions		
Security / Locking Fitted		
Markings for destination and description		
Warning labels relating to handling lifting and stacking limits		
Any additional Comments		

TRANSPORT CONTAINERS INTERNAL CONDITION	REMARKS	Status
Check Mounting fixtures fitted internal packaging		Checked
Internal padding / packaging required		Checked
Mounting provisions secure		Checked
Any additional Comments	Item Returned in the dedicated container it was received in	See Remarks

ENVIROMENTAL MONITORS					
<b>Temp Monitors</b>		<b>Humidity Monitors</b>		<b>Shock Sensors Triggerd Information</b>	
Fitted:	<input type="text" value="No"/>	Fitted:	<input type="text" value="No"/>	5g	10g
Condition:	<input type="text"/>	Condition:	<input type="text"/>	15g	25g
				50g	

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002433**

Issue    **1**

Sub System    **BSM SN 070-001**

Date    **29th April 05**

Model    **PFM**

**INSTRUMENT VISUAL INSPECTION**

CHECK LIST	REMARKS	RESULTS
Contents against shipping list		Correct
All closure procedures	None required	See Remarks
Instrument label	None required	See Remarks
Note status of external contamination		None
Degradation of paintwork or Coating?		None
Fasteners correctly locked?		Correct
Check protective covers are correctly labelled and fitted?		N/A
Double bagged?		Correct
Additional Comments		

# SSTD Outgoing Inspection Report

Spacecraft/Project    **HERSCHELL/SPIRE**

Document Number    **SPIRE-RAL-REP- 002433**

Issue    **1**

Sub System    **BSM SN 070-001**

Date    **29th April 05**

Model    **PFM**

**INSPECTION OF ALL CONNECTORS**

CHECK LIST	REMARKS (LIST CONNECTOR NUMBERS)	RESULTS
Pin Alignment		Pass
Damaged Sockets		None
Internal Debris		None
Connector Covers fitted		Pass
Connector Savers Fitted		N/A
EMC Covers Fitted		N/A
RED Tag Item / Green Tag Items fitted		None
Additional Comments		None

# SSTD Outgoing Inspection Report

Spacecraft/Project	HERSCHELL/SPIRE	Document Number	SPIRE-RAL-REP- 002433	Issue	1
Sub System	BSM SN 070-001	Date	29th April 05	Model	PFM

## DOCUMENTATION CHECK LIST

Check	REMARKS	RESULTS
End Item Data Pack	The EIDP in Electronic format only was supplied, no paper copy available.	See Remarks
Transportaion Documents		Yes
Packing un- Packing instructions		N/A
Additional Comments		No

## Verification of Interfaces

**Mechanical interface:** dimensions specified in the interface control documents such as mass, flatness of surfaces, location of fixing holes and overall dimensions should be measured accurately and recorded. Record Test Report Number, or confirm that measurement result is included in delivery documentation, (EIDP).

<b>INSPECTION / TEST REPORT NUMBER</b>	N/A for this inspection	<b>CHECKED</b>	No
--	-------------------------	----------------	----

**Electrical interfaces:** verifying the location and types of connectors against interface control document is normally carried as part of mechanical verification, confirm this has been done. Functional testing: final functional test report number should be noted.

<b>INSPECTION / TEST REPORT NUMBER</b>	N/A for this inspection	<b>CHECKED</b>	No
--	-------------------------	----------------	----

# SSTD Outgoing Inspection Report

Spacecraft/Project	HERSCHELL/SPIRE
--------------------	-----------------

Document Number	SPIRE-RAL-REP- 002433
-----------------	-----------------------

Issue	1
-------	---

Sub System	BSM SN 070-001
------------	----------------

Date	29th April 05
------	---------------

Model	PFM
-------	-----

EXTRA COMMENT SHEET
---------------------